



Customer Release Note

Linux QMI SDK 04.00.02



SIERRA
WIRELESS®

4134477
01.00
September 30, 2016

Important Notice

Due to the nature of wireless communications, transmission and reception of data can never be guaranteed. Data may be delayed, corrupted (i.e., have errors) or be totally lost. Although significant delays or losses of data are rare when wireless devices such as the Sierra Wireless modem are used in a normal manner with a well-constructed network, the Sierra Wireless modem should not be used in situations where failure to transmit or receive data could result in damage of any kind to the user or any other party, including but not limited to personal injury, death, or loss of property. Sierra Wireless accepts no responsibility for damages of any kind resulting from delays or errors in data transmitted or received using the Sierra Wireless modem, or for failure of the Sierra Wireless modem to transmit or receive such data.

Safety and Hazards

Do not operate the Sierra Wireless modem in areas where cellular modems are not advised without proper device certifications. These areas include environments where cellular radio can interfere such as explosive atmospheres, medical equipment, or any other equipment which may be susceptible to any form of radio interference. The Sierra Wireless modem can transmit signals that could interfere with this equipment. Do not operate the Sierra Wireless modem in any aircraft, whether the aircraft is on the ground or in flight. In aircraft, the Sierra Wireless modem **MUST BE POWERED OFF**. When operating, the Sierra Wireless modem can transmit signals that could interfere with various onboard systems.

Note: Some airlines may permit the use of cellular phones while the aircraft is on the ground and the door is open. Sierra Wireless modems may be used at this time.

The driver or operator of any vehicle should not operate the Sierra Wireless modem while in control of a vehicle. Doing so will detract from the driver or operator's control and operation of that vehicle. In some states and provinces, operating such communications devices while in control of a vehicle is an offence.

Limitations of Liability

This manual is provided "as is". Sierra Wireless makes no warranties of any kind, either expressed or implied, including any implied warranties of merchantability, fitness for a particular purpose, or noninfringement. The recipient of the manual shall endorse all risks arising from its use.

The information in this manual is subject to change without notice and does not represent a commitment on the part of Sierra Wireless. SIERRA WIRELESS AND ITS AFFILIATES SPECIFICALLY DISCLAIM LIABILITY FOR ANY AND ALL DIRECT, INDIRECT, SPECIAL, GENERAL, INCIDENTAL, CONSEQUENTIAL, PUNITIVE OR EXEMPLARY DAMAGES INCLUDING, BUT NOT LIMITED TO, LOSS OF PROFITS OR REVENUE OR ANTICIPATED PROFITS OR REVENUE ARISING OUT OF THE USE OR INABILITY TO USE ANY SIERRA WIRELESS PRODUCT, EVEN IF SIERRA WIRELESS AND/OR ITS AFFILIATES HAS BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES OR THEY ARE FORESEEABLE OR FOR CLAIMS BY ANY THIRD PARTY.

Notwithstanding the foregoing, in no event shall Sierra Wireless and/or its affiliates aggregate liability arising under or in connection with the Sierra Wireless product, regardless of the number of events, occurrences, or claims giving rise to liability, be in excess of the price paid by the purchaser for the Sierra Wireless product.

Customer understands that Sierra Wireless is not providing cellular or GPS (including A-GPS) services. These services are provided by a third party and should be purchased directly by the Customer.

SPECIFIC DISCLAIMERS OF LIABILITY: CUSTOMER RECOGNIZES AND ACKNOWLEDGES SIERRA WIRELESS IS NOT RESPONSIBLE FOR AND SHALL NOT BE HELD LIABLE FOR ANY DEFECT OR DEFICIENCY OF ANY KIND OF CELLULAR OR GPS (INCLUDING A-GPS) SERVICES.

Patents

This product may contain technology developed by or for Sierra Wireless Inc.

This product includes technology licensed from QUALCOMM®.

This product is manufactured or sold by Sierra Wireless Inc. or its affiliates under one or more patents licensed from InterDigital Group and MMP Portfolio Licensing.

Copyright

© 2014 Sierra Wireless. All rights reserved.

Trademarks

Sierra Wireless®, AirPrime®, AirLink®, AirVantage®, WISMO® and the Sierra Wireless and Open AT logos are registered trademarks of Sierra Wireless, Inc. or one of its subsidiaries.

Watcher® is a registered trademark of Netgear, Inc., used under license.

Windows® and Windows Vista® are registered trademarks of Microsoft Corporation.

Macintosh® and Mac OS X® are registered trademarks of Apple Inc., registered in the U.S. and other countries.

QUALCOMM® is a registered trademark of QUALCOMM Incorporated. Used under license.

Other trademarks are the property of their respective owners.

Contact Information

Sales Desk:	Phone:	1-604-232-1488
	Hours:	8:00 AM to 5:00 PM Pacific Time
	Contact:	http://www.sierrawireless.com/sales
Post:	Sierra Wireless 13811 Wireless Way Richmond, BC Canada V6V 3A4	
Technical Support:	support@sierrawireless.com	
RMA Support:	repairs@sierrawireless.com	
Fax:	1-604-231-1109	
Web:	http://www.sierrawireless.com/	

Consult our website for up-to-date product descriptions, documentation, application notes, firmware upgrades, troubleshooting tips, and press releases: www.sierrawireless.com

Document History

Version	Date	Updates
01.00	September 30, 2016	Creation



Contents

1. INTRODUCTION	7
1.1. Document Scope	7
1.2. Document Audience	7
1.3. New Features/Enhancements	7
1.4. Removed Features	8
2. ABBREVIATIONS AND DEFINITIONS	9
3. RELATED DOCUMENTATION	10
4. COMPATIBILITY	11
5. SOFTWARE RELEASE DESCRIPTION	13
6. SOFTWARE CHANGES DESCRIPTION	14
6.1. Validated Corrections/Improvements	14
6.2. Known Issues	15
6.3. New API.....	15
6.4. Minor API prototype change.....	15
6.5. Macro Usage	16



List of Tables

Table 1.	New Features/Enhancements	7
Table 2.	Removed features	8
Table 3.	Abbreviations and Definitions	9
Table 4.	Related Documentation	10
Table 5.	Hardware Compatibility	11
Table 6.	Supported Application-Mode VID/PIDs	11
Table 7.	Supported Boot-Mode VID/PIDs	11
Table 8.	Modem and Firmware tested with the SDK.....	12
Table 9.	Release Information	13



Introduction

1.1. Document Scope

This document describes the content of the Linux QMI SDK 04.00.02 release.

1.2. Document Audience

This release note may be distributed to all direct and indirect customers.

1.3. New Features/Enhancements

Table 1. New Features/Enhancements

Feature	Description
Lite APIs	<ul style="list-style-type: none">• New Wrappers<ul style="list-style-type: none">○ NAS<ul style="list-style-type: none">▪ SLQSSwiGetLteScRxInfo○ DMS<ul style="list-style-type: none">▪ GetManufacturer▪ GetOfflineReason○ UIM<ul style="list-style-type: none">▪ SLQSUIPowerUp▪ SLQSUIPowerDown○ WDS<ul style="list-style-type: none">▪ GetPacketStatistics▪ GetByteTotals▪ SLQSGetCurrentChannelRate▪ SLQSSGetLoopback▪ SLQSSSetLoopback• Enhancement<ul style="list-style-type: none">○ Add libsdp_set_log_func for setting custom log function○ Add "LTE Attach Profile" in unpack_wds_SLQSGet3GPPConfigItem and pack_wds_SLQSSet3GPPConfigItem_t
New API	<ul style="list-style-type: none">• SLQSSetCrashStateCheckIgnore• SLQSSwiGetLteScRxInfo
Miscellaneous	<ul style="list-style-type: none">• Fix incorrect service id used in SetDHCPv4ClientLeaseChange• Includes ARM64 binaries• Add SQF filters for 9x30• Fix scanning modem with 2 digits serial port number

1.4. Removed Features

Table 2. Removed features

Feature	Description
---------	-------------

2.

Abbreviations and Definitions

Table 3. Abbreviations and Definitions

Abbreviation/Acronym	Definitions
MSM	Mobile Station Modem
PRI	Product Release Instructions
QMI	Qualcomm MSM Interface
SLQS	Sierra Linux QMI SDK
WP	Work Package

3.

Related Documentation

Table 4. Related Documentation

Ref. #	Doc. #	Document title
[R-1]	4110914	Linux QMI SDK Application Developer's Guide

4.

Compatibility

Table 5. Hardware Compatibility

Devices Compatibility List
AR7554/AR7554RD
EM/MC73xx
MC77xx
MC83x5
MC/SL9090
WP71xx
MC/EM74xx
WP8548/7502/7504

Note: MC77xx devices must operate in "QMI Mode" and not in "Direct-IP" mode.

To switch device into QMI mode of operation, use the following AT commands:

- **AT!UDPID=68A2**
- **AT!RESET**

Note: MC73xx, set the device using "AT!UDPID=68C0".

The tables below list the hexadecimal values of the Vendor ID (VID) and Product ID (VID) pairs supported by the Linux QMI SDK.

Table 6. Supported Application-Mode VID/PIDs

VID	1199	1199	1199	1199	1199	1199	1199	1199	3F0
PID	68A2	68C0	9011	9013	9015	9019	9041	9071	371D

Table 7. Supported Boot-Mode VID/PIDs

VID	1199	1199	1199	1199	1199	1199	1199	1199	3F0
PID	68A2	68C0	9010	9012	9014	9018	9040	9070	361D

To check your device's VID/PID, issue the `lsusb` command. The output will present a list of USB devices with a column showing each device's manufacturer. The device VID/PID can be read from the row containing the correct device manufacturer. Additionally, on MC77xx devices, you can use the `AT!UDINFO?` command to check VID/PID information. If your VID/PID does not match the any of the entries in the tables above, contact your FAE for support.

The following table enumerates the modems with their corresponding firmware that were tested with Linux QMI SDK 04.00.02.

Table 8. Modem and Firmware tested with the SDK

Modem	Firmware
MC7430	SWI9X30C_02.22.00.00
EM/MC7455	SWI9X30C_02.22.00.00
MC7304	SWI9X15C_05.05.58.00
MC7354	SWI9X15C_05.05.67.00
MC7350	SWI9C15C_05.05.58.01
MC7355	SWI9X15C_05.05.58.00
MC7330	SWI9X15C_05.05.65.00
MC7305	SWI9X15C_05.05.58.00
MC7710	SWI9200X_03.05.29.06
MC9090	SWI6600U_02.04.05.00
EM7355	SWI9X15C_05.05.67.00
EM7330	SWI9X15C_05.05.65.00
EM7305	SWI9X15C_05.05.67.00
WP7502	SWI9X15Y_07.10.04.00
WP7504	SWI9X15Y_07.10.04.00
WP8548	SWI9X15Y_07.10.04.00

Note: The SDK in general work across all firmware revisions. However, some new API might require a recent firmware.

5.

Software Release Description

Table 9. Release Information

Component	Content
SDK version	04.00.02
Date of generation	29/09/2016
Binary archive name	SLQS04.00.02.bin.tar.gz
MD5 checksum	e2b7d0514518f0161714ac51e7a655a9
Source code archive name	SLQS04.00.02.tar.gz
MD5 checksum	fae5868991275641aae3d5d0b0f5295d
Processor compatibility	x86, ARM, PowerPC, MIPS
Linux kernel compatibility	2.6.32 to 4.1
USB drivers compatibility	S2.26N2.38



6.

Software Changes Description

6.1. Validated Corrections/Improvements

ID	Description
LXQMISDK-758	Custom logging function to be added in libSDP
LXQMISDK-745	[Linux] Firmware download sometimes return failure code 59405 E80D
LXQMISDK-737	SetDHCPv4ClientLeaseChange() uses wrong Service ID - causing invalid QMI command error
LXQMISDK-296	[Linux SDK] [EM7455] SLQS does not detect device when the ttyUSB port number goes over 10
LXQMISDK-724	Need API to retrieve Scell signal info for carrier aggregation
LXQMISDK-757	syslog to be replaced with libpack_log for printing SDK Lite license
LXQMISDK-743	[Linux QMI SDK] 04.00.01 unable to make -f pkgs.mak complete
LXQMISDK-738	SLQSGetFirmwareInfo does not work for WP x5xx devices
LXQMISDK-403	SLQSUIVerifyPin returns Malformed or Corrupted QMI msg error when encrypted PIN1 is specified
LXQMISDK-751	pack_wds_SLQSSet3GPPConfigItem_t to be updated to handle optional parameters
LXQMISDK-747	lite FW download tool to be updated to handle OEM PRI case correctly
LXQMISDK-733	update release script to tag libsdp & libpack
LXQMISDK-748	DM log filters packaged with SDK need to updated to support 9x30 modems
LXQMISDK-742	update release script to include arm64/mips libpack/libsdp binaries
LXQMISDK-731	update release script for Dev Studio 32/64bit binaries
LXQMISDK-740	[arm64bit] EM7455 remaining file size displayed is wrong during firmware download on arm64bit platform
LXQMISDK-749	Implement Lite APIs for WP support

ID	Description
LXQMISDK-763	SDK crash when starting Firmware_Download without device
LXQMISDK-764	[SLQS04.00.02_alpha] 9x30 image switching failure issue for DOCOMO and PTCRB using option 7 of MC7xxx image management sample application
LXQMISDK-765	Lite API doc update

6.2. Known Issues

ID	Description
----	-------------

6.3. New API

API	Comment
SLQSSetCrashStateCheckIgnore	This API is used to set whether ignore crash state checking before proceed firmware download using the API UpgradeFirmware2k()
SLQSSwiGetLteScRxInfo	This API retrieves the LTE Secondary carrier Rx signal level information

6.4. Minor API prototype change

Note: when updating SDK, please make sure to pull the latest headers from <SDK_ROOT>/api folder

API	Comment
pack_wds_SLQSSet3GPPConfigItem	Updated pack_wds_SLQSSet3GPPConfigItem_t to handle optional parameters

6.5. Macro Usage

Macro	Usage
AM_API_MUTEX_TIMEOUT_IN_SEC	This is the timeout time (in seconds) for which the mutex is locked when the SDK is compiled with API_TIMEOUT flag.
API_TIMEOUT	This is a compilation flag. If this flag is defined during compilation, SDK will lock the mutex for a particular time. The locking time is defined by AM_API_MUTEX_TIMEOUT_IN_SEC. If this flag is not defined then the mutex is locked indefinitely.