



Customer Release Note

Linux QMI SDK 03.03.16



SIERRA
WIRELESS®

4134416
01.00
April 15, 2016

Important Notice

Due to the nature of wireless communications, transmission and reception of data can never be guaranteed. Data may be delayed, corrupted (i.e., have errors) or be totally lost. Although significant delays or losses of data are rare when wireless devices such as the Sierra Wireless modem are used in a normal manner with a well-constructed network, the Sierra Wireless modem should not be used in situations where failure to transmit or receive data could result in damage of any kind to the user or any other party, including but not limited to personal injury, death, or loss of property. Sierra Wireless accepts no responsibility for damages of any kind resulting from delays or errors in data transmitted or received using the Sierra Wireless modem, or for failure of the Sierra Wireless modem to transmit or receive such data.

Safety and Hazards

Do not operate the Sierra Wireless modem in areas where cellular modems are not advised without proper device certifications. These areas include environments where cellular radio can interfere such as explosive atmospheres, medical equipment, or any other equipment which may be susceptible to any form of radio interference. The Sierra Wireless modem can transmit signals that could interfere with this equipment. Do not operate the Sierra Wireless modem in any aircraft, whether the aircraft is on the ground or in flight. In aircraft, the Sierra Wireless modem **MUST BE POWERED OFF**. When operating, the Sierra Wireless modem can transmit signals that could interfere with various onboard systems.

Note: Some airlines may permit the use of cellular phones while the aircraft is on the ground and the door is open. Sierra Wireless modems may be used at this time.

The driver or operator of any vehicle should not operate the Sierra Wireless modem while in control of a vehicle. Doing so will detract from the driver or operator's control and operation of that vehicle. In some states and provinces, operating such communications devices while in control of a vehicle is an offence.

Limitations of Liability

This manual is provided "as is". Sierra Wireless makes no warranties of any kind, either expressed or implied, including any implied warranties of merchantability, fitness for a particular purpose, or noninfringement. The recipient of the manual shall endorse all risks arising from its use.

The information in this manual is subject to change without notice and does not represent a commitment on the part of Sierra Wireless. SIERRA WIRELESS AND ITS AFFILIATES SPECIFICALLY DISCLAIM LIABILITY FOR ANY AND ALL DIRECT, INDIRECT, SPECIAL, GENERAL, INCIDENTAL, CONSEQUENTIAL, PUNITIVE OR EXEMPLARY DAMAGES INCLUDING, BUT NOT LIMITED TO, LOSS OF PROFITS OR REVENUE OR ANTICIPATED PROFITS OR REVENUE ARISING OUT OF THE USE OR INABILITY TO USE ANY SIERRA WIRELESS PRODUCT, EVEN IF SIERRA WIRELESS AND/OR ITS AFFILIATES HAS BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES OR THEY ARE FORESEEABLE OR FOR CLAIMS BY ANY THIRD PARTY.

Notwithstanding the foregoing, in no event shall Sierra Wireless and/or its affiliates aggregate liability arising under or in connection with the Sierra Wireless product, regardless of the number of events, occurrences, or claims giving rise to liability, be in excess of the price paid by the purchaser for the Sierra Wireless product.

Customer understands that Sierra Wireless is not providing cellular or GPS (including A-GPS) services. These services are provided by a third party and should be purchased directly by the Customer.

SPECIFIC DISCLAIMERS OF LIABILITY: CUSTOMER RECOGNIZES AND ACKNOWLEDGES SIERRA WIRELESS IS NOT RESPONSIBLE FOR AND SHALL NOT BE HELD LIABLE FOR ANY DEFECT OR DEFICIENCY OF ANY KIND OF CELLULAR OR GPS (INCLUDING A-GPS) SERVICES.

Patents

This product may contain technology developed by or for Sierra Wireless Inc.

This product includes technology licensed from QUALCOMM®.

This product is manufactured or sold by Sierra Wireless Inc. or its affiliates under one or more patents licensed from InterDigital Group and MMP Portfolio Licensing.

Copyright

© 2014 Sierra Wireless. All rights reserved.

Trademarks

Sierra Wireless®, AirPrime®, AirLink®, AirVantage®, WISMO® and the Sierra Wireless and Open AT logos are registered trademarks of Sierra Wireless, Inc. or one of its subsidiaries.

Watcher® is a registered trademark of Netgear, Inc., used under license.

Windows® and Windows Vista® are registered trademarks of Microsoft Corporation.

Macintosh® and Mac OS X® are registered trademarks of Apple Inc., registered in the U.S. and other countries.

QUALCOMM® is a registered trademark of QUALCOMM Incorporated. Used under license.

Other trademarks are the property of their respective owners.

Contact Information

Sales Desk:	Phone:	1-604-232-1488
	Hours:	8:00 AM to 5:00 PM Pacific Time
	Contact:	http://www.sierrawireless.com/sales
Post:	Sierra Wireless 13811 Wireless Way Richmond, BC Canada V6V 3A4	
Technical Support:	support@sierrawireless.com	
RMA Support:	repairs@sierrawireless.com	
Fax:	1-604-231-1109	
Web:	http://www.sierrawireless.com/	

Consult our website for up-to-date product descriptions, documentation, application notes, firmware upgrades, troubleshooting tips, and press releases: www.sierrawireless.com

Document History

Version	Date	Updates
01.00	April 15, 2016	Creation



Contents

1. INTRODUCTION	7
1.1. Document Scope	7
1.2. Document Audience	7
1.3. New Features/Enhancements	7
2. ABBREVIATIONS AND DEFINITIONS	9
3. RELATED DOCUMENTATION	10
4. COMPATIBILITY	11
5. SOFTWARE RELEASE DESCRIPTION	13
6. SOFTWARE CHANGES DESCRIPTION	14
6.1. Validated Corrections/Improvements	14
6.2. Known Issues	15
6.3. New API.....	15
6.4. Minor API prototype change.....	15
6.5. Macro Usage	15



List of Tables

Table 1.	New Features/Enhancements	7
Table 2.	Abbreviations and Definitions	9
Table 3.	Related Documentation	10
Table 4.	Hardware Compatibility	11
Table 5.	Supported Application-Mode VID/PIDs	11
Table 6.	Supported Boot-Mode VID/PIDs	11
Table 7.	Modem and Firmware tested with the SDK.....	12
Table 8.	Release Information	13



Introduction

1.1. Document Scope

This document describes the content of the Linux QMI SDK 03.03.16 release.

1.2. Document Audience

This release note may be distributed to all direct and indirect customers.

1.3. New Features/Enhancements

Table 1. New Features/Enhancements

Feature	Description
Lightweight APIs	This provide functions to directly encode/decode QMI request/response. Please refer to packingdemo sample app and the "Lite-SDK-howto" guide
New API	<ul style="list-style-type: none">• SetLocEngineStateCallback• SLQSSwiGet/SetDyingGaspCfg• SLQSSwiGetDyingGaspStatistics• SLQSSwiClearDyingGaspStatistics• SLQSSetSwiGetResetInfoCallback• SLQSDmsSwiIndicationRegister• SLQSDmsSwiGetResetInfo• SLQSSSetDHCPv4ClientConfig• SetDHCPv4ClientLeaseCallback
Miscellaneous	<ul style="list-style-type: none">• Update SLQSGetPLMNName to support MNC PCS digit• Fix SLQSOMADMGetSessionInfo compatibility with 74xx• Add LOC_Service sample app• typedef ULONG changed from "unsigned long" to "unsinged int"

1.4. Removed Features

Table 2. Removed features

Feature	Description
Sync MTU	Automatically Sync MTU from WDS Runtime Setting. This feature is remove as it is more flexible for developer to manage MTU setting via ifconfig or similar utility

2.

Abbreviations and Definitions

Table 3. Abbreviations and Definitions

Abbreviation/Acronym	Definitions
MSM	Mobile Station Modem
PRI	Product Release Instructions
QMI	Qualcomm MSM Interface
SLQS	Sierra Linux QMI SDK
WP	Work Package

3.

Related Documentation

Table 4. Related Documentation

Ref. #	Doc. #	Document title
[R-1]	4110914	Linux QMI SDK Application Developer's Guide

4.

Compatibility

Table 5. Hardware Compatibility

Devices Compatibility List
AR7554/AR7554RD
EM/MC73xx
MC77xx
MC83x5
MC/SL9090
WP71xx
MC/EM74xx

Note: MC77xx devices must operate in “QMI Mode” and not in “Direct-IP” mode.

To switch device into QMI mode of operation, use the following AT commands:

- **AT!UDPID=68A2**
- **AT!RESET**

Note: MC73xx, set the device using “AT!UDPID=68C0”.

The tables below list the hexadecimal values of the Vendor ID (VID) and Product ID (PID) pairs supported by the Linux QMI SDK.

Table 6. Supported Application-Mode VID/PIDs

VID	1199	1199	1199	1199	1199	1199	1199	1199	3F0
PID	68A2	68C0	9011	9013	9015	9019	9041	9071	371D

Table 7. Supported Boot-Mode VID/PIDs

VID	1199	1199	1199	1199	1199	1199	1199	1199	3F0
PID	68A2	68C0	9010	9012	9014	9018	9040	9070	361D

To check your device’s VID/PID, issue the `lsusb` command. The output will present a list of USB devices with a column showing each device’s manufacturer. The device VID/PID can be read from the row containing the correct device manufacturer. Additionally, on MC77xx devices, you can use the `AT!UDINFO?` command to check VID/PID information. If your VID/PID does not match any of the entries in the tables above, contact your FAE for support.

The following table enumerates the modems with their corresponding firmware that were tested with Linux QMI SDK 03.03.16.

Table 8. Modem and Firmware tested with the SDK

Modem	Firmware
MC7430	SWI9X30C_02.15.00.00
EM/MC7455	SWI9X30C_02.15.00.00
MC7304	SWI9X15C_05.05.67.00
MC7354	SWI9X15C_05.05.66.00
MC7350	SWI9C15C_05.05.58.01
MC7355	SWI9X15C_05.05.58.00
MC7330	SWI9X15C_05.05.58.00
MC7305	SWI9X15C_05.05.58.00
MC7710	SWI9200X_03.05.29.06
MC7750	SWI9600M_03.05.13.02
MC9090	SWI6600U_02.04.05.00
EM7355	SWI9X15C_05.05.66.00
EM7330	SWI9X15C_05.05.66.00
EM7305	SWI9X15C_05.05.58.00

Note: The SDK in general work across all firmware revisions. However, some new API might require a recent firmware.

5.

Software Release Description

Table 9. Release Information

Component	Content
SDK version	03.03.16
Date of generation	15/04/2016
Binary archive name	SLQS03.03.16.bin.tar.gz
MD5 checksum	97dfc3a2d4022be43c2c61504236b024
Source code archive name	SLQS03.03.16.tar.gz
MD5 checksum	5e567dc0953bc99db021ced21e5b5b1b
Processor compatibility	x86, ARM, PowerPC, MIPS
Linux kernel compatibility	2.6.32 to 4.1
USB drivers compatibility	S2.25N2.36

6.

Software Changes Description

6.1. Validated Corrections/Improvements

ID	Description
DEV86808	Check that Firmware Download application may not be disturbed by built-in laptop Sierra modem
DEV86812	New file option ("-f") to be managed by Firmware download tool
DEV87737	Add callback for QMI_LOC_EVENT_ENGINE_STATE_IND
ANO87799	Struct SwiLocGetAutoStartResp and SwiLocSetAutoStartResp use type int instead of defined Sierra type
CUS87807	[Doc] SLQSLOCDeAssData documentation incorrectly describes how to delete all assistance data
CUS88069	information and usage of the LOC API in the SDK
CUS89018	MTU size change in SLQS03.03.11/GobiNet N2.35 causes problems in WAN network
CUS89064	Firmware download completion callback to document events received
DEV89151	Add support for Dying Gasp Linux SLQS SDK APIs
DEV89185	Please add support for MNC PCS digit to SLQSGetPLMNName
DEV89186	SLQSNasGetSysInfo structures to describe how 2 digit MNC values are handled
ANO89272	download_9x30_to_slot uses DEVICE_SHUTDOWN
CUS89278	FwDIdCompletionCbK not triggered when using SLQSDownloadFirmwareToSlot
CUS89279	MC7350: SLQSSDK 03.03.14 patch for compilation
DEV89309	Implement API to indicate a reboot is pending
CUS89324	SLQSupgradeFirmware9x15 and SLQSDownloadFirmwareToSlot to document success values
DEV89332	Add APIs to support DHCPv4 Client Configuration and Lease Status
ANO89506	Update documentation of txInfo fiield in struct nasGetTxRxInfoResp
DEV89594	merge SDK Lite wrapper
ANO89609	[Linux][MC7430][FirmwareDownload] fwDL fails after 9 downloads
ANO90171	Documentation for pMinIntervalTime missing in SLQSLOCStart
ANO90248	[SLQS03.03.15] API doc qaGobiApilms.h update for API supported device
ANO90444	doSLQSSwiGetAllCarrierImages qatest case crash
ANO90445	adapt 8/16bit retry count on 9x30/9x15 on SWIOMA_GET_SESSION_INFO
DEV90585	[Developer Studio FDT] Firmware download failed when launch SDK without root permission
ANO90660	[SLQS03.03.16 scope] firmware download sample application fails to read the image information if there is no '\ ' symbol in the end of the path

6.2. Known Issues

ID	Description
----	-------------

6.3. New API

API	Comment
SLQSSetDHCPv4ClientLeaseStatusCallback	This API enables/disables the DHCP Client V4 Lease Status callback function. The most recent successfully subscribed callback function will be the only function that is invoked when the corresponding event occur
SetLocEngineStateCallback	This API Sends the GPS State Information event to the control point
SLQSSetSwiGetResetInfoCallback	This API set/clear Reset Info callback
SLQSSwiSet/GetDyingGaspCfg	This function set/get Dying GASP Config
SLQSSwiGetDyingGaspStatistics	This function queries Dying GASP Statistics
SLQSSwiClearDyingGaspStatistics	This function Clear Dying GASP Statistics
SLQSDmsSwiIndicationRegister	This function used to set Swi Indication Register
SLQSDmsSwiGetResetInfo	This function is used to get reset info
SLQSSetDHCPv4ClientConfig	This API configures the DHCP Client V4 Configuration

6.4. Minor API prototype change

Note: when updating SDK, please make sure to pull the latest headers from <SDK_ROOT>/api folder

API	Comment
SLQSGetPLMNName	Add MNC PCS status in request structure

6.5. Macro Usage

Macro	Usage
AM_API_MUTEX_TIMEOUT_IN_SEC	This is the timeout time (in seconds) for which the mutex is locked when the SDK is compiled with API_TIMEOUT flag.
API_TIMEOUT	This is a compilation flag. If this flag is defined during compilation, SDK will lock the mutex for a particular time. The locking time is defined by AM_API_MUTEX_TIMEOUT_IN_SEC. If this flag is not defined then the mutex is locked indefinitely.