



# AirPrime RC76xx

## Customer Release Notes for Release 6.2



**SIERRA**  
WIRELESS®

41114091  
2.0  
October 22, 2020

## Important Notice

Due to the nature of wireless communications, transmission and reception of data can never be guaranteed. Data may be delayed, corrupted (i.e., have errors) or be totally lost. Although significant delays or losses of data are rare when wireless devices such as the Sierra Wireless product are used in a normal manner with a well-constructed network, the Sierra Wireless product should not be used in situations where failure to transmit or receive data could result in damage of any kind to the user or any other party, including but not limited to personal injury, death, or loss of property. Sierra Wireless accepts no responsibility for damages of any kind resulting from delays or errors in data transmitted or received using the Sierra Wireless product, or for failure of the Sierra Wireless product to transmit or receive such data.

## Safety and Hazards

Do not operate the Sierra Wireless product in areas where cellular products are not advised without proper device certifications. These areas include environments where cellular radio can interfere such as explosive atmospheres, medical equipment, or any other equipment which may be susceptible to any form of radio interference. The Sierra Wireless product can transmit signals that could interfere with this equipment. Do not operate the Sierra Wireless product in any aircraft, whether the aircraft is on the ground or in flight. In aircraft, the Sierra Wireless product **MUST BE POWERED OFF**. When operating, the Sierra Wireless product can transmit signals that could interfere with various onboard systems.

---

*Note: Some airlines may permit the use of cellular phones while the aircraft is on the ground and the door is open. Sierra Wireless products may be used at this time.*

---

The driver or operator of any vehicle should not operate the Sierra Wireless product while in control of a vehicle. Doing so will detract from the driver or operator's control and operation of that vehicle. In some states and provinces, operating such communications devices while in control of a vehicle is an offence.

## Limitations of Liability

This manual is provided "as is". Sierra Wireless makes no warranties of any kind, either expressed or implied, including any implied warranties of merchantability, fitness for a particular purpose, or noninfringement. The recipient of the manual shall endorse all risks arising from its use.

The information in this manual is subject to change without notice and does not represent a commitment on the part of Sierra Wireless. SIERRA WIRELESS AND ITS AFFILIATES SPECIFICALLY DISCLAIM LIABILITY FOR ANY AND ALL DIRECT, INDIRECT, SPECIAL, GENERAL, INCIDENTAL, CONSEQUENTIAL, PUNITIVE OR EXEMPLARY DAMAGES INCLUDING, BUT NOT LIMITED TO, LOSS OF PROFITS OR REVENUE OR ANTICIPATED PROFITS OR REVENUE ARISING OUT OF THE USE OR INABILITY TO USE ANY SIERRA WIRELESS PRODUCT, EVEN IF SIERRA WIRELESS AND/OR ITS AFFILIATES HAS BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES OR THEY ARE FORESEEABLE OR FOR CLAIMS BY ANY THIRD PARTY.

Notwithstanding the foregoing, in no event shall Sierra Wireless and/or its affiliates aggregate liability arising under or in connection with the Sierra Wireless product, regardless of the number of events, occurrences, or claims giving rise to liability, be in excess of the price paid by the purchaser for the Sierra Wireless product.

## Patents

This product may contain technology developed by or for Sierra Wireless Inc.

This product includes technology licensed from QUALCOMM®.

This product is manufactured or sold by Sierra Wireless Inc. or its affiliates under one or more patents licensed from MMP Portfolio Licensing.

## Copyright

© 2020 Sierra Wireless. All rights reserved.

## Trademarks

Sierra Wireless®, AirPrime®, AirLink®, AirVantage®, WISMO®, ALEOS® and the Sierra Wireless and Open AT logos are registered trademarks of Sierra Wireless, Inc. or one of its subsidiaries.

Watcher® is a registered trademark of NETGEAR, Inc., used under license.

Windows® and Windows Vista® are registered trademarks of Microsoft Corporation.

Macintosh® and Mac OS X® are registered trademarks of Apple Inc., registered in the U.S. and other countries.

QUALCOMM® is a registered trademark of QUALCOMM Incorporated. Used under license.

ThreadX® RTOS is a registered trademark of Express Logic, Inc.

Other trademarks are the property of their respective owners.

## Contact Information

Sales information and technical support, including warranty and returns	Web: <a href="http://sierrawireless.com/company/contact-us/">sierrawireless.com/company/contact-us/</a> Global toll-free number: 1-877-687-7795 6:00 am to 5:00 pm PST
Corporate and product information	Web: <a href="http://sierrawireless.com">sierrawireless.com</a>

# Document History

Version	Date	Updates
1.0	March 12, 2020	Creation – Release 2 BP 8
1.01	July 29, 2020	Release 4
1.02	July 29, 2020	Release 5
1.03	July 29, 2020	Release 6
1.04	July 29, 2020	Release 6.1
1.05	October 06, 2020	Release 6.2
2.0	October 22, 2020	Release 6.2 to be published on the Source



# Contents

<b>1. INTRODUCTION .....</b>	<b>7</b>
1.1. Document Scope .....	7
1.2. Document Audience .....	7
<b>2. ABBREVIATIONS AND DEFINITIONS .....</b>	<b>8</b>
<b>3. RELATED DOCUMENTATION .....</b>	<b>9</b>
<b>4. COMPATIBILITY .....</b>	<b>10</b>
4.1. Hardware Compatibility .....	10
<b>5. SWI9X07H RELEASE 6.2 .....</b>	<b>11</b>
5.1. Software Release Description .....	11
5.1.1. Release Identification .....	11
5.1.2. Software Tools Version.....	11
5.1.3. Released Files .....	12
5.2. Software Changes Description .....	13
<b>6. WI9X07H RELEASE 6.1 .....</b>	<b>14</b>
6.1. Software Release Description .....	14
6.1.1. Release Identification .....	14
6.1.2. Software Tools Version.....	14
6.1.3. Released Files .....	15
6.2. Software Changes Description .....	16
6.3. Restrictions/Known Issues .....	16
<b>7. SWI9X07H RELEASE 6 .....</b>	<b>17</b>
7.1. Software Release Description .....	17
7.1.1. Release Identification .....	17
7.1.2. Software Tools Version.....	17
7.1.3. Released Files .....	18
7.2. Software Changes Description .....	19
7.3. Restrictions/Known Issues .....	19
<b>8. SWI9X07H RELEASE 5 .....</b>	<b>20</b>
8.1. Software Release Description .....	20
8.1.1. Release Identification .....	20
8.1.2. Software Tools Version.....	20
8.1.3. Released Files .....	21
8.2. Software Changes Description .....	22
8.3. Restrictions/Known Issues .....	22
<b>9. SWI9X07H RELEASE 4 .....</b>	<b>23</b>
9.1.3. Released Files .....	24

---

9.2.	Software Changes Description .....	25
9.3.	Restrictions/Known Issues .....	25
<b>10.</b>	<b>SWI9X07H RELEASE 2 BP 8 .....</b>	<b>26</b>
10.1.3.	Released Files .....	27
10.2.	Software Changes Description .....	28



# 1. Introduction

## 1.1. Document Scope

This document describes RC76xx firmware releases.

## 1.2. Document Audience

These release notes may be distributed to all direct and indirect customers.



## 2. Abbreviations and Definitions

Table 1. Abbreviations and Definitions

Abbreviation/Acronym	Definitions
AT	Access Terminal, Attention
EDL	Emergency Download
FDT	Firmware Download Tool
GCF	Global Certification Forum
PSM	Power Saving Mode
QMI	Qualcomm Messaging Interface
SDP	Software Download Protocol



## 3. Related Documentation

- [1] AirPrime RC7611 Product Technical Specification  
Reference number: 41113440
- [2] AirPrime RC76xx AT Command Reference Guide  
Reference number: 41113566
- [3] AirPrime RC76xx Customer Release Notes  
Reference number: 41114005

## >> 4. Compatibility

### 4.1. Hardware Compatibility

Table 2. Hardware Compatibility

AirPrime Compatibility List	
RC7611	LTE Cat-4, LTE bands 2/4/5/12/13/14/25/26/66/71
RC7611-1	LTE Cat-1, LTE bands 2/4/5/12/13/14/25/26/66/71
RC7620	LTE Cat-4, LTE bands 1/3/7/8/20/28(A+B) WCDMA bands 1/8, GSM900/1800
RC7620-1	LTE Cat-1, LTE bands 1/3/7/8/20/28(A+B) WCDMA bands 1/8, GSM900/1800

## >> 5. SWI9X07H Release 6.2

SWI9X07H Release 6.2 is a major release.

### 5.1. Software Release Description

#### 5.1.1. Release Identification

Table 3. Firmware Release Information

Component	Revision
Modem Firmware	SWI9X07H_00.03.03.00 2bb7a4 jenkins 2020/04/15 07:57:29
Legato Application Framework	20.03.0.m4.ThreadX.rc2
Binary Size	28.4 MB (compressed one-click exe)
IMEI SV	14
Qualcomm baseline	MDM9607.TX.1.0 Post-CS 0.0.064.1
Qualcomm SBA	MDM9607.TX.1.0 Post-CS 0.0.064.1.275918.1
Supported H/W	RC7611, RC7611-1, RC7620, RC7620-1

#### 5.1.2. Software Tools Version

---

Note: Download the following tools from <https://source.sierrawireless.com/>

---

Table 4. Software Tools Version

Software Tools Name	Version
Windows Driver Package	B4956
Linux Drivers	S2.36N2.60
Linux SDK	SLQS04.00.23

### 5.1.3. Released Files

Table 5. RC76xx Approved Packages

File	Carrier	Modem Firmware	Config	Base Legato System	Comment
<b>RC7611/RC7611-1 Approved/Pending</b>					
RC76xx_Release6.2_ATT_7611.exe	ATT	SWI9X07H_00.03.03.00	001.040_000	20.03.0.m4.ThreadX.rc2	ATT approved
RC76xx_Release6.2_GENERIC_GCF_7611.exe	Generic	SWI9X07H_00.03.03.00	001.046_000	20.03.0.m4.ThreadX.rc2	PTCRB / GCF approved
RC76xx_Release6.2_SIERRA_R2C_7611.exe	Sierra	SWI9X07H_00.03.03.00	000.027_000	20.03.0.m4.ThreadX.rc2	R2C approved
RC76xx_Release6.2_VERIZON_7611.exe	Verizon	SWI9X07H_00.03.03.01	001.040_000	20.03.0.m4.ThreadX.rc2	Verizon approved
RC76xx_Release6.2_TMO_7611.exe	TMO	SWI9X07H_00.03.03.00	001.024_000	20.03.0.m4.ThreadX.rc2	TMO approved
<b>RC7620/RC7620-1 Approved/Pending</b>					
RC76xx_Release6.2_GENERIC_GCF_7620.exe	Generic	SWI9X07H_00.03.03.00	001.043_000	20.03.0.m4.ThreadX.rc2	GCF approved
RC76xx_Release6.2_SIERRA_R2C_7620.exe	Sierra	SWI9X07H_00.03.03.00	000.027_000	20.03.0.m4.ThreadX.rc2	R2C approved

Function	Files
Firmware components	9999999_9909667_SWI9X07H_00.03.03.00_00_GENERIC_001.043_000.spk (RC7620 GCF) 9999999_9909667_SWI9X07H_00.03.03.00_00_GENERIC_001.046_000.spk (RC7611 PTCRB/GCF) 9999999_9909693_SWI9X07H_00.03.03.00_00_ATT_001.040_000.spk (RC7611 ATT) 9999999_9909694_SWI9X07H_00.03.03.01_00_VERIZON_001.040_000.spk (RC7611 Verizon) 9999999_9909696_SWI9X07H_00.03.03.00_00_TMO_001.024_000.spk (RC7611 TMO) 9999999_9909717_SWI9X07H_00.03.03.00_00_SIERRA_000.027_000.spk (RC7611/RC7620 R2C)  appl_20.03.0.m4.ThreadX.rc2.cwe
These files will be available for download at <a href="https://source.sierrawireless.com/">https://source.sierrawireless.com/</a>	

## 5.2. Software Changes Description

The following changes were implemented in Release 6.2 since Release 6.

Table 6. Software Changes Description for R2C

ID	Description	Impacted Domain
QT19X07TX-2355	RC7620 R6 : if SELRAT 01 , Synchronize with AVMS Failed	



## 6. WI9X07H Release 6.1

SWI9X07H Release 6.1 is a major release.

### 6.1. Software Release Description

#### 6.1.1. Release Identification

Table 7. Firmware Release Information

Component	Revision
Modem Firmware	SWI9X07H_00.03.03.01 707452 jenkins 2020/05/20 07:13:09
Legato Application Framework	20.03.0.m1.ThreadX.rc11
Binary Size	28.4 MB (compressed one-click exe)
IMEI SV	15
Qualcomm baseline	MDM9607.TX.1.0 Post-CS 0.0.064.1
Qualcomm SBA	MDM9607.TX.1.0 Post-CS 0.0.064.1.275918.1
Supported H/W	RC7611, RC7611-1, RC7620, RC7620-1

#### 6.1.2. Software Tools Version

---

*Note:* Download the following tools from <https://source.sierrawireless.com/>

---

Table 8. Software Tools Version

Software Tools Name	Version
Windows Driver Package	B4956
Linux Drivers	S2.36N2.60
Linux SDK	SLQS04.00.23

### 6.1.3. Released Files

Table 9. RC76xx Approved Packages

File	Carrier	Modem Firmware	Config	Base Legato System	Comment
<b>RC7611/RC7611-1 Approved/Pending</b>					
RC76xx_Release6.1_VERIZON_7611.exe	Verizon	SWI9X07H_00.03.03.01	001.040_000	20.03.0.m1.ThreadX.rc11	Verizon
<b>Test</b>					
RC76xx_Release6.1_SIERRA_test.exe	Sierra	SWI9X07H_00.03.03.01	000.029_000	20.03.0.m1.ThreadX.rc11	Test
RC76xx_Release6.1_VERIZON_test.exe	Verizon	SWI9X07H_00.03.03.01	001.040_000	20.03.0.m1.ThreadX.rc11	Test
RC76xx_Release6.1_ATT_test.exe	ATT	SWI9X07H_00.03.03.01	001.043_000	20.03.0.m1.ThreadX.rc11	Test
RC76xx_Release6.1_SPRINT_test	SPRINT	SWI9X07H_00.03.03.01	001.026_000	20.03.0.m1.ThreadX.rc11	Test
RC76xx_Release6.1_TMO_test.exe	TMO	SWI9X07H_00.03.03.01	001.026_000	20.03.0.m1.ThreadX.rc11	Test
RC76xx_Release6.1_GENERIC_test.exe	Generic	SWI9X07H_00.03.03.01	001.050_000	20.03.0.m1.ThreadX.rc11	Test
RC76xx_Release6.1_VODAFONE_test.exe	VODAFONE	SWI9X07H_00.03.03.01	000.024_000	20.03.0.m1.ThreadX.rc11	Test

Function	Files
Firmware components	9999999_9909694_SWI9X07H_00.03.03.01_00_VERIZON_001.040_000.spk
These files will be available for download at <a href="https://source.sierrawireless.com/">https://source.sierrawireless.com/</a>	

## 6.2. Software Changes Description

The following changes were implemented in Release 6.1 since Release 6.

Table 10. Software Changes Description for Verizon

ID	Description	Impacted Domain
QT19X07TX-1789	Sync WP76XX modem_proc by cherry-pick	
QT19X07TX-1930	[LwM2M][DTLS] Rehandshake upon decryption error on received packet	
QT19X07TX-1933	Merge prod-wp76xx(cbf23012 to ac21d2a1)	
QT19X07TX-1940	Increment SVN on RC76 main branch to 15	

## 6.3. Restrictions/Known Issues

This section presents restrictions or known issues that must be considered regarding this release.

ID	Description (What/When)
NA	NA

# >> 7. SWI9X07H Release 6

SWI9X07H Release 6 is a major release.

## 7.1. Software Release Description

### 7.1.1. Release Identification

Table 11. Firmware Release Information

Component	Revision
Modem Firmware	SWI9X07H_00.03.03.00 2bb7a4 jenkins 2020/04/15 07:57:29
Legato Application Framework	20.03.0.m1.ThreadX.rc11
Binary Size	29.1 MB (compressed one-click exe)
IMEI SV	14
Qualcomm baseline	MDM9607.TX.1.0 Post-CS 0.0.064.1
Qualcomm SBA	MDM9607.TX.1.0 Post-CS 0.0.064.1.275918.1
Supported H/W	RC7611, RC7611-1, RC7620, RC7620-1

### 7.1.2. Software Tools Version

---

*Note:* Download the following tools from <https://source.sierrawireless.com/>

---

Table 12. Software Tools Version

Software Tools Name	Version
Windows Driver Package	B4956
Linux Drivers	S2.36N2.60
Linux SDK	SLQS04.00.23

### 7.1.3. Released Files

Table 13. RC76xx Approved Packages

File	Carrier	Modem Firmware	Config	Base Legato System	Comment
<b>RC7611/RC7611-1 Approved/Pending</b>					
RC76xx_Release6_GENERIC_GCF_7611.exe	GENERIC (GCF)	SWI9X07H_00.03.03.00	001.046_000	20.03.0.m1.ThreadX.rc11	GCF approved
RC76xx_Release6_SIERRA_R2C_7611.exe	Sierra	SWI9X07H_00.03.03.00	000.027_000	20.03.0.m1.ThreadX.rc11	R2C
<b>Test</b>					
RC76xx_Release6_SIERRA_test.exe	Sierra	SWI9X07H_00.03.03.00	000.027_000	20.03.0.m1.ThreadX.rc11	Test
RC76xx_Release6_VERIZON_test.exe	Verizon	SWI9X07H_00.03.03.00	001.038_000	20.03.0.m1.ThreadX.rc11	Test
RC76xx_Release6_ATT_test.exe	ATT	SWI9X07H_00.03.03.00	001.040_000	20.03.0.m1.ThreadX.rc11	Test
RC76xx_Release6_SPRINT_test	SPRINT	SWI9X07H_00.03.03.00	001.023_000	20.03.0.m1.ThreadX.rc11	Test
RC76xx_Release6_TMO_test.exe	TMO	SWI9X07H_00.03.03.00	001.024_000	20.03.0.m1.ThreadX.rc11	Test
RC76xx_Release6_GENERIC_test.exe	Generic	SWI9X07H_00.03.03.00	001.046_000	20.03.0.m1.ThreadX.rc11	Test
RC76xx_Release6_VODAFONE_test.exe	VODAFONE	SWI9X07H_00.03.03.00	000.022_000	20.03.0.m1.ThreadX.rc11	Test

Function	Files
Firmware components	9999999_9909667_SWI9X07H_00.03.03.00_00_GENERIC_001.046_000.spk 9999999_9909717_SWI9X07H_00.03.03.00_00_SIERRA_000.027_000.spk
These files will be available for download at <a href="https://source.sierrawireless.com/">https://source.sierrawireless.com/</a>	

## 7.2. Software Changes Description

The following changes were implemented in Release 6 since Release 5.

Table 14. Software Changes Description for R2C

ID	Description	Impacted Domain
QT19X07TX-1903	Using oneClick file , Module freezes on WDSS command until next manual Power OFF/ON	
QT19X07TX-1905	RC7620 R5B1 After FOTA the module doesn't connect server Airvantage	
QT19X07TX-1915	[AVMS][FOTA] AVMS command causes module freezes after FOTA and job status is failed	
QT19X07TX-1921	[AVMS][UPD] The module cannot start downloading package from the AVMS server automatically after initiating a connection for FOTA update job	

## 7.3. Restrictions/Known Issues

This section presents restrictions or known issues that must be considered regarding this release.

ID	Description (What/When)
NA	NA

## >> 8. SWI9X07H Release 5

SWI9X07H Release 5 is a major release.

### 8.1. Software Release Description

#### 8.1.1. Release Identification

Table 15. Firmware Release Information

Component	Revision
Modem Firmware	SWI9X07H_00.03.03.00 2bb7a4 jenkins 2020/04/15 07:57:29
Legato Application Framework	20.03.0.m1.ThreadX.rc7
Binary Size	29.1 MB (compressed one-click exe)
IMEI SV	14
Qualcomm baseline	MDM9607.TX.1.0 Post-CS 0.0.064.1
Qualcomm SBA	MDM9607.TX.1.0 Post-CS 0.0.064.1.275918.1
Supported H/W	RC7611, RC7611-1, RC7620, RC7620-1

#### 8.1.2. Software Tools Version

---

Note: Download the following tools from <https://source.sierrawireless.com/>

---

Table 16. Software Tools Version

Software Tools Name	Version
Windows Driver Package	B4956
Linux Drivers	S2.36N2.60
Linux SDK	SLQS04.00.23

### 8.1.3. Released Files

Table 17. RC76xx Approved Packages

File	Carrier	Modem Firmware	Config	Base Legato System	Comment
<b>RC7611/RC7611-1 Approved/Pending</b>					
RC76xx_Release5_ATT_7611.exe	ATT	SWI9X07H_00.03.03.00	001.040_000	20.03.0.m1.ThreadX.rc7	ATT approved
<b>Test</b>					
RC76xx_Release5_SIERRA_test.exe	Sierra	SWI9X07H_00.03.03.00	001.027_000	20.03.0.m1.ThreadX.rc7	Test
RC76xx_Release5_VERIZON_test.exe	Verizon	SWI9X07H_00.03.03.00	001.038_000	20.03.0.m1.ThreadX.rc7	Test
RC76xx_Release5_ATT_test.exe	ATT	SWI9X07H_00.03.03.00	001.040_000	20.03.0.m1.ThreadX.rc7	Test
RC76xx_Release5_SPRINT_test	SPRINT	SWI9X07H_00.03.03.00	001.023_000	20.03.0.m1.ThreadX.rc7	Test
RC76xx_Release5_TMO_test.exe	TMO	SWI9X07H_00.03.03.00	001.024_000	20.03.0.m1.ThreadX.rc7	Test
RC76xx_Release5_GENERIC_test.exe	Generic	SWI9X07H_00.03.03.00	001.046_000	20.03.0.m1.ThreadX.rc7	Test
RC76xx_Release5_VODAFONE_test.exe	VODAFONE	SWI9X07H_00.03.03.00	000.022_000	20.03.0.m1.ThreadX.rc7	Test

Function	Files
Firmware components	9999999_9909693_SWI9X07H_00.03.03.00_00_ATT_001.040_000.spk
These files will be available for download at <a href="https://source.sierrawireless.com/">https://source.sierrawireless.com/</a>	

## 8.2. Software Changes Description

The following changes were implemented in Release 6 since Release 5.

Table 18. Software Changes Description for R2C

ID	Description	Impacted Domain
QTI9X07TX-1279	[AVMS] The value of some resources of the location object are not synchronized on AVMS server.	
QTI9X07TX-1820	[AVMS] RC7620 FOTA and Power Off during Download failed and no more FOTA can be done.	
QTI9X07TX-1280	[AVMS] The value of SMS Tx Counter and SMS Rx Counter are not synchronized on AVMS server.	
QTI9X07TX-1128	[AVMS][WDSI]The module re-initiates a bootstrap session after rebooting the module.	
QTI9X07TX-1373	[RC7620][AvMS] Module can't register the server right away.	

Table 19. Software Changes Description for AT&T

ID	Description	Impacted Domain
QTI9X07TX-1702	[RC7611][AT&T][AVL_DDR][10776 v19.3][LTE-BTR-1-8224][IMS as its usage setting is not expected]	
QTI9X07TX-1732	[RC7611][AT&T][AVL_DDR][10776 v19.3][LTE-BTR-1-8266][Data browsing did not work]	
QTI9X07TX-1734	[RC7611][AT&T][AVL_DDR][10776 v19.3][Defect#878220][LTE-BTR-1-7843][UE doesn't register within 8 mins]	
QTI9X07TX-1740	[RC7611][AT&T][AVL_DDR][10776 v19.3][Defect#878218][LTE-BTR-1-7907][Unable to Verify that the UE finds the performs Attach procedure on any cell except E-Cell-A]	
QTI9X07TX-1741	[RC7611][AT&T][AVL_DDR][10776 v19.3][Defect#878219][LTE-BTR-1-7930][no PING Replies have been received as Limit is 5 seconds]	
QTI9X07TX-1807	[RC7611][AT&T][AVL_DDR][10776 v19.3][Defect#878283][LTE-BTR-1529][UE capability is mismatch]	
QTI9X07TX-1822	[RC7611][AT&T][Defect#389708][10776 Pre-Lab Test Results - APTN test review – DDA LE-4. (LE-4 CR DVM)]	

## 8.3. Restrictions/Known Issues

This section presents restrictions or known issues that must be considered regarding this release.

ID	Description (What/When)
NA	NA

## 9. SWI9X07H Release 4

SWI9X07H Release 4 is a major release.

### 9.1. Software Release Description

#### 9.1.1. Release Identification

##### Firmware Release Information

Component	Version
Modem Firmware	SWI9X07H_00.03.03.00 2bb7a4 jenkins 2020/04/15 07:57:29
Legato Application Framework	20.03.0.m1.ThreadX.rc6
Binary Size	29.1 MB (compressed one-click exe)
IMEI SV	14
Qualcomm Stack Version	Post-CS 0.0.064.1
Supported H/W	RC7611, RC7611-1, RC7620, RC7620-1

#### 9.1.2. Software Tools Version

---

Download the following tools from <https://source.sierrawireless.com/>

---

##### Software Tools Version

Software Tools Name	Version
Windows Driver Package	B4956
Linux Drivers	S2.36N2.60
Linux SDK	SLQS04.00.23

### 9.1.3. Released Files

Table 20. RC76xx Approved Packages

File	Carrier	Modem Firmware	Config	Base Legato System	Comment
<b>RC7611/RC7611-1 Approved/Pending</b>					
RC76xx_Release4_GENERIC_GCF_7620.exe	GENERIC (GCF)	SWI9X07H_00.03.03.00	001.043_000	20.03.0.m1.ThreadX.rc6	GCF approved
<b>Test</b>					
RC76xx_Release4_SIERRA_test.exe	Sierra	SWI9X07H_00.03.03.00	001.024_000	20.03.0.m1.ThreadX.rc6	Test
RC76xx_Release4_VERIZON_test.exe	Verizon	SWI9X07H_00.03.03.00	001.035_000	20.03.0.m1.ThreadX.rc6	Test
RC76xx_Release4_ATT_test.exe	ATT	SWI9X07H_00.03.03.00	001.037_000	20.03.0.m1.ThreadX.rc6	Test
RC76xx_Release4_SPRINT_test	SPRINT	SWI9X07H_00.03.03.00	001.021_000	20.03.0.m1.ThreadX.rc6	Test
RC76xx_Release4_TMO_test.exe	TMO	SWI9X07H_00.03.03.00	001.022_000	20.03.0.m1.ThreadX.rc6	Test
RC76xx_Release4_GENERIC_test.exe	Generic	SWI9X07H_00.03.03.00	001.043_000	20.03.0.m1.ThreadX.rc6	Test
RC76xx_Release4_VODAFONE_test.exe	VODAFONE	SWI9X07H_00.03.03.00	000.019_000	20.03.0.m1.ThreadX.rc6	Test

Function	Files
Firmware components	9999999_9909667_SWI9X07H_00.03.03.00_00_GENERIC_001.043_000.spk
These files will be available for download at <a href="https://source.sierrawireless.com/">https://source.sierrawireless.com/</a>	

## 9.2. Software Changes Description

The following changes were implemented in Release 6 since Release 5.

Table 21. Software Changes Description for R2C

ID	Description	Impacted Domain
QTI9X07TX-1439	AVMS claimed not implemented after FOTA succeed	
QTI9X07TX-1469	AvMS related AT command will responds "NOT IMPLEMENTED" after upgrade from v2.08 to v2.11	

Table 22. Software Changes Description for Verizon

ID	Description	Impacted Domain
[QTI9X07-4228]	[LWM2M] Add !DM command documentation with md files	
[QTI9X07-4364]	LwM2M AT&T Initial skeleton and device tree support	
[QTI9X07-4447]	LwM2M Move BootstrapConfigurationSetDefault to custom	
[QTI9X07-4449]	LwM2M - Move paramStorage enums to custom	
[QTI9X07-4455]	LwM2M Fix typo ApnConnetion as ApnConnection in various locations	
[QTI9X07-4472]	LwM2M bootstrap inactive control when multiple bootstrap instances are defined	
[QTI9X07-4472]	LwM2M bootstrap inactive control when multiple bootstrap instances are defined	
[QTI9X07TX-1488]	[VZW][LWM2M][Diagnostic] Failed r/w (4/0/30000/1) & (4/0/30000/2)	
[QTI9X07TX-1659]	[LwM2M] Update SWI API lwm2m_log_uri() argument uriP with const	

## 9.3. Restrictions/Known Issues

This section presents restrictions or known issues that must be considered regarding this release.

ID	Description (What/When)
[QTI9X07TX-1171]	[AVMS] FOTA download progress is very slow



# 10. SWI9X07H Release 2 BP 8

SWI9X07H Release 2 BP 8 is a minor release from Release 2.

## 10.1. Software Release Description

### 10.1.1. Release Identification

#### Firmware Release Information

Component	Version
Modem Firmware	SWI9X07H_00.02.18.00 1ce0ac jenkins 2020/03/11 03:56:19
Legato Application Framework	20.02.0.ThreadX.rc3
Binary Size	28.3 MB (compressed one-click exe)
IMEI SV	10
Qualcomm Stack Version	Post-CS 0.0.061.1.259087.1
Supported H/W	RC7611, RC7611-1, RC7620, RC7620-1

### 10.1.2. Software Tools Version

---

Download the following tools from <https://source.sierrawireless.com/>

---

#### Software Tools Version

Software Tools Name	Version
Windows Driver Package	B4956
Linux Drivers	S2.36N2.60
Linux SDK	SLQS04.00.23

### 10.1.3. Released Files

Table 23. RC76xx Approved Packages

File	Carrier	Modem Firmware	Config	Base Legato System	Comment
RC76xx_Release2_SWI9X07H_00.02.18.0_0_ATT_test.exe	ATT	SWI9X07H_00.02.18.00	001.030_000	20.02.0.ThreadX.rc3	
RC76xx_Release2_SWI9X07H_00.02.18.0_0_VERIZON_test.exe	Verizon	SWI9X07H_00.02.18.00	001.027_000	20.02.0.ThreadX.rc3	
RC76xx_Release2_SWI9X07H_00.02.18.0_0_GENERIC_test.exe	Generic	SWI9X07H_00.02.18.00	001.035_000	20.02.0.ThreadX.rc3	

Function	Files
Firmware components	9999999_9909694_SWI9X07H_00.02.18.00_00_VERIZON_001.027_000.spk 9999999_9909693_SWI9X07H_00.02.18.00_00_ATT_001.030_000.spk 9999999_9909667_SWI9X07H_00.02.18.00_00_GENERIC_001.035_000.spk
These files will be available for download at <a href="https://source.sierrawireless.com/">https://source.sierrawireless.com/</a>	

## 10.2. Software Changes Description

The following are changes in Release 2 BP8 since Release 2.

Table 24. Software Changes Description

ID	Description	Impacted Domain
QT19X07TX-1115	Update TS.25 to 2020.Jan.06	
QT19X07TX-1201	AT!DMREAD does not return any data	
QT19X07TX-1264	The module will crash when write 5/0/1 package URL on module	
QT19X07TX-1246	AT!DMREAD="3/0/19" returns empty	
QT19X07TX-1472	[LWM2M] Fail to register to Verizon Repo server when MSISDN not ready	