



**WP76xx R13.1.1 / R13.2.1 /
R13.3.1**

Customer Release Notes



SIERRA
WIRELESS®

41114343
Rev. 1.0

Important Notice

Due to the nature of wireless communications, transmission and reception of data can never be guaranteed. Data may be delayed, corrupted (i.e., have errors) or be totally lost. Although significant delays or losses of data are rare when wireless devices such as the Sierra Wireless product are used in a normal manner with a well-constructed network, the Sierra Wireless product should not be used in situations where failure to transmit or receive data could result in damage of any kind to the user or any other party, including but not limited to personal injury, death, or loss of property. Sierra Wireless accepts no responsibility for damages of any kind resulting from delays or errors in data transmitted or received using the Sierra Wireless product, or for failure of the Sierra Wireless product to transmit or receive such data.

Safety and Hazards

Do not operate the Sierra Wireless product in areas where blasting is in progress, where explosive atmospheres may be present, near medical equipment, near life support equipment, or any equipment which may be susceptible to any form of radio interference. In such areas, the Sierra Wireless product **MUST BE POWERED OFF**. The Sierra Wireless product can transmit signals that could interfere with this equipment.

Do not operate the Sierra Wireless product in any aircraft, whether the aircraft is on the ground or in flight. In aircraft, the Sierra Wireless product **MUST BE POWERED OFF**. When operating, the Sierra Wireless product can transmit signals that could interfere with various onboard systems.

Note: Some airlines may permit the use of cellular phones while the aircraft is on the ground and the door is open. Sierra Wireless products may be used at this time.

The driver or operator of any vehicle should not operate the Sierra Wireless product while in control of a vehicle. Doing so will detract from the driver or operator's control and operation of that vehicle. In some states and provinces, operating such communications devices while in control of a vehicle is an offence.

Limitation of Liability

The information in this manual is subject to change without notice and does not represent a commitment on the part of Sierra Wireless. SIERRA WIRELESS AND ITS AFFILIATES SPECIFICALLY DISCLAIM LIABILITY FOR ANY AND ALL DIRECT, INDIRECT, SPECIAL, GENERAL, INCIDENTAL, CONSEQUENTIAL, PUNITIVE OR EXEMPLARY DAMAGES INCLUDING, BUT NOT LIMITED TO, LOSS OF PROFITS OR REVENUE OR ANTICIPATED PROFITS OR REVENUE ARISING OUT OF THE USE OR INABILITY TO USE ANY SIERRA WIRELESS PRODUCT, EVEN IF SIERRA WIRELESS AND/OR ITS AFFILIATES HAS BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES OR THEY ARE FORESEEABLE OR FOR CLAIMS BY ANY THIRD PARTY.

Notwithstanding the foregoing, in no event shall Sierra Wireless and/or its affiliates aggregate liability arising under or in connection with the Sierra Wireless product, regardless of the number of events, occurrences, or claims giving rise to liability, be in excess of the price paid by the purchaser for the Sierra Wireless product.

Patents

This product may contain technology developed by or for Sierra Wireless Inc. This product includes technology licensed from QUALCOMM®. This product is manufactured or sold by Sierra Wireless Inc. or its affiliates under one or more patents licensed from MMP Portfolio Licensing.

Copyright © 2021 Sierra Wireless. All rights reserved.

Trademarks Sierra Wireless®, AirLink®, AirVantage® and the Sierra Wireless logo are registered trademarks of Sierra Wireless.

Windows® and Windows Vista® are registered trademarks of Microsoft Corporation.

Macintosh® and Mac OS X® are registered trademarks of Apple Inc., registered in the U.S. and other countries.

QUALCOMM® is a registered trademark of QUALCOMM Incorporated. Used under license from LTE product manuals%%

Other trademarks are the property of their respective owners.

Contact Information

Sales information and technical support, including warranty and returns	Web: sierrawireless.com/company/contact-us/ Global toll-free number: 1-877-687-7795 6:00 am to 5:00 pm PST
Corporate and product information	Web: sierrawireless.com

Revision History

Revision number	Release date	Changes
1.0	December 2021	Creation

>> Contents

Introduction	5
Compatibility	6
Hardware Compatibility	6
SWI9X07Y Release 13.1.1	7
Software Release Description	7
Release Identification	7
Software Tools Version	8
Released Files	9
Software Changes Description	11
Known Issues	12
SWI9X07Y Release 13.2.1	14
Software Release Description	14
Release Identification	14
Software Tools Version	15
Released Files	16
Software Changes Description	17
Known Issues	18
SWI9X07Y Release 13.3.1	20
Software Release Description	20
Release Identification	20
Software Tools Version	21
Released Files	22
Software Changes Description	23
Known Issues	24
Appendix	25
List of Abbreviations	25
List of References	25

>> 1: Introduction

This document describes WP76xx firmware releases. These release notes may be distributed to all direct and indirect customers.

Compatibility

Hardware Compatibility

Product compatibility list
WP7601 - LTE Cat-4, LTE bands 4/13
WP7601-1 - LTE Cat-1, LTE bands 4/13
WP7603 - LTE Cat-4, LTE bands 2/4/5/12, WCDMA bands 2/4/5
WP7603-1 - LTE Cat-1, LTE bands 2/4/5/12, WCDMA bands 2/4/5
WP7605 – LTE Cat-4, LTE bands 1/3/8/11/18/19/21, WCDMA bands 1,6,19
WP7605-1 – LTE Cat-1, LTE bands 1/3/8/11/18/19/21, WCDMA bands 1,6,19
WP7607 - LTE Cat-4, LTE bands 1/3/7/8/20/28, WCDMA bands 1/8, GSM900/1800
WP7607-1 - LTE Cat-1, LTE bands 1/3/7/8/20/28, WCDMA bands 1/8, GSM900/1800
WP7608 - LTE Cat-4, LTE bands 1/3/5/8/40/41(partial) WCDMA bands 1/8, GSM900/1800
WP7608-1 - LTE Cat-1, LTE bands 1/3/5/8/40/41(partial) WCDMA bands 1/8, GSM900/1800
WP7609 - LTE Cat-4, LTE bands 1/3/5/7/8/28, WCDMA bands 1/5/8, GSM900/1800
WP7610 - LTE Cat-4, LTE bands 2/4/5/12/13/14/17/66, WCDMA bands 2/4/5
WP7611 – LTE Cat-4 LTE bands 2/4/5/12/13/14/25/26/66/71, WCDMA bands 2/4/5
WP7611-1 – LTE Cat-1, LTE bands 2/4/5/12/13/14/25/26/66/71, WCDMA bands 2/4/5

>> 2: SWI9X07Y Release 13.1.1

Release 13.1.1 is a point release to Release 13.1 with minor updates of alternate memory drivers for:

- WP7603 / WP7603-1
- WP7607 / WP7607-1
- WP7608 / WP7608-1
- WP7609
- WP7610

Software Release Description

Release Identification

Component	Revision
Modem Firmware	SWI9X07Y_02.28.03.03 000000 jenkins 2019/05/21 03:33:04
Linux Firmware	SWI9X07Y_02.28.06.01 2021-08-19_11:14:24
MCU Firmware	002.011 (embedded as a binary in the Linux image, not distributed as a separate component)
Legato Application Framework	19.02.0_4cb954265427b8c2c668a010ff5be274
Binary Size	61MB (compressed one-click .exe file)
IMEI SV	6
Qualcomm Stack Version	MDM9607.LE.2.0-00161-STD.PROD-1
Linux Kernel Version	Linux version 3.18.131 (oe-user@oe-host) (gcc version 7.3.0 (GCC)) #1 PREEMPT Thu Aug 19 11:02:22 UTC 2021
Supported H/W	WP7603 / WP7603-1 WP7607 / WP7607-1 WP7608 / WP7608-1 WP7609 WP7610

Software Tools Version

S/W Tools Name	Version
Windows Driver Package	B4836
Windows SDK	None
Skylight	None
Linux Drivers	S2.36N2.57
Linux SDK	SLQS04.00.20

*Available in <https://source.sierrawireless.com>

Released Files

File	Carrier	Modem Firmware	Config	Linux Distribution	Base Legato System	Comment
WP7603/WP7603-1 Approved						
WP76xx_Release-13.1.1_ATT.exe	ATT	SWI9X07Y_02.28.03.01	002.071_006	SWI9X07Y_02.28.06.01	19.02.0	AT&T Approved
WP76xx_Release-13.1.1_GENERIC_PTCRB.exe	GENERIC (PTCRB)	SWI9X07Y_02.28.03.01	002.064_003	SWI9X07Y_02.28.06.01	19.02.0	PTCRB Approved
WP76xx_Release-13.1.1_SIERRA_GCF.exe	SIERRA (GCF)	SWI9X07Y_02.28.03.03	001.026_003	SWI9X07Y_02.28.06.01	19.02.0	GCF Approved
WP7607 / WP7607-1 Approved						
WP76xx_Release-13.1.1_GENERIC_GCF.exe	GENERIC (GCF)	SWI9X07Y_02.28.03.03	002.068_003	SWI9X07Y_02.28.06.01	19.02.0	GCF Approved
WP76xx_Release-13.1.1_SIERRA_GCF.exe	SIERRA (GCF)	SWI9X07Y_02.28.03.03	001.026_003	SWI9X07Y_02.28.06.01	19.02.0	GCF Approved
WP7608 / WP7608-1 Approved						
WP76xx_Release-13.1.1_GENERIC_GCF.exe	GENERIC (GCF)	SWI9X07Y_02.28.03.03	002.068_003	SWI9X07Y_02.28.06.01	19.02.0	GCF Approved
WP7609 Approved						
WP76xx_Release-13.1.1_GENERIC_GCF.exe	GENERIC (GCF)	SWI9X07Y_02.28.03.03	002.068_003	SWI9X07Y_02.28.06.01	19.02.0	GCF Approved
WP7610 Approved						
WP76xx_Release-13.1.1_ATT.exe	ATT	SWI9X07Y_02.28.03.01	002.071_006	SWI9X07Y_02.28.06.01	19.02.0	AT&T Approved
WP76xx_Release-13.1.1_GENERIC_PTCRB.exe	GENERIC (PTCRB)	SWI9X07Y_02.28.03.01	002.064_003	SWI9X07Y_02.28.06.01	19.02.0	PTCRB Approved
WP76xx_Release-13.1.1_SIERRA_GCF.exe	SIERRA (GCF)	SWI9X07Y_02.28.03.03	001.026_003	SWI9X07Y_02.28.06.01	19.02.0	GCF Approved

Function	Files
Firmware components	9999999_9907152_SWI9X07Y_02.28.03.01_00_GENERIC_002.064_003.spk (PTCRB) 9999999_9907256_SWI9X07Y_02.28.03.01_00_ATT_002.071_006.spk (ATT) 9999999_9908787_SWI9X07Y_02.28.03.03_00_SIERRA_001.026_003.spk (SIERRA) 9999999_9907152_SWI9X07Y_02.28.03.03_00_GENERIC_002.068_003.spk (GCF) linux-SWI9X07Y_02.28.06.01.cwe legato-19.02.0.cwe
Available in https://source.sierrawireless.com.	

Software Changes Description

The second memory source changes are included in Release 13.1.1, built from Release 13.1.

Table 2-1: Software Changes Description for WP76xx Release 13.1.1

ID	Description	Impacted Domain
QT19X07-5444	Add the IDs of these alternate memory sources: New Micron/ESMT/JSC	System
QT19X07-5464	Exclude the legato.cwe from ant-rollback fw download	
QT19X07-5524	Implement the anti-rollback mechanism to prevent from downgrading to the firmwares in which alternate memory sources (New Micron/ESMT/JSC) are not supported	

Known Issues

The following table presents the known issues in this release.

Table 2-2: Known Issues for WP76xx Release 13.1.1

ID	Description	Impacted Domain
QT19X07-3451	On some occasion, modules fail to make an LTE-only data connection using an external Sierra Wireless SIM.	AVMS
QT19X07-3407	Preamble transmission power failed to meet the specification at -30C.	RF
QT19X07-3381	AT!GPSLOC? does not return the last known location if the command is requested in a less than 1 second interval.	GPS
QT19X07-3371	Sometimes I2C control to MCU is lost when reading the ADC2 from MCU and ULPM mode is requested at the same time.	I2C
QT19X07-3367	As the temperature approaches its high critical limit, modules enter LPM when making a voice call.	Thermal
QT19X07-3348	Create a Legato AT command handler and then start the AT server. No response returned when closing the AT server by le_atServer_Close().	Legato
QT19X07-3347	If the GPS simulator set the latitude to 0 and longitude to -90 exactly, modules are unable to find a location fix.	GPS
QT19X07-3308	AT!GPSCLRRASSIST=1,0,0,0,0 can't clear GPS assistance data. FAILCODE = 9 is returned	GPS
QT19X07-3281	The WiFi-LTE coexistence feature does not seem to work and it would impact the performance when using some RF bands.	Wi-Fi
QT19X07-3200	The WiFi-LTE coexistence feature does not seem to work and it would impact the performance when using some RF bands.	SFS
QT19X07-3199	Truncated SecStore writes without the Legato API reporting an error.	SFS
QT19X07-3134	Unable to mount a USB flash memory device onto the module.	Linux
QT19X07-2988	SIM PIN has to be re-entered after being woken up from PSM.	PSM
QT19X07-2950	Without fixing and restoring the PSM/ULPM Fallback mode, the mode is just in ULPM mode.	ULPM
QT19X07-2706	RF sensitivity for products using LTE B1/B4/B7 is degraded when GPS is active.	GPS
QT19X07-2387	With Legato, fails to establish a data session with authentication enabled	Legato

Table 2-2: Known Issues for WP76xx Release 13.1.1

ID	Description	Impacted Domain
QT19X07-2272	Periodic high current draw when testing EDRX/DRX with HSIC enabled	PSM
QT19X07-2195	Unlike the WPx5, the WP76 SNTP client must open a new connection, which is more visible and could have undesirable consequences. Therefore, for WP76, the feature is turned off by default. The user would need to enable it via QMI/Legato, but because it is an AT!CUSTOM feature, it requires a level 2 password.	Linux
QT19X07-2186	With the SINGLEAPNSWITCH feature enabled, Legato cm data connect always fails on LTE with Legato 18.05.1 or older	Legato
QT19X07-2106	Periodic high current spike, every 20s, is disabled when using EDRX and HSIC.	PSM
QT19X07-1928	eth0 address is erased when Wi-Fi chip is inserted after reboot	Driver
QT19X07-1653	At temperature below -20, units in sleep mode may lose LTE network synchronization. A workaround that inhibits sleep mode at low temperature has been placed (QT19X07-2478) to mitigate this problem.	Protocol

>> 3: SWI9X07Y Release 13.2.1

Release 13.2.1 is a point release to Release 13.2 with minor updates of alternate memory drivers for:

- WP7610

Software Release Description

Release Identification

Component	Revision
Modem Firmware	SWI9X07Y_02.28.03.04 000000 jenkins 2019/06/05 10:14:36
Linux Firmware	SWI9X07Y_02.28.05.02 2021-08-11_08:07:04
MCU Firmware	002.011 (embedded as a binary in the Linux image, not distributed as a separate component)
Legato Application Framework	19.02.0_4cb954265427b8c2c668a010ff5be274
Binary Size	61MB (compressed one-click .exe file)
IMEI SV	6
Qualcomm Stack Version	MDM9607.LE.2.0-00161-STD.PROD-1
Linux Kernel Version	Linux version 3.18.131 (oe-user@oe-host) (gcc version 7.3.0 (GCC)) #1 PREEMPT Wed Aug 11 07:56:12 UTC 2021
Supported H/W	WP7610

Software Tools Version

S/W Tools Name	Version
Windows Driver Package	B4836
Windows SDK	None
Skylight	None
Linux Drivers	S2.36N2.57
Linux SDK	SLQS04.00.20

*Available in <https://source.sierrawireless.com>

Released Files

File	Carrier	Modem Firmware	Config	Linux Distribution	Base Legato System	Comment
WP7610 Approved						
WP76xx_Release13 .2.1_ATT.exe	ATT	SWI9X07Y_02.28.03.01	002.071_006	SWI9X07Y_02.28.05.02	19.02.0	AT&T Approved
WP76xx_Release13 .2.1_VERIZON_WP7610.exe	VERIZON	SWI9X07Y_02.28.03.04	002.075_002	SWI9X07Y_02.28.05.02	19.02.0	Verizon Approved
WP76xx_Release13 .2.1_GENERIC_PT CRB.exe	GENERIC (PTCRB)	SWI9X07Y_02.28.03.01	002.064_002	SWI9X07Y_02.28.05.02	19.02.0	PTCRB Approved
WP76xx_Release13 .2.1_SIERRA_GCF.exe	SIERRA (GCF)	SWI9X07Y_02.28.03.03	001.026_002	SWI9X07Y_02.28.05.02	19.02.0	GCF Approved
WP76xx_Release13 .2.1_TELUS.exe	TELUS	SWI9X07Y_02.28.03.01	001.000_002	SWI9X07Y_02.28.05.02	19.02.0	Telus Approved

Function	Files
Firmware components	9999999_9907152_SWI9X07Y_02.28.03.01_00_GENERIC_002.064_002.spk (PTCRB) 9999999_9907256_SWI9X07Y_02.28.03.01_00_ATT_002.071_006.spk (ATT) 9999999_9908787_SWI9X07Y_02.28.03.03_00_SIERRA_001.026_002.spk (SIERRA) 9999999_9907255_SWI9X07Y_02.28.03.04_00_VERIZON_002.075_002.spk (VERIZON - WP7610) 9999999_9909580_SWI9X07Y_02.28.03.01_00_TELUS_001.000_002.spk (TELUS) linux-SWI9X07Y_02.28.05.02.cwe legato-19.02.0.cwe
Available in https://source.sierrawireless.com .	

Software Changes Description

The second memory source changes are included in Release 13.2.1, built from Release 13.1.

Table 3-1: Software Changes Description for WP76xx Release 13.2.1

ID	Description	Impacted Domain
QT19X07-5444	Add the IDs of these alternate memory sources: New Micron/ESMT/JSC	System
QT19X07-5464	Exclude the legato.cwe from ant-rollback fw download	
QT19X07-5524	Implement the anti-rollback mechanism to prevent from downgrading to the firmwares in which alternate memory sources (New Micron/ ESMT/JSC) are not supported	

Known Issues

The following table presents the known issues in this release.

Table 3-2: Known Issues for WP76xx Release 13.2.1

ID	Description	Impacted Domain
QT19X07-3451	On some occasion, modules fail to make an LTE-only data connection using an external Sierra Wireless SIM.	AVMS
QT19X07-3371	Sometimes I2C control to MCU is lost when reading the ADC2 from MCU and ULPM mode is requested at the same time.	I2C
QT19X07-3367	As the temperature approaches its high critical limit, modules enter LPM when making a voice call.	Thermal
QT19X07-3348	Create a Legato AT command handler and then start the AT server. No response returned when closing the AT server by le_atServer_Close().	Legato
QT19X07-3347	If the GPS simulator set the latitude to 0 and longitude to -90 exactly, modules are unable to find a location fix.	GPS
QT19X07-3308	AT!GPSCLRASSIST=1,0,0,0,0 can't clear GPS assistance data. FAILCODE = 9 is returned	GPS
QT19X07-3281	The WiFi-LTE coexistence feature does not seem to work and it would impact the performance when using some RF bands.	Wi-Fi
QT19X07-3200	The WiFi-LTE coexistence feature does not seem to work and it would impact the performance when using some RF bands.	SFS
QT19X07-3199	Truncated SecStore writes without the Legato API reporting an error.	SFS
QT19X07-3134	Unable to mount a USB flash memory device onto the module.	Linux
QT19X07-2988	SIM PIN has to be re-entered after being woken up from PSM.	PSM
QT19X07-2950	Without fixing and restoring the PSM/ULPM Fallback mode, the mode is just in ULPM mode.	ULPM
QT19X07-2706	RF sensitivity for products using LTE B1/B4/B7 is degraded when GPS is active.	GPS
QT19X07-2387	With Legato, fails to establish a data session with authentication enabled	Legato
QT19X07-2272	Periodic high current draw when testing EDRX/DRX with HSIC enabled	PSM

Table 3-2: Known Issues for WP76xx Release 13.2.1

ID	Description	Impacted Domain
QT19X07-2195	Unlike the WPx5, the WP76 SNTP client must open a new connection, which is more visible and could have undesirable consequences. Therefore, for WP76, the feature is turned off by default. The user would need to enable it via QMI/Legato, but because it is an AT!CUSTOM feature, it requires a level 2 password.	Linux
QT19X07-2186	With the SINGLEAPNSWITCH feature enabled, Legato cm data connect always fails on LTE with Legato 18.05.1 or older	Legato
QT19X07-2106	Periodic high current spike, every 20s, is disabled when using EDRX and HSIC.	PSM
QT19X07-1928	eth0 address is erased when Wi-Fi chip is inserted after reboot	Driver
QT19X07-1653	At temperature below -20, units in sleep mode may lose LTE network synchronization. A workaround that inhibits sleep mode at low temperature has been placed (QT19X07-2478) to mitigate this problem.	Protocol

>> 4: SWI9X07Y Release 13.3.1

Release 13.3.1 is a point release to Release 13.3 with minor updates of alternate memory drivers for:

- WP7605
- WP7609

Software Release Description

Release Identification

Component	Revision
Modem Firmware	SWI9X07Y_02.28.03.05 000000 jenkins 2019/07/08 11:04:16
Linux Firmware	SWI9X07Y_02.28.04.01 2021-09-08_15:45:55
MCU Firmware	002.011 (embedded as a binary in the Linux image, not distributed as a separate component)
Legato Application Framework	19.02.0_4cb954265427b8c2c668a010ff5be274
Binary Size	61MB (compressed one-click .exe file)
IMEI SV	6
Qualcomm Stack Version	MDM9607.LE.2.0-00161-STD.PROD-1
Linux Kernel Version	Linux version 3.18.131 (oe-user@oe-host) (gcc version 7.3.0 (GCC)) #1 PREEMPT Wed Sep 8 15:29:33 UTC 2021
Supported H/W	WP7605 WP7609

Software Tools Version

S/W Tools Name	Version
Windows Driver Package	B4836
Windows SDK	None
Skylight	None
Linux Drivers	S2.36N2.57
Linux SDK	SLQS04.00.20

*Available in <https://source.sierrawireless.com>

Released Files

File	Carrier	Modem Firmware	Config	Linux Distribution	Base Legato System	Comment
WP7605 Approved packages						
WP76xx_Release13.3.1_DOCOMO.exe	DOCOMO	SWI9X07Y_02.28.03.05	001.024_001	SWI9X07Y_02.28.04.01	19.02.0	DOCOMO approved
WP76xx_Release13.3.1_SoftBank.exe	SoftBank	SWI9X07Y_02.28.03.05	001.028_001	SWI9X07Y_02.28.04.01	19.02.0	SoftBank approved
WP76xx_Release13.3.1_KDDI.exe	KDDI	SWI9X07Y_02.28.03.05	001.026_002	SWI9X07Y_02.28.04.01	19.02.0	KDDI approved
WP76xx_Release13.3.1_SIERRA_GCF.exe	SIERRA (GCF)	SWI9X07Y_02.28.03.05	001.032_001	SWI9X07Y_02.28.04.01	19.02.0	Sierra Approved
WP7609 Approved packages						
WP76xx_Release13.3.1_GENERIC_GC F.exe	GENERIC (GCF)	SWI9X07Y_02.28.03.05	002.073_001	SWI9X07Y_02.28.04.01	19.02.0	GCF Approved
WP76xx_Release13.3.1_TELSTRA.exe	TELSTRA	SWI9X07Y_02.28.03.05	001.058_001	SWI9X07Y_02.28.04.01	19.02.0	Telstra Approved

Function	Files
Firmware components	9999999_9907152_SWI9X07Y_02.28.03.05_00_GENERIC_002.073_001.spk (GCF) 9999999_9908843_SWI9X07Y_02.28.03.05_00_DOCOMO_001.024_001.spk (DOCOMO) 9999999_9908844_SWI9X07Y_02.28.03.05_00_SOFTBANK_001.028_001.spk (SOFTBANK) 9999999_9908845_SWI9X07Y_02.28.03.05_00_KDDI_001.026_002.spk (KDDI) 9999999_9908043_SWI9X07Y_02.28.03.05_00_TELSTRA_001.058_001.spk (TELSTRA) 9999999_9908787_SWI9X07Y_02.28.03.05_00_SIERRA_001.032_001.spk (SIERRA) linux-SWI9X07Y_02.28.04.01.cwe legato-19.02.0.cwe
Available in https://source.sierrawireless.com .	

Software Changes Description

The second memory source changes are included in Release 13.3.1, built from Release 13.3.

Table 4-1: Software Changes Description for WP76xx Release 13.3.1

ID	Description	Impacted Domain
QT19X07-5444	Add the IDs of these alternate memory sources: New Micron/ESMT/JSC	System
QT19X07-5464	Exclude the legato.cwe from ant-rollback fw download	
QT19X07-5524	Implement the anti-rollback mechanism to prevent from downgrading to the firmwares in which alternate memory sources (New Micron/ESMT/JSC) are not supported	

Known Issues

The following table presents the known issues in this release.

Table 4-2: Known Issues for WP76xx Release 13.3.1

ID	Description	Impacted Domain
QT19X07-3371	Sometimes I2C control to MCU is lost when reading the ADC2 from MCU and ULPM mode is requested at the same time.	I2C
QT19X07-3348	Create a Legato AT command handler and then start the AT server. No response returned when closing the AT server by le_atServer_Close().	Legato
QT19X07-3347	If the GPS simulator set the latitude to 0 and longitude to -90 exactly, modules are unable to find a location fix.	GPS
QT19X07-3308	AT!GPSCLRASSIST=1,0,0,0,0 can't clear GPS assistance data. FAILCODE = 9 is returned	GPS
QT19X07-3281	The WiFi-LTE coexistence feature does not seem to work and it would impact the performance when using some RF bands.	Wi-Fi
QT19X07-3200	The WiFi-LTE coexistence feature does not seem to work and it would impact the performance when using some RF bands.	SFS
QT19X07-3199	Truncated SecStore writes without the Legato API reporting an error.	SFS
QT19X07-3134	Unable to mount a USB flash memory device onto the module.	Linux
QT19X07-2988	SIM PIN has to be re-entered after being woken up from PSM.	PSM
QT19X07-2950	Without fixing and restoring the PSM/ULPM Fallback mode, the mode is just in ULPM mode.	ULPM
QT19X07-2706	RF sensitivity for products using LTE B1/B4/B7 is degraded when GPS is active.	GPS
QT19X07-2387	With Legato, fails to establish a data session with authentication enabled	Legato
QT19X07-2272	Periodic high current draw when testing EDRX/DRX with HSIC enabled	PSM
QT19X07-2186	With the SINGLEAPNSWITCH feature enabled, Legato cm data connect always fails on LTE with Legato 18.05.1 or older	Legato
QT19X07-2106	Periodic high current spike, every 20s, is disabled when using EDRX and HSIC.	PSM
QT19X07-1928	eth0 address is erased when Wi-Fi chip is inserted after reboot	Driver

>> A: Appendix

List of Abbreviations

Abbreviation /Acronym	Definitions
AT	Access Terminal, Attention
CS	Circuit Switched
EDL	Emergency Download
FDT	Firmware Download Tool
GCF	Global Certification Forum
LK	Little Kernel Linux bootloader
MCU	Microcontroller Unit – An onboard MCU enables Ultra Low Power modes of operation
MR	Maintenance Release
PSM	Power Saving Mode
QMI	Qualcomm Messaging Interface
SDP	Software Download Protocol
ULPM	Ultra Low Power Mode

List of References

1. WP76xx - Product Technical Specification
Reference number: 4119652
2. WPx5xx-76xx-77xx AT Command Reference
Reference number: 4118047
3. WP Series - Preparing Your Devices for Deployment
Reference number: 41110380
4. WPX5-76-77 Scalability Guide
Reference number: 41110866
5. WP Series - Secure Boot
Reference number: 41112164