



# S4\_1\_0\_8

## Customer Release Note

Document number	4134070
Rev	R02.00
Date	2013/09/05

## Document History

Rev XX.YY	Date YYYY/MM/DD	Updates	Author
01.00	2013/08/28	Creation	Blues
02.00	2013/09/05	Updated to add cumulative information	Evan

## Table of Contents

<b><u>1</u></b>	<b><u>INTRODUCTION</u></b>	<b>5</b>
1.1	SCOPE OF THIS DOCUMENT	5
1.2	AUDIENCE OF THIS DOCUMENT	5
1.3	NEW FEATURES / ENHANCEMENTS	5
<b><u>2</u></b>	<b><u>ABBREVIATIONS AND DEFINITIONS</u></b>	<b>5</b>
<b><u>3</u></b>	<b><u>RELATED DOCUMENTATION</u></b>	<b>5</b>
<b><u>4</u></b>	<b><u>COMPATIBILITY</u></b>	<b>6</b>
<b><u>5</u></b>	<b><u>SOFTWARE RELEASE DESCRIPTION</u></b>	<b>6</b>
5.1	RELEASE IDENTIFICATION	6
5.2	RELEASED FILES AND DOWNLOAD PROCESSES	6
5.2.1	DOWNLOAD THE ENTIRE NECESSARY UPGRADE FILES	7
5.2.2	SUPPORTED OPERATING SYSTEMS	7
5.2.3	UPGRADE INSTRUCTIONS	7
5.2.4	BINARY FILES	8
5.3	SOFTWARE TOOLS VERSIONS	8
<b><u>6</u></b>	<b><u>SOFTWARE CHANGES DESCRIPTION</u></b>	<b>9</b>
6.1	VALIDATED CORRECTIONS / IMPROVEMENTS	9
<b><u>7</u></b>	<b><u>TROUBLESHOOTING</u></b>	<b>11</b>
7.1	CIPHERING/INTEGRITY	11
7.2	CRASH INVESTIGATION	11
7.2.1	FULL MEMORY DUMP	11
7.2.1.1	Configuring the UE for crash dump capture	11
7.2.1.2	Capturing a crash dump	12
7.2.1.3	Mini Dump	12
7.2.1.4	Error Listing	12
7.2.2	DEBUG TOOLS	12
<b><u>8</u></b>	<b><u>CERTIFICATION DESCRIPTION</u></b>	<b>12</b>
<b><u>9</u></b>	<b><u>RESTRICTIONS AND ADDITIONAL INFORMATION</u></b>	<b>12</b>
9.1	VISTA RECOMMENDATIONS	12
9.1.1	DISABLING GLOBAL SELECTIVE SUSPEND	13

Template #:	4134070	Revision:	R02.00
-------------	---------	-----------	--------

## 1 Introduction

### 1.1 Scope of this document

This document covers issues that affect carriers and end users.

### 1.2 Audience of this document

The audiences include System engineering team, certification team and customers of Sierra Wireless.

### 1.3 New Features / Enhancements

Feature	Description
NA	NA

## 2 Abbreviations and definitions

Abbreviation/Acronym	Definitions
NA	NA

## 3 Related documentation

Ref. #	Doc. #	Document title
NA	NA	NA

## 4 Compatibility

### Hardware compatibility

#### Airprime compatibility list

SL8080T / SL8082T / SL8084T

### Software compatibility

Component	Version
Firmware	S4_1_0_8
Open AT OS	support
Location Library	NA
eCall inbandModem Library	NA
Security Library	NA
Internet Library	NA
Extended AT Application	NA

## 5 Software Release Description

### 5.1 Release identification

Component	Revision
Boot loader	SIERRA_BOOT_S4.1.0.8.cwe
Application	SIERRA_S4.1.0.8.cwe
Date of generation	8/19/2013
Binary Size	SIERRA_BOOT_S4.1.0.8.cwe (527252 bytes) SIERRA_S4.1.0.8.cwe (14548992 bytes)
IMEI SV	11
Qualcomm Stack Version	AMSS 6270 4.2.31(4231003A_Q6270BKPEZL)
USB Host Version	Support USB1.1 and USB2.0

### 5.2 Released Files and Download Processes

Download Option	Files
SIERRA_BOOT_S4.1.0.8.cwe	Boot loader
SIERRA_S4.1.0.8.cwe	AMSS Application
S4_1_0_8bt-S4_1_0_8ap.exe	OneClick to upgrade Boot & AMSS application
S4_1_0_8bt-S4_1_0_8ap.zip	Compressed OneClick

### 5.2.1 Download the entire necessary upgrade files

Download the files and follow any additional instructions from the restricted access SL SharePoint website:

From: <https://swiextranet.sierrawireless.com/Products/SL%20Series/default.aspx>

Please contact your Sierra Wireless representative for access information.

### 5.2.2 Supported Operating Systems

This software and firmware package supports the Sierra Wireless AirPrime SL808x Series on the following Microsoft Operating Systems:

- Windows XP SP3 (Service Pack 3 or higher)
- Windows Vista SP1 (Service Pack 1 or higher)
- Windows 7

### 5.2.3 Upgrade Instructions

Sierra Wireless firmware upgrades are provided in a One-Click tool, which contains the firmware and download tool bundled in a self-extracting executable. Before starting an upgrade, please ensure the following:

- The host computer is connected to an AC power supply, or has at least 30 minutes of battery life remaining
- The device to be upgraded is powered and operating normally
- All applications which communicate with the device, such as Watcher, Hyper-terminal, etc. are closed

Steps:

1. Navigate to the folder in the current release containing the folder named "Firmware" and open it
2. Open the folder named "[S4\\_1\\_0\\_8bt-S4\\_1\\_0\\_8ap.exe](#)" and click on the executable within that folder to start the BinUpdater tool and download the firmware automatically.
3. When BinUpdater tool starts, the following window will appear:



**NOTE:** The upgrade can take up to 10 minutes to complete. Do not remove the power to either the laptop or the card until the One-Click Tool announces that the upgrade has been successful, as shown below.



**NOTE 2:** There can be more than one firmware image bundled with the One Click Tool. If so, then you will be asked if you want to upgrade the device once for each image. If you click Cancel instead of OK, the remainder of the download will be aborted.

**NOTE 3:** When a boot image is released it is usually bundled with the application firmware within the same OneClickTool executable. That OneClickTool will automatically install both the boot and application images for you. If you intend to perform repeated download stability tests, please use the oneclick tools with just the Application image.

#### 5.2.4 Binary Files

If you are using binary CWE files to update your module, your platform must be setup to handle these files. Use the method that you have setup for your platform in order to update the module.

### 5.3 Software Tools Versions

S/W Tools Name	Version	Resource file
BinUpdater	R11.2.1105.0	<a href="\\jasmine2\Projects-1\Engineering\HostSW\15 - External Release Packages\BinUpdater\BinUpdater-R11.2.1105.0">\\jasmine2\Projects-1\Engineering\HostSW\15 - External Release Packages\BinUpdater\BinUpdater-R11.2.1105.0</a>

## 6 Software Changes Description

### 6.1 Validated Corrections / Improvements

ID	Description	Fixed in
CUS67024	[UMTS][SL808x][BZ47046] Docomo IOT FT failure -1.	S4.1.0.8
BZ47104	fix the issue that SL8084T Docomo IOT MTPDP test fail	S4.1.0.8
BZ45986	Fix the issue that at!swicallprog command not functional with CSD call	S4.1.0.8
BZ46556	Fix the issue that when the CSD call is released, double NO CARRIER is displayed in the HyperTerminal.	S4.1.0.8
BZ46610	Fix the issue that Change call state for !SWICALLPROG from incoming state to waiting state on receiving a new call, when there are held call but no active call	S4.1.0.8
BZ46030	Fix the issue that AT port can't input anymore after at+cops=0 without SIM card	S4.1.0.8
BZ 46591	Fix the issue that [BSP][SL808xT][OAT] Impossible to upload the FW using the JTAG	S4.1.0.8
BZ46752	Fix the issue that [SL808XT] command AT!PCOFFEN=1 return OK, but invalid in fact.	S4.1.0.8
BZ46351	Fix the issue that [SL808xT][GpsOne] Factory start shall delete DEE content and start in factory mode	S4.1.0.8
BZ45124	Fix the issue that [SL808X][BSP]:boot_debug_6K_2_0.cmm, mjinload_sierra_debug.cmm, those files are invalid	S4.1.0.8
ANO65483	fix the issue that modules only download apps in 115200 baud rate	S4.1.0.8
CUS66938	fix the issue that playing audio file gets hung after voice call (Hughes Telematics)	S4.1.0.8
CUS66950	Update the SE13 file as GCF request.	S4.1.0.8
CUS66951	fix the issue that TC42.3.1a/b fail.	S4.1.0.8
CUS66793	fixes the issue that missing DTMF tones during high system load (with GPS running).	S4.1.0.8
ANO67012	fixes the issue that Crash dump message found during the Anritsu tests.	S4.1.0.8
CUS67234	fixes the issue that unable to write IMEIs to units with blank IMEIs (Hughes Telematics).	S4.1.0.8
DEV67235	improve Fine Grained Schedule on AMSS side.	S4.1.0.8
ANO67279	to support DOTA function.	S4.1.0.8
CUS67283	revert code changes on BZ39783	S4.1.0.8
ANO67159	[BSP][SL8084T][UART] AT+WHCF command in SL8084T with FW S4.1.0.7	S4.1.0.8
ANO67321	[UMTS][SL808X][TC_6329]The DTMF tone just heard locally lasts for 1 seconds when set "AT+VTD=100"(10S).	S4.1.0.8
CUS67264	[SL808xT][AMSS] Missing !SWICALLPROG notification remote side hangs up call	S4.1.0.8
ANO67301	[SL808XT]+CCWA will return incorrect number when SWICALLPORG enable.	S4.1.0.8
ANO67455	[SL8080T][increase IMEI SVN	S4.1.0.8
NEW67399	SL808xT Feature IMEI programming tool	S4.1.0.8
CUS67175	[UMTS][SL8084T][Telstra][54-55-56-57]Emergency call 000 not possible in PIN or PUK	S4.1.0.8
ANO67439	[BSP][SL8080T] Modem can't enter into download mode when crash happen	S4.1.0.8
CUS67170	[BSP][SL8080T][GPS] - loss of GPS lock when in good GPS signal conditions (Hughes Telematics)	S4.1.0.8
CUS67020	[BSP][SL8080T][GPS] Incorrect location reported with "good" NMEA	S4.1.0.8
ANO67493	[BSP][SL8080T] Vtimer issue	S4.1.0.8



ID	Description	Fixed in
ANO66896	[SL808X][BSP] - AT^HVER return Error,FSN in it	S4.1.0.8
CUS66948	[UMTS][SL8082][BZ47135][GCF] TC57.1.6.1	S4.1.0.8
ANO67534	[BSP][SL808XT] AMSS standalone support	S4.1.0.8
ANO66878	[BSP][SL808XT] Reset was monitored while enabling CUSD indication	S4.1.0.8
DEV66710	Read big size NV with at!nv, modem will crash	S4.1.0.8
ANO67656	When the user back nv great than specific size	S4.1.0.8
DEV67611	Add the TTY profile support	S4.1.0.8
ANO67829	Support FOTA function	S4.1.0.8
DEV67625	reconfigure the GPIO pin for Netgear	S4.1.0.8
ANO67785	AMSS resets Open AT Firmware	S4.1.0.8
CUS67413	Redundant information on 2G neighbor cells when using AT+CCED=0,2 or AT+CCED=0,35 command	S4.1.0.8
ANO67714	removing redundant files	S4.1.0.8
ANO67965/ ANO67966	When the CSD call is released using ATH command, the distant is not warned that the call is over / it is not possible to make successive CSD call	S4.1.0.8
ANO68244	When unplug/plug cable, IMEI is default one for old produced SL808x	S4.1.0.8
CUS66905	Fix the issue where ATT test case GSM-BTR-1-9815 failed	S4.1.0.8
ANO65722	Wrong TON of address for phone number is received	S4.1.0.8
DEV68233	After at!custrst, OAT will be disabled	S4.1.0.8
ANO68179	Modem will always stay at "LOW POWER MODE" when disabled Open AT	S4.1.0.8
ANO66311	Dual PDP not working	S4.1.0.8
ANO66398	Module has not fallback for the special package	S4.1.0.8
DEV68259	update success or failed depending on the order the patches into the update package	S4.1.0.8
ANO68015	[Location][SL808xT] AT port becomes irresponsible when DEE download is requested	S4.1.0.8
CUS68309	[BSP][SL8080T] WP8 to WP9 Upgrade Requires 2 attempts	S4.1.0.8
ANO68431	[BSP][BOOT][SL808xT] special command included into dwl not executed by the bootloader	S4.1.0.8
DEV68438	[BSP][FS][SL808xT][OAT-QCT]OAT File System working efficiency need to be improved	S4.1.0.8
ANO68260	[SL808x] [Supplementary service] No unsolicited response after SS reject the interrogation	S4.1.0.8
ANO66595	[CSD][SL808x] ATH doesn't work with outgoing CSD calls	S4.1.0.8
ANO67546	[UMTS][SL808xT] The MO Emergency call will auto release from callbox after PUK1 unlocked.	S4.1.0.8
ANO68502	[CSD][UMTS][SL808xT]MO CSD call with ATH on AT port, without !SWICALLPROG indication.	S4.1.0.8
ANO68543	[BSP][SL808X] Correct the band support	S4.1.0.8
DEV68560	[BSP][SL808X] Add the calibrated data to the audio profile	S4.1.0.8
CUS68588	[BSP][SL808X][GPIO] GPIO pin sleep configuration for Netgear	S4.1.0.8
ANO68459	[IMEI QCT Reprogramming Tool]: IMEI_APPLI.dwl cannot be used for Imei Reprogramming	S4.1.0.8
ANO66155	[UMTS][SL808x] Cannot make Emergency call without SIM or cpin lock	S4.1.0.8
ANO68715	[SL808xT] [MWI]: Unable to display user prompt when received MWI message	S4.1.0.8

Template #:	4134070	Revision:	R02.00
-------------	---------	-----------	--------



ID	Description	Fixed in
ANO68913	[UMTS][SL808X][TTY] Test case 9.2 failed	S4.1.0.8
ANO68952	Crash will happen when doing PRI	S4.1.0.8
	Fix the issue that crash when run "AT+CSMP=132".	S4.1.0.7
	Support OPEN-AT Application	S4.1.0.7
	Add flow control for VSIO	S4.1.0.7
	Enhance PCM vocoder performance	S4.1.0.7
	Fix the issue that poor DTMF decoding performance	S4.1.0.7

## 7 Troubleshooting

The following sections describe troubleshooting information when using the AirPrime when using in a live network and when using with a test box.

### 7.1 Cipherring/Integrity

If you're not attaching, check your cipherring settings. The UE needs to use the same settings as the network/test set. Generally, live networks will have cipherring/integrity enabled. Test sets may have them enabled or disabled, but it is common for test sets to leave it disabled unless explicitly testing that feature.

The AT command is noted below:

AT Command	Description
AT!GCIPHER=X	Set the card to support integrity and cipherring with the following settings: X = 0, Cipherring OFF, Integrity OFF X = 1, Cipherring ON, Integrity OFF X = 2, Cipherring ON, Integrity ON
AT!GCIPHER?	Query the GCIPHER settings.

### 7.2 Crash Investigation

[R-1] Should the UE crash there are a number of different means to provide useful feedback to Sierra Wireless for resolution of the issue.

#### 7.2.1 Full memory dump

[R-2] This is the preferred process because it captures the most crash information.

##### 7.2.1.1 Configuring the UE for crash dump capture

This must be done to enable or disable the crash capture feature on the UE. This configuration is stored in NV so it is persistent across power cycles / power removal. The UE must be reset after changing the setting before the changes take effect.

To enable crash dump capture  
AT!EROPTION=0

Template #:	4134070	Revision:	R02.00
-------------	---------	-----------	--------

To enable UE reset upon a crash (default behaviour)  
 AT!EROPTION=1

#### 7.2.1.2 Capturing a crash dump

1. Wait for / cause a crash to occur
2. Close connection manager software (to release the com port)
3. Run SwiMemDebug
4. Click Start to initiate crash dump collection. If this fails, the application likely cannot open the com port (see step 2)
5. Once 100% is reached, the crash dump collection is complete. Click Reset to reset the modem (optional), and Exit to exit the program
6. Crash files will be in the same location as SwiMemDebug. Zip up the crash files and label the zip file with a unique name (date/timestamp is suggested) and send the zip to Sierra Wireless for analysis

#### 7.2.1.3 Mini Dump

If a crash occurs, the summary of why the crash occurs is saved in memory. The command following command will display the crash summary:  
 AT!GCDUMP

Note that this crash summary is lost once power is removed from the device (or manually cleared via AT!GCCLR).

#### 7.2.1.4 Error Listing

The AT!ERR command will display “points of interest” that have occurred in the UE. These are not crashes, but are often used by developers to highlight areas they wish to examine.

### 7.2.2 Debug Tools

Sierra Wireless devices provide support for trace tools such as QXDM or the Sierra Wireless log-gathering tool. Please contact your Sierra Wireless representative for the logger tool and the installation instructions

## 8 Certification Description

This version has passed the PTCRB certification

## 9 Restrictions and Additional Information

Issue ID	Description (What/When)	Impacted Domain	Impacted Sub-Domain
None	None	None	None

### 9.1 Vista Recommendations

For optimum performance and stability in Microsoft Vista, it is recommended that USB Selective Suspend be disabled. In order to disable Selective Suspend properly, follow both procedures (9.1 and 9.2) below:

Template #:	4134070	Revision:	R02.00
-------------	---------	-----------	--------

### 9.1.1 Disabling Global Selective Suspend

The following procedure will disable the global selective suspend setting in Microsoft Vista.

1. Open the Control Panel
2. Select the Power Options applet
3. For whichever item is selected as the current Power Mode (ie: Maximum Battery Life), select Change plan settings
4. Select Change advanced power settings
5. Expand USB Settings
6. Expand USB Selective Suspend settings
7. Change the settings for Plugged in to DISABLED
8. Change the settings for On Battery to DISABLED
9. Close the Power Options applet

### 9.1.2 Disabling Device Specific Selective Suspend for Generic Sierra Wireless Drivers

The following procedure will disable the device specific selective suspend setting in Microsoft Vista when using a device configured with the generic Sierra Wireless drivers:

1. Open a notepad
2. Type the following text into notepad

```
[HKEY_LOCAL_MACHINE\SYSTEM\CurrentControlSet\Services\SWUMX3C\Parameters]
"IdleDetect"=dword:00000000
"UsbSelSus"=dword:00000000
[HKEY_LOCAL_MACHINE\SYSTEM\CurrentControlSet\Services\SWUMX3E\Parameters]
"IdleDetect"=dword:00000000
"UsbSelSus"=dword:00000000
[HKEY_LOCAL_MACHINE\SYSTEM\CurrentControlSet\Services\SWUMXA3\Parameters]
"IdleDetect"=dword:00000000
"UsbSelSus"=dword:00000000
```

3. Save the text file you just created with the filename disableSelSus.reg to the Desktop
4. Exit Notepad
5. Double-click the file you just created (disableSelSus.reg )
6. When prompted by Vista to allow this information to be added to the registry, select Yes.
7. Select OK
8. Reboot the PC