

# **General Equipment Safety Bulletin**

**Technical Support Department** 

#### Bulletin 010/2013

Subject: Failure – Hoist Rope Roller Bracket

Affected Product: 8750 Dragline located at Lake Lindsay

Serial Number: 141276 (Caterpillar Serial no. JKZ41276)

**Risks Identified:** Hoist Rope Roller can fall into the machinery house

\_\_\_\_\_

## **Problem Overview:**

Hastings Deering has become aware of a failure of the mounting brackets for the hoist rope rollers on the machinery house roof. This resulted in the roller falling into the machinery house presenting a severe falling object safety risk.

To fix this problem, the manufacturer has revised the mounting bracket design. The original bracket, (Drawing no.S051907, part no. PRI 20122053015) has been superseded by the part number 4147231 welded bracket. The updated parts need to be fitted to the above listed machine

# **Corrective Actions Implemented by Hastings Deering:**

Hastings Deering are requesting the rework outlined in this bulletin be performed immediately.

## **Rework Procedure:**

Refer to the original machine specific GA drawing/Item No. as noted below for additional information not contained in this bulletin.

Identification number	House Roof	Tri-Structure
141276 (JKZ41276)	S058245/Item 8	S058701/Item 4
Location: Lake Lindsay		

## Approximate weight information:

Welded Bracket:168 kg eachRoller Assembly Short:53.43" 168 kg eachRoller Assembly Long:83.43" 377 kg each

ESB010/2013

Issue date: 06 March 2013



# **General Equipment Safety Bulletin**

**Technical Support Department** 

#### **Suggested Rework Sequence:**

- 1. Perform individual and job specific risk and hazard analysis.
- 2. Utilize appropriate lifting devices and support one end of the roller.
- 3. Loosen mounting bolts for the roller and bracket at both ends.
- 4. Raise the roller slightly to take the weight off the bracket
- 5. Remove bolts for the roller and bracket.
- 6. Remove the bracket.
- 7. Install the new bracket and bolt into location
- 8. Loosely bolt roller to bracket. Remove lifting device and position on opposite end.
- 9. Repeat above steps 4 7.
- 10.Tighten all mounting bolts for the roller and bracket per the General assembly drawing.

#### Parts Required:

Qty	Part Number	SAP Part Number	Description
8	4147231	4147231	Welded Bracket
8	1418537	1418537	Tapped Bar
	(S051900)		
32	1232479	1232479	Screw Hex 1x4.5 UNC Gr 8
	(03301441)		
48	0963193	963193	Washer Hardened Flat 1"
	(03952150)		
4	1232486	1232486	Screw Hex 1x5.50"
	(03301582)		UNC Gr 8
4	1009492	1009492	Nut Hex 1" Full UNC
	(02716054)		
8	1427577	1427577	Bar 2.00 x 2.00
	(S078186)		
4	1232491	1232491	Screw Hex 1x7 UNC
	(03301775)		Gr 8
4	1231697	1231697	Nut Flexloc 1.00
	(02786552)		

## **Contact Details:**

Please contact the Service Department at the Hastings Deering Excavation and Underground Coal Support division, if you require assistance.

This bulletin is to inform you of the recommendations of the supplier in respect of issues dealt with in the bulletin and should not be used as specific advice in respect of any particular events. Advice from a qualified repairer should be sought in respect of any particular events and Hastings Deering (Australia) Ltd accepts no responsibility for any loss or damage occasioned by a party using this general bulletin.