

General Equipment Safety Bulletin

Technical Support Department

Bulletin 008/2013

Subject: Failure of Hoist Rope Roller Bracket

Affected Product: 8750 Dragline located at Ensham

Serial Number: 141202 (Caterpillar Serial no.JKZ41202)

Risk Identified: Hoist Rope Roller can fall into the machinery house

Problem Overview:

Hastings Deering has become aware of a failure of the mounting brackets for the hoist rope rollers on the machinery house roof. This resulted in the roller falling into the machinery house presenting a severe falling object safety risk.

To fix this problem, the manufacturer has revised the mounting bracket design. The original bracket, drawing number S051907 / part number PRI 20122053015, has been superseded by the 4147231 Welded Bracket. The updated parts need to be installed on the above listed machine

Corrective Actions Required:

Hastings Deering is requesting the rework outlined in this bulletin be performed immediately.

Rework Procedure:

Refer to the original machine specific GA drawing / Item No. as noted below for additional information not contained in this bulletin.

Identification number	House Roof	Tri-Structure
141202 (JKZ41202)	N/A	E023340/Item 7
Location: Ensham		

Approximate weight information:

Welded Bracket: 168 kg each Roller Assembly Short (53.43"): 168 kg each Roller Assembly Long (83.43"): 377 kg each



General Equipment Safety Bulletin

Technical Support Department

Suggested rework sequence:

- 1. Perform individual and job specific risk and hazard analysis.
- 2. Utilise appropriate lifting devices and support one end of the roller.
- 3. Loosen mounting bolts for the roller and bracket at both ends.
- 4. Raise the roller slightly to take the weight off the bracket
- 5. Remove bolts for the roller and bracket.
- 6. Remove the bracket.
- 7. Install the new bracket and bolt into location
- 8. Loosely bolt roller to bracket. Remove lifting device and position on opposite end.
- 9. Repeat above steps 4 7.
- 10. Tighten all mounting bolts for the roller and bracket per the General assembly drawing.

Parts Required:

Qty	Part Number	SAP Part Number	Description
4	4147231	4147231	Welded Bracket
8	1201454	1201454	Tapped Bar
	(MP357099)		
16	1232475	1232475	Screw Hex 1x4.00" UNC
	(03301280)		
24	0963193	963193	Washer Hardened Flat 1"
	(03952150)		
4	1053841	1053841	Screw Hex 1x5.50" UNC
	(03301580)		
4	1047785	1047785	Nut Hex 1" Full UNC
	(02716050)		

Contact Details:

Please contact your Service Department at the Hastings Deering Excavation and Underground Coal Support (EUCS) Division.

This bulletin is to inform you of the recommendations of the supplier in respect of issues dealt with in the bulletin and should not be used as specific advice in respect of any particular events. Advice from a qualified repairer should be sought in respect of any particular events and Hastings Deering (Australia) Ltd accepts no responsibility for any loss or damage occasioned by a party using this general bulletin.