ANORA

Anora Minimum Requirements for the use of Personal Protective Equipment (PPE)

Introduction	The purpose of this document is to determine Anora PPE that should be used
Introduction	
	in every production or logistics site.
	AMR aim is to ensure proper selection, use, and care of PPE through
	workplace hazard assessments and appropriate employee training.
	A workplace assessment is required to determine the potential hazards
	and select the appropriate PPE for adequate protection.
	Employees must receive training which includes the proper PPE for
	their job, when this PPE must be worn, how to wear, adjust, maintain
	and the limitations of the PPE. The training must be documented.
	PPE is to be considered as the last choice of defence. PPE devices alone
	should not be relied on to provide protection against hazards, but
	should be used in conjunction with guards, engineering controls, and
	sound manufacturing practices.
	NOTE: PPE must meet local standard/certification e.g. GMP and
	hygiene requirements.

Responsibility	It is the responsibility of the department managers to ensure that correct PPE is worn within the department and the training in the use of PPE is conducted and documented. It is also the department managers' responsibility to provide the required PPE. In order to ensure that correct PPE is worn, hazard assessments need to be conducted to identify specific PPE for specific tasks. It is the responsibility of the employees to wear the PPE and immediately inform the supervisor or manager if PPE is damaged or not
	effective.
	The priority should be the elimination and control of hazards by technical and organizational improvements.

Training	The training in the use of Personal Protective Equipment (PPE) must
Requirements	include:
-	• Proper use
	Inspection requirements
	• Storage requirements
	• Cleaning requirements



• Limitations of specific PPE
All new employees must be trained before starting work.
Frequency of PPE training must be at least annually (once per year).
Training will be arranged in local language by e-training.

Warehouse	Type of PPE	Comments
and	Safety	All persons working in warehouse and production
production areas	Shoes	areas must wear Altia approved safety, closed shoes (EN ISO 20345:2011 Class I, S3).
	Clothes	All persons working in warehouse and production areas must wear Altia approved work clothes. Fleece clothes are not accepted.
	Safety	Safety glasses must be worn at all times in
	Glasses	production and bottling (EN166, class 1F), as well as in
		areas where the work place hazard assessments
		have revealed the need for eye protection safety
		glasses must be worn.
		Normal eye glasses cannot replace safety glasses.
		In cases where the hazard assessment shows that
		safety glasses are not sufficient – full eye goggles
		(EN 166) must be worn - a clear sign indication or
		instruction must be in place.
	Hearing	In areas where the work place hazard assessments
	Protection	have revealed the need for hearing protection (over
		80 db) - hearing protection (CE EN352-1, CE EN352-2)
		must be worn at all times - a clear sign indication or
		instruction must be in place.
	Head	All units that have both warehouse and production
	Protection	facilities the employees must wear Anora approved
		hats. In areas where there is a hygiene risk (medium
		risk area) the hat must include a hair net. In areas
		where the work place hazard assessments have
		revealed the need for head protection, a hard hat or
		helmet must be worn- these must be worn at all
		times - a clear sign indication or instruction must be
		in place.

ANORA

	Truck drivers can enter in limited, marked areas in
	logistics without a hat.
Respirators	All persons must use respirators approved for the
	specific substance for protection from the (chemical,
	dust, etc.) substances where the work place hazard
	assessments have revealed the need for respirators.
	These must be worn at all times - a clear sign
	indication or instruction must be in place
Safety Belt	Safety belt must be worn when driving forklifts. New
	forklifts must always include seat belts.
	NOTE: This does not apply to stand-up forklifts.
Hand	Safety gloves must be worn at all times when
Protection	handling glass bottles and in areas where the work
	place hazard assessments
	have revealed the need for hand protection -
	appropriate gloves must be worn as necessary - a
	clear
	sign indication or instruction must be in place.
Face Protection	In areas where the work place hazard assessments have revealed the need for face protection – appropriate face protection, such as face shield, must be worn as necessary – a clear sign indication or instruction must be in place.
Body Protection	In areas where the work place hazard assessments have revealed the need for body protection – appropriate clothing and/or gear, such as chemical resistant apron, must be worn as necessary – a clear sign indication or instruction must be in place.

Laboratories	Type of PPE	Comments
	Eye protection	In laboratories approved eye protection (EN166, class
		1F) must be worn at all times excluding sensory
		evaluation, data saving or microbiological result
		counting.
		Working with hazardous chemicals chemical eye
		glasses must be worn.
		- a clear sign indication or instruction must be in
		place. In cases where the hazard assessment shows
		that safety glasses are not sufficient – full eye
		goggles (EN 166) must be worn.

ANORA

Protectiv	In areas where the work place hazard assessments
gloves	have revealed the need for appropriate protective
	gloves – these must be worn at all times – clear sign
	indication or instruction must be in place.
Clothes	All Laboratory personnel must wear Altia approved
	work clothes when working in the laboratory.
	Clothes must cover arms and legs and fleece clothes
	are not accepted.
Safety	All operators working in laboratory
shoes	areas must wear Altia approved safety, closed shoes
	(EN ISO 20345:2011 Class I, S3).
Face	In areas where the work place hazard assessments
Protectio	have revealed the need for face protection, such as
	face shields - these must be worn at all times - clea
	sign indication or instruction must be in place.

Employees	The Anora employees must follow customer or supplier safety instructions.
1 v	
visiting	Anora employees must contact the customer or supplier site
customers or	prior to the visit to ask for the required PPE at their site.
supplier	If the customer or supplier site requires PPE but does not provide it to visitors,
••	Anora employees shall contact their Supervisor or local EHS Responsible for
	help in obtaining the required PPE.

Visitors,	Every Anora site must have written guidelines in place for
guests and	needed Personal Protective Equipment for Visitors, Guests and External
external	Contractors.
contractors	

Revision This is a new document.	
---	--