



End of Sale Announcement: LS300

OVERVIEW

DATE ISSUED:	APR 1, 2019
ISSUED BY:	Sierra Wireless Enterprise Solutions Product Management
PRODUCTS AFFECTED:	LS300 Series Gateways
ORDER CODES AFFECTED:	LS300 Gateway - ROW variant
FOR DISTRIBUTION TO:	General Distribution
SUMMARY:	<p>Sierra Wireless announces the last time buy and last time ship date for LS300 Series Gateways (ROW variant). This notice contains all relevant milestones and dates for the affected products.</p> <p>The AirLink® RV50X and LX40 are available as a functional replacement for LS300. www.sierrawireless.com/rv50x www.sierrawireless.com/lx40</p>

PRODUCTION MILESTONES

AFFECTED MODELS:	LS300 (ROW variant)
LAST TIME BUY:	30-SEP-2019 The product cannot be ordered from Sierra Wireless after this date.
LAST TIME SHIP:	30-DEC-2019 The last possible ship date that can be requested from Sierra Wireless.
REASON:	Component obsolescence

PRODUCT SUPPORT AND MAINTENANCE

ACTIVE SOFTWARE MAINTENANCE PHASE:	FROM 1-APR-2019 TO 31-MAR-2020 During this phase, device software will be actively maintained. Software releases will contain bug fixes and security patches only, no new features will be deployed. Following Active Software Maintenance the products move to Critical Software Maintenance (see below).
CRITICAL SOFTWARE MAINTENANCE PHASE:	FROM 1-APR-2020 TO 31-DEC-2021 During this phase, new device software will be released if a Critical software issue or security vulnerability is discovered.



	<p>A software issue is deemed to be Critical if it causes the Sierra Wireless product or service to become systemically unavailable or unresponsive, and there is no available resolution or workaround.</p> <p>A security vulnerability is deemed to be Critical if it scores 9 or 10 on the Common Vulnerability Scoring System Version 3.0 (CVSSv3) as determined by Sierra Wireless.</p>
END OF SOFTWARE MAINTENANCE:	31-DEC-2021 No new device software will be released after this date.

CONTACT

SALES:	www.sierrawireless.com/sales 1-877-687-7795
CUSTOMER SUPPORT:	www.sierrawireless.com/support

REVISION HISTORY

APR 1, 2019	Rev1: Initial announcement
--------------------	----------------------------

AFFECTED PART NUMBERS

PART No.	MODEL DESCRIPTION	SUGGESTED REPLACEMENT	PART No.
1101429	LS300 (HSPA+, ROW, AC)	RV50X (LTE, NA & EMEA, DC)	1103052
1101492	LS300 (HSPA+, ROW, DC)	RV50X (LTE, APAC, DC)	1103045
		LX40 (LTE, EMEA, DC)	1104181