



# GNX G604.09.02kX Release Notes

## OVERVIEW

<b>DATE ISSUED:</b>	November 30, 2020
<b>ISSUED BY:</b>	Sierra Wireless GNX Product Management
<b>PRODUCTS AFFECTED:</b>	All GNX-6 LTE <sup>(Note 3)</sup> & LTEM <sup>(Note 1,2)</sup> devices All GNX-5P LTE <sup>(Note 3)</sup> & LTEM <sup>(Note 1,2)</sup> devices
<b>FOR DISTRIBUTION TO:</b>	All GNX Customers
<b>SUMMARY:</b>	<p>The major features of this release are:</p> <ol style="list-style-type: none"><li>1. Additional modem support for LARA-R202 and HL7800-M modules</li><li>2. Adds "Itemobile.apn" to the APN hunt list for Rogers</li><li>3. Fix for GNX not properly detecting J1939 zero DTC in G604_08_09kX and later</li><li>4. Fix for handle of END_ROM_ADDR section, includes GNX-6 Companion PRI</li><li>5. Improvement for GNX reporting momentary invalid ECM odometer value close to ignition on/off</li><li>6. Creates a label to indicate if the executing firmware is an official release or a pre-release</li><li>7. Fix for GNX-5P incorrectly reporting 4 relay output</li><li>8. Fix for Fleet Complete APN name in Mexico, make APN check case-agnostic</li><li>9. Fix for PVTQ points removed incorrectly</li><li>10. Fix for false SIM removal event on device reset</li><li>11. Fix for unintended Relay 2 output On</li></ol>

## PRODUCT SUPPORT

<b>WHEN IS THIS UPDATE AVAILABLE:</b>	<ol style="list-style-type: none"><li>1. New GNX-5P/6 LTEM devices will be pre-installed with this firmware from the factory</li><li>2. We recommend that existing GNX-5P/6 LTEM devices be upgraded to this firmware</li><li>3. We do not recommend upgraded existing GNX-5P/6 LTE devices to this version of firmware unless directed by Sierra Wireless. Call for details.</li></ol>
---------------------------------------	---



## CONTACT

---

SUPPORT:	<a href="mailto:support@sierrawireless.com">support@sierrawireless.com</a>
----------	--

## REVISION HISTORY

---

30-NOV-2020	Initial Release
-------------	-----------------