



Restricted Availability Announcement: MP70 Wi-Fi

OVERVIEW

DATE ISSUED:	Nov 15, 2021
ISSUED BY:	Sierra Wireless Enterprise Solutions Product Management
PRODUCTS AFFECTED:	AirLink® MP70 Wi-Fi Routers
FOR DISTRIBUTION TO:	General Distribution
SUMMARY:	<p>Sierra Wireless advises that the AirLink® MP70 Wi-Fi variants are entering a restricted availability phase. Please note that MP70 Non-Wi-Fi variants <i>remain in full production</i>.</p> <p>With the launch of the new AirLink XR80 router, we recommend customers migrate to the XR80. During the restricted availability phase:</p> <ol style="list-style-type: none">1) Orders for MP70 Wi-Fi will be accepted subject to pre-approval by Sierra Wireless.2) Please contact your Regional Sales Manager or Channel Business Manager. <p>Recommended Action</p> <p>Sierra Wireless recommends customers migrate to the AirLink XR80.</p> <ol style="list-style-type: none">1) XR80 is the recommended alternate product to MP70 Wi-Fi.2) The XR platform offers significant benefits in performance, availability and longevity.3) XR80 offers both 5G and 4G LTE Cat-20 variants.4) XR80 is available with certification on major carriers complete or already in progress. <p>The XR80 is available with AirLink Complete, which includes ALMS, 24/7 Support and a unique Out of Band Management feature via LPWA.</p> <p>The AirLink RV55 is a suitable alternative for MP70 Wi-Fi customers using one ethernet interface.</p>

PRODUCTION MILESTONES

AFFECTED MODELS:	MP70 Wi-Fi variants
RESTRICTED AVAILABILITY DATE:	15-NOV-2021 After this date, orders will only be accepted with prior approval.
REASON:	Introduction of the XR Series Routers and supply constraints restrict availability of MP70 Wi-Fi.

OTHER MODELS:	MP70 <i>Base</i> (Non- <i>Wi-Fi</i> variants)
STATUS:	This notice does not apply to MP70 Base models. These variants are available as normal.



PRODUCT SUPPORT AND MAINTENANCE

ACTIVE SOFTWARE MAINTENANCE PHASE:	During the restricted availability phase, device software will be actively maintained. Software releases will contain bug fixes and security patches only; no new features will be deployed.
---	--

CONTACT

SALES:	www.sierrawireless.com/sales 1-877-687-7795
CUSTOMER SUPPORT:	www.sierrawireless.com/support

REVISION HISTORY

NOV 15, 2021	Rev1: Initial announcement
---------------------	----------------------------

AFFECTED PART NUMBERS

PART No.	MODEL DESCRIPTION	SUGGESTED ALTERNATIVE	PART No.
1104073	MP70 LTE-A Pro, NA, Wi-Fi	XR80 5G, NA, Wi-Fi XR80 LTE CAT-20, NA, Wi-Fi RV55 LTE-A Pro, NA, Wi-Fi	1104789 1104879 1104302
1104074	MP70 LTE-A Pro, Global, Wi-Fi	XR80 5G, Global, Wi-Fi XR80 LTE CAT-20, Global, Wi-Fi RV55 LTE-A Pro, Global, Wi-Fi	1104787 1104878 1104331
	The products below are subject to this notice and the previously issued End of Sale Notice		
1102743	MP70, NA & EMEA, Wi-Fi (North American Customers)	XR80 5G, NA, Wi-Fi XR80 LTE CAT-20, NA, Wi-Fi RV55 LTE-A Pro, NA, Wi-Fi	1104789 1104879 1104302
1102743	MP70, NA & EMEA, Wi-Fi (EMEA Customers)	XR80 5G, Global, Wi-Fi XR80 LTE CAT-20, Global, Wi-Fi RV55 LTE-A Pro, Global, Wi-Fi	1104787 1104878 1104331
1102745	MP70, APAC, Wi-Fi		