



## »» | ALEOS 4.6.1 Release Notes

ALEOS 4.6.1 is for AirLink MP70 gateways. It is not compatible with AirLink LS300, AirLink RV50, AirLink GX Series, or AirLink ES Series gateways.

### New Features

#### Radio Modules

Approved radio module firmware for Telstra  
SWI9X30C\_02.14.03.00

Approved radio module firmware for Sprint  
SWI9X30C\_02.14.03.02

#### WAN/Cellular

Updated the handling of network reject codes for non-LANES Telstra devices

#### Services

Added ability to enable server-initiated MSCI when using LWM2M for communication with AirLink Management Service (ALMS). Note that MSCI must be enabled in order for ACEview to work.

### Bug Fixes

#### AirLink Management Service

Resolved an issue in AirLink Management Service (ALMS) where the template was not being applied when the Reboot option was selected on the Apply Template screen.

#### WAN/Cellular

Resolved an issue where Apple computers running OS X sometimes experienced loss of Wi-Fi traffic while connected to an AirLink MP70 configured as an Access Point (when using AES encryption).

Resolved an issue where automatic SIM switching was not working properly when service loss timeout was configured.

Resolved a Wi-Fi issue related to Wakeup From Sleep mode on Apple computers running OS X El Capitan 10.11.4. When connected to the MP70 via Wi-Fi, the Wi-Fi connection would sometimes fail or there would be no data on the connection. This is no longer true.

#### Services

Resolved an issue where ALMS Status Report variables differed depending on the ALMS protocol being used (LWM2M or MSCI).