



# Sierra Wireless Technical Bulletin: MGOS 4.1.1

Date of Issue: Nov 27th 2017

## Introduction

Sierra Wireless has identified an issue in the MGOS 4.1.1 firmware release for the MG90, where the second Wi-Fi radio may sometimes not be available on boot. MGOS 4.1.2 firmware will be released to address this issue, in the interim MGOS 4.1.1 firmware has been removed from the support site 'The Source' and hosted AMMs.

In addition to the fix for this issue, MGOS 4.1.2 will also include the same fixes previously offered in MGOS 4.1.1, including the fix for the Wi-Fi Key Reinstallation Attacks (KRACK) vulnerability.

MGOS 4.1.2 will be released in December 2017.

## Products covered by this bulletin

- MG90

## Recommended Actions

Sierra Wireless advises customers to not deploy MGOS 4.1.1, and instead upgrade to MGOS 4.1.2 when it becomes available.

Customers who have already installed MGOS 4.1.1, and wish to downgrade to MGOS 4.1, are encouraged to contact Sierra Wireless Technical Support.

## Further Information

Please contact your Sierra Wireless Sales Representative or your Authorized Reseller for more information.