



Customer Release Note

Android Nougat 7.1.5.0 ARM 64 RIL



SIERRA
WIRELESS®

41111582
1.3
September 29, 2017

Important Notice

Due to the nature of wireless communications, transmission and reception of data can never be guaranteed. Data may be delayed, corrupted (i.e., have errors) or be totally lost. Although significant delays or losses of data are rare when wireless devices such as the Sierra Wireless modem are used in a normal manner with a well-constructed network, the Sierra Wireless modem should not be used in situations where failure to transmit or receive data could result in damage of any kind to the user or any other party, including but not limited to personal injury, death, or loss of property. Sierra Wireless accepts no responsibility for damages of any kind resulting from delays or errors in data transmitted or received using the Sierra Wireless modem, or for failure of the Sierra Wireless modem to transmit or receive such data.

Safety and Hazards

Do not operate the Sierra Wireless modem in areas where cellular modems are not advised without proper device certifications. These areas include environments where cellular radio can interfere such as explosive atmospheres, medical equipment, or any other equipment which may be susceptible to any form of radio interference. The Sierra Wireless modem can transmit signals that could interfere with this equipment. Do not operate the Sierra Wireless modem in any aircraft, whether the aircraft is on the ground or in flight. In aircraft, the Sierra Wireless modem **MUST BE POWERED OFF**. When operating, the Sierra Wireless modem can transmit signals that could interfere with various onboard systems.

Note: Some airlines may permit the use of cellular phones while the aircraft is on the ground and the door is open. Sierra Wireless modems may be used at this time.

The driver or operator of any vehicle should not operate the Sierra Wireless modem while in control of a vehicle. Doing so will detract from the driver or operator's control and operation of that vehicle. In some states and provinces, operating such communications devices while in control of a vehicle is an offence.

Limitations of Liability

This manual is provided "as is". Sierra Wireless makes no warranties of any kind, either expressed or implied, including any implied warranties of merchantability, fitness for a particular purpose, or noninfringement. The recipient of the manual shall endorse all risks arising from its use.

The information in this manual is subject to change without notice and does not represent a commitment on the part of Sierra Wireless. SIERRA WIRELESS AND ITS AFFILIATES SPECIFICALLY DISCLAIM LIABILITY FOR ANY AND ALL DIRECT, INDIRECT, SPECIAL, GENERAL, INCIDENTAL, CONSEQUENTIAL, PUNITIVE OR EXEMPLARY DAMAGES INCLUDING, BUT NOT LIMITED TO, LOSS OF PROFITS OR REVENUE OR ANTICIPATED PROFITS OR REVENUE ARISING OUT OF THE USE OR INABILITY TO USE ANY SIERRA WIRELESS PRODUCT, EVEN IF SIERRA WIRELESS AND/OR ITS AFFILIATES HAS BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES OR THEY ARE FORESEEABLE OR FOR CLAIMS BY ANY THIRD PARTY.

Notwithstanding the foregoing, in no event shall Sierra Wireless and/or its affiliates aggregate liability arising under or in connection with the Sierra Wireless product, regardless of the number of events, occurrences, or claims giving rise to liability, be in excess of the price paid by the purchaser for the Sierra Wireless product.

Customer understands that Sierra Wireless is not providing cellular or GPS (including A-GPS) services. These services are provided by a third party and should be purchased directly by the Customer.

SPECIFIC DISCLAIMERS OF LIABILITY: CUSTOMER RECOGNIZES AND ACKNOWLEDGES SIERRA WIRELESS IS NOT RESPONSIBLE FOR AND SHALL NOT BE HELD LIABLE FOR ANY DEFECT OR DEFICIENCY OF ANY KIND OF CELLULAR OR GPS (INCLUDING A-GPS) SERVICES.

Patents

This product may contain technology developed by or for Sierra Wireless Inc.

This product includes technology licensed from QUALCOMM®.

This product is manufactured or sold by Sierra Wireless Inc. or its affiliates under one or more patents licensed from InterDigital Group and MMP Portfolio Licensing.

Copyright

© 2017 Sierra Wireless. All rights reserved.

Trademarks

Sierra Wireless®, AirPrime®, AirLink®, AirVantage®, WISMO®, ALEOS® and the Sierra Wireless and Open AT logos are registered trademarks of Sierra Wireless, Inc. or one of its subsidiaries.

Watcher® is a registered trademark of NETGEAR, Inc., used under license.

Windows® and Windows Vista® are registered trademarks of Microsoft Corporation.

Macintosh® and Mac OS X® are registered trademarks of Apple Inc., registered in the U.S. and other countries.

QUALCOMM® is a registered trademark of QUALCOMM Incorporated. Used under license.

Other trademarks are the property of their respective owners.

Contact Information

Sales Desk:	Phone:	1-604-232-1488
	Hours:	8:00 AM to 5:00 PM Pacific Time
	Contact:	http://www.sierrawireless.com/sales
Post:	Sierra Wireless 13811 Wireless Way Richmond, BC Canada V6V 3A4	
Technical Support:	support@sierrawireless.com	
RMA Support:	repairs@sierrawireless.com	
Fax:	1-604-231-1109	
Web:	http://www.sierrawireless.com/	

Consult our website for up-to-date product descriptions, documentation, application notes, firmware upgrades, troubleshooting tips, and press releases: www.sierrawireless.com

Document History

Version	Date	Updates
1.0	Apr 28, 2017	Creation
1.1	May 26, 2017	Update for 7.1.3.0 release
1.2	Jul 11, 2017	Update for 7.1.4.0 release
1.3	Sep 29, 2017	Update for 7.1.5.0 release



Contents

- 1. INTRODUCTION 6**
 - 1.1. Document Scope6
 - 1.2. Supported Configurations and Modules6
 - 1.2.1. Supported Release Configuration6
 - 1.2.2. Supported AirPrime Modules6
 - 1.3. Terminology and Acronyms.....7
 - 1.4. Related document8
- 2. CHANGE SUMMARY 9**
 - 2.1. Version 7.1.5.09
 - 2.2. Version 7.1.4.09
 - 2.3. Version 7.1.3.09
 - 2.4. Version 7.1.2.09
- 3. KNOWN LIMITATIONS 10**
- 4. PLANNED FUTURE ENHANCEMENTS 11**

1. Introduction

1.1. Document Scope

This document describes the Sierra Wireless Android Nougat 7.1 ARM RIL release.

1.2. Supported Configurations and Modules

1.2.1. Supported Release Configuration

This release note is applicable to release configuration:

AndroidRIL_V7.1.5_ARM64_bin

Android RIL version 7.1.5.0

ARM based processors for Android Nougat (7.1) 64-bit user space

Binary only release

1.2.2. Supported AirPrime Modules

The following table lists supported AirPrime modules and corresponding firmware versions.

Table 1. Supported AirPrime Modules and Firmware Versions

AirPrime Module	Firmware Version	RIL Type
AR7552	SWI9X15A_07.10.08.00 r32399 (or newer)	AR
EM7305	SWI9X15C_05.05.16 (or newer)	QMI
EM7330	SWI9X15C_05.05.22 (or newer)	QMI
EM8805	SWI9X15C_05.05.16 (or newer)	QMI
EM7565	SWI9X50C_00.06.00.00 (or newer)	QMI
HL7518	HL75xx.2.13 (or newer)	HL
HL7528	AHL7528.2.6.151000 (or newer)	HL
HL7538	AHL7538.1.0.152100 (or newer)	HL
HL7539	AHL7539.1.0.152101 (or newer)	HL
HL7548	HL75xx.A.2.13 (or newer)	HL
HL7549	BHL7549.1.3.15200 (or newer)	HL
HL7588	AHL75xx.A2.6.151600 (or newer)	HL
HL7618	RHL7618.4.2.151600.201607210015.x7120_1 (or newer)	HL
HL7648	AHL7648.A.1.3.161601.201608091650.x7120m_1 (or newer)	HL
HL7688	AHL75xx.A2.6.151600 (or newer)	HL
HL7690	AHL769x_TEST.0.0.154401 (or newer)	HL
HL7692	HL769x.2.24.173100.201709051100.x7120m_1(or newer)	HL

AirPrime Module	Firmware Version	RIL Type
HL8518	AHL85xx.5.13.2.3 (or newer)	HL
HL8528	AHL85xx.5.13.2.3 (or newer)	HL
HL8529	AHL85xx.5.13.2.3 (or newer)	HL
HL8548	RHL85xx.5.5.12.0 (or newer)	HL
HL8549	RHL85xx.5.5.12.0 (or newer)	HL
MC/EM7355	SWI9X15C_05.05.16 (or newer)	QMI
MC/EM7455	SWI9X30C_02.02.00.00 (or newer)	QMI
MC/EM7430	SWI9X30C_02.24.03.00 (or newer)	QMI
EM7430C	SWI9X30C_02.24.05.06 (or newer)	QMI
MC7304	SWI9X15C_05.04.02 (or newer)	QMI
MC7354	SWI9X15C_05.04.02 (or newer)	QMI
MC7700	SWI9200X_03.05.16.01 (or newer)	QMI
MC7710	SWI9200X_03.05.16.01 (or newer)	QMI
MC7750	SWI9600M_03.05.10.05 (or newer)	QMI
MC8305 (G3K)	1580 and 3.3	QMI
MC8355 (G3K)	1580 and 3.3	QMI
SL8092	SWI6600P_02.00.01.01 (or newer)	AT
SL909x	331403 (or newer)	QMI
WP7504	SWI9X15Y_07.12.09.00 (or newer)	QMI
WP7603	SWI9X07Y_02.00.01.0 (or newer)	QMI

Note that:

- MC7700 and MC7710 modules can be configured to operate in either “QMI mode” or “Direct-IP” mode; the MC7700 and MC7710 modules must be in “QMI mode” for the Android RIL to operate properly.
- MC73xx, MC7750, MC8305, MC8355 and SL909x modules only support QMI mode and so will work by default.
- MC73xx supports multi-PDN by default; it must be switched back to single PDN to work with the Android RIL.

1.3. Terminology and Acronyms

Term/Acronym	Definition
API	Application Programming Interface
OEM	Original Equipment Manufacturer
QMI	Qualcomm Modem Interface; Qualcomm MSM Interface
RIL	Radio Interface Layer

1.4. Related document

- [AirPrime - Android RIL Integration Guide.pdf](#)



2. Change Summary

2.1. Version 7.1.5.0

- Add support to EM7565, HL7692 and EM7430C.
- Add support radio capability RIL request in QMI RIL.
- Improved firmware download and power up sequence on WP76xx.
- Fix DTMF slow response in HL RIL.
- Fix network time not update correctly in HL RIL.
- Fix InCallUI is missing in Dialer.
- Fix GPS time injection failed on WP76xx.
- Fix data connection failed with IPv4v6 profile.
- Fix GNSS memory issue if satellite number over 32.

2.2. Version 7.1.4.0

- Add firmware download support to WP76xx.
- Fix WP7603 not able to report NMEA data.
- Fix NITZ indication delay issue.
- Fix high probability get IP address failed.
- Fix WP7603-1 cannot detect in RIL.

2.3. Version 7.1.3.0

- Add support to WP7504 and WP7603
- Add support to Galileo and Beidou satellites
- Improve RIL task scheduler
- Improve Sierra GPS library stability
- Fix HL85xx 2G data session not working in India network

2.4. Version 7.1.2.0

- Add Sierra USB driver supported on Hikey Android 7.1 ARM64 platform.
- Add Sierra RIL supported on Hikey Android 7.1 ARM64 platform.



3. Known Limitations

Known issues in the Android 7.1 RIL.

- None

4. Planned Future Enhancements

The following features are planned to be supported in a future release of the Android RIL:

- OTASP/OMADM support for MC73xx