

CAUTION

RESISTANCE WELDING MACHINE

WEAR APPROPRIATE PERSONAL PROTECTIVE EQUIPMENT

(ie. eye, face, hearing etc.)

- Never start machine unless all guards are in place, properly designed and adjusted.
- Shields of safety glass or other fire-resistant material confine flying sparks.
- Keep work area clean. Foreign materials may cause poor footing
- Wear proper gloves to protect hands—keep hands clear of electrodes.
- Operate machine using only certified control settings and procedures.
- Double check heat and tip pressure before welding.
- Inspect welding cables often for damage and wear.
- De-energize and lockout all energy systems before making adjustments/ repairs.
- Do not wear gloves, jewelry, or loose clothing.
- Ensure that operator is properly trained and has read owners operation manual.

Note: Immediately report all machinery malfunctions to management