

Pictures for question 25



21

Corrosion of steel girder at connection to helix ramp core wall at the Level 4 north bridge




22


Corrosion of steel girder at connection to helix ramp core wall at the Level 4 north bridge



23 Corrosion of steel box girder



27 Spalled concrete and exposed reinforcement at underside of parking garage beam



31

Spalled and cracked concrete curb