

Reference Number	Bulletin 01 – 2026
Affected Product	9U-6698 Puller Stud
Risks Identified	Reduced Capacity
Release Date	21 st September 2026

9U-6698 Puller Studs Could Have a Reduced Capacity

Introduction

The problem that is identified below does not have a known permanent solution. Until a permanent solution is known, use the solution that is identified below.

Problem

Some **9U-6698** Puller Studs could have a reduced capacity.



Arrow indicates the date code

(A) - a 9U-6698 Puller Stud.

Some **9U-6698** Puller Studs could have a reduced capacity

Solution

Please inspect all inventory of **9U-6698** Puller Studs.

All **9U-6698** Puller Studs with the date code of **7-25** and **5-26** should be taken out of service and labelled as "do not use/defective". Parts should be retained until further instructions are received from the Original Equipment Manufacturer.

Please contact your local dealer support representative for further information.

This bulletin is to inform you of the recommendations of the supplier in respect of issues dealt with in the bulletin and should not be used as specific advice in respect of any particular event. Advice from a qualified repairer should be sought in respect of any particular event. Hastings Deering (Australia) Limited accepts no responsibility for any loss or damage occasioned by a person using this general bulletin.