

RELEASE NOTES

# Viking Payment Terminals



Version 2.04 Patch 2 | October 2025

<b>1.</b>	<b>INTRODUCTION .....</b>	<b>3</b>
<b>2.</b>	<b>DEFECTS AND KNOWN ISSUES.....</b>	<b>4</b>
2.1	Defects and issues fixed .....	4
2.2	Known issues at the time of release .....	4
<b>3.</b>	<b>COMPLIANCE.....</b>	<b>5</b>
3.1	PCI SSS/SSF Validation .....	5
3.2	Acquiring Kernels .....	5

# 1. INTRODUCTION

This release covers all the Ingenico TETRA based payment terminal models running Viking Payment Application. The version is PCI (Payment Card Industry) SSS (Software Security Standard)) validated and compatible with all acquiring channels available for the Viking Payment platform from Nets.

Major issues in this patch release include:

- Known SELF/4000 issues resolved partly
- Includes a new Ingenico SDK and Unattended add-on components

For information on the availability of this release, please contact your Nets support channel(s). For further information on the terminal ranges supported, please consult the user guides/quick guides available on the Nets website (<https://payments.nets.eu/payment-terminals> ).

The information contained in this document is confidential and only aimed at the intended recipient. The information shall neither be used, published, nor redistributed without the prior written consent of Nets.

**NOTE:** *With integrated terminals, it is mandatory to familiarize with the PCI regulations and SSF Implementation Guide available via the Nets website (<https://support.nets.eu/category/payment-terminals> > under the Guides tab), take the necessary action required by those guidelines, and follow any other requirements from card schemes. Not following these rules may incur additional fees or sanctions.*

*Whenever receipt printing or saving is required, please be aware that integrated solutions require you to print all the contents of preformatted receipt data.*

## 2. DEFECTS AND KNOWN ISSUES

*Please note that this patch version is only targeted to be used with SELF/4000!*

### 2.1 Defects and issues fixed

- When a card is left inside the payment terminal over 1 minute after the transaction completion, the payment terminal may freeze, observed on SELF/4000 units
- Random reboot on idle state

### 2.2 Known issues at the time of release

Lane/3600

- Random black screen might occur when entering menus or key press in idle state
- When using APM (Alternative Payment Methods), the touch screen does not respond when trying to select manual QR code.

## 3. COMPLIANCE

### 3.1 *PCI SSS/SSF Validation*

This release has been approved by our chosen QSA (Qualified Security Assessor) and, in a while, will be listed on the PCI council website (<https://www.pcisecuritystandards.org/product-solutions-listings-overview/>). Our Product version numbering is presented in the following format: X.YY (e.g. 2.03) as described in the implementation guide.

### 3.2 *Acquiring Kernels*

The release has no updated kernels for payment schemes. The release has been validated through functional testing for the applicable acquiring channels.