

RELEASE NOTES

Viking Payment Application

Version 2.05 - Patch 2



Table of Contents

Section	Page
1. INTRODUCTION.....	3
2. MAJOR FEATURES.....	4
3. DEFECTS AND KNOWN ISSUES	5
3.1 Defects and issues fixed.....	5
3.2 Known issues at the time of release	5
4. COMPLIANCE	6
4.1 PCI SSS/SSF Validation	6
4.2 Acquiring Kernels	6

1. INTRODUCTION

This release covers the attended Ingenico TETRA based attended payment terminal models running Viking Payment Application. The version is PCI (Payment Card Industry) SSS (Software Security Standard) validated and compatible with all acquiring channels available for the Viking Payment platform from Nets.

This patch release includes:

- A fix for issue when Lane3600 payment terminal ends up into the reboot loop when it is updated to version 2.06. An update to version 2.06 for Lane3600 must go via this patch version.

For information on the availability of this release, please contact your Nets support channel(s). For further information on the terminal ranges supported, please consult the user guides/quick guides available on the Nets website (<https://payments.nets.eu/payment-terminals>).

The information contained in this document is confidential and only aimed at the intended recipient. The information shall neither be used, published, nor redistributed without the prior written consent of Nets.

NOTE: *With integrated terminals, it is mandatory to familiarize with the PCI regulations and SSF Implementation Guide available via the Nets website (<https://support.nets.eu/category/payment-terminals> > under the Guides tab), take the necessary action required by those guidelines, and follow any other requirements from card schemes. Not following these rules may incur additional fees or sanctions.*

Whenever receipt printing or saving is required, please be aware that integrated solutions require you to print all the contents of preformatted receipt data.

2. MAJOR FEATURES

Contents introduced in this Viking release are targeted only for Lane3600 payment terminals.

No new major features included. This patch version is targeted to Lane3600 to get the later release version 2.06 successfully updated.

3. DEFECTS AND KNOWN ISSUES

3.1 *Defects and issues fixed*

- Lane3600 payment terminal may end up into the reboot loop after the later release version 2.06 is loaded via update.
 - This “jump version” must be used to successfully update Viking payment terminal software to release version 2.06!

3.2 *Known issues at the time of release*

Payment terminal Lane/3600

- When using APM (Alternative Payment Methods), the touch screen does not respond when trying to select manual QR code.

4. COMPLIANCE

4.1 *PCI SSS/SSF Validation*

This release has been approved by our chosen QSA (Qualified Security Assessor) and, in a while, will be listed on the PCI council website (<https://www.pcisecuritystandards.org/product-solutions-listings-overview/>). Our Product version numbering is presented in the following format: X.YY (e.g. 2.03) as described in the implementation guide.

4.2 *Acquiring Kernels*

The release has no updated kernels for payment schemes. The release has been validated through functional testing for the applicable acquiring channels.