

28 Burrows Road St Peters - CAE Flight Training Centre - Complaints Register

No.	Date	Complainant	Issue	Cause	Resolution Date	Resolution
				Vibration caused by excavator tracking across		Observation of the demolition procedure. Operator instructed to track across slabs
1	14/12/2023	Specialist Tunnel Excavations	Vibration felt in neighbouring commerical office.	existing slab during demolition.	14/12/2023	in low gear.
2	16/12/2023	Specialist Tunnel Excavations	Vibration felt in neighbouring commerical office.	Vibration due to demolition material hitting slab.	16/12/2023	Subcontractor instructed to lower sections of warehouse to floor with excavator.
				Vibration caused by slab removal with ripper		Work stopped. An alternate methodology was deployed for slab removal (use of
3	18/12/2023	Specialist Tunnel Excavations	Vibration felt in neighbouring commerical office.	attachment.	18/12/2023	hammer attachment).
						Work stopped in that area. Excavation backfilled. Lime added to stockpile and
				Odour from spoil around UST4,5,6 Tank		fogmaster deodouriser used for future works. Council officer confirmed FDC's
4	20/12/2023	Transurban	Petroleum odour in office building.	excavation.	20/12/2023	compliance with the RAP was appropriate.
5	2/02/2023	Specialist Tunnel Excavations	Vibration felt in neighbouring commerical office.	Vibration due to removing slab with ripper	2/02/2023	Work stopped. Different methodology deployed for slab removal (use of hammer).