



## **ENGINEERING BULLETIN**

Subject: Instinct Gas Valve Plug

The Instinct Gas Valve Plug (X9) is capable of being installed backwards. Do not operate the boiler with the plug in a backwards orientation as the boiler will not operate correctly and damage to the blower will occur requiring it to be replaced. See the photos below for the correct

orientation of the plug and correct if it is plugged in the incorrect orientation.





Date: 5/12/2021

Please contact technical support at <u>techsupport@triangletube.com</u> or (856) 228-8881 x575 with any questions.

Triangle Tube - 1240 Forest Parkway, Suite 100 - West Deptford, NJ 08066 Tel: 856 228 8881 - Fax: 856 228 3584 - e-mail: info@triangletube.com