



Vehicle Inspection Checklist

Robbie White / Jason Reyes / 21 Jun 2023

Complete

Score	48 / 52 (92.31%)	Flagged items	0	Actions	0
-------	------------------	---------------	---	---------	---

Client / Site

Robbie White

Location

8068 Ortigas Ave Ext, Cainta, Rizal,
Philippines

Prepared by

Jason Reyes

Conducted on

21 Jun 2023 12:30 PST

Audit		48 / 52 (92.31%)
General Information		
Select vehicle identification type		
VIN	License Plate #	Other
Enter VIN #		5F08A2257591
Enter License Plate No.		IK 2845
Take photo of license plate		
		
Photo 1		
Enter identification type		Ford Everest 2015 Dark Blue
Enter Mileage		91,308
Take photo of vehicle		
		
Photo 2		
Inspection		48 / 52 (92.31%)
BRAKE SYSTEM		4 / 4 (100%)
Service brakes	OK	
Parking brakes	OK	
Brake drums/rotors	Not Applicable	
Brake hose	OK	
Low pressure warning device	OK	
COUPLING DEVICES		
Fifth wheel	Not Applicable	
Pintle hooks	Not Applicable	

Drawbar/towbar eye and tongue	Not Applicable
ENGINE OPERATION	3 / 4 (75%)
Fan/compressor belts	OK
Oil pressure	OK
Radiator	OK
Battery	Needs Repair

Car battery became more pronounced. Colder temperatures made the engine oil much thicker.




Photo 3

REFERENCE: Vehicle Battery clean and maintained regularly
[This is an example of how you can use iAuditor to include best practice reference images in your templates to assist with inspections]



EXHAUST SYSTEM	3 / 3 (100%)
Check below driver position	OK
Check for damage to wiring and fuel line	OK
Muffler	OK
FUEL SYSTEM	2 / 3 (66.67%)
Visible leak	Needs Repair

Leaks found on fuel engine system.



Photo 4

Fuel tank filler cap missing	OK
Fuel tank securely attached	OK
LIGHTING DEVICES	6 / 6 (100%)
Head lights	OK
Brake lights	OK
Tail lights	OK
Dash lights	OK
Clearance lights	OK
Turn indicators	OK
SAFETY EQUIPMENT	4 / 4 (100%)
Seat belts available and working	OK
Fire extinguisher	Not Applicable
Fags, flares	OK
Decals	OK
Spare bulbs, fuses	OK
SAFE LOADING	2 / 2 (100%)
Protection against shifting cargo	OK
Lift gate and accessories	OK
STEERING MECHANISM	7 / 8 (87.5%)
Steering wheel free play	OK
Steering column	OK
Front axle beam	OK

Steering gear box	OK
Pitman arm	Needs Repair
Noticed some steering problems due to poor condition of pitman arm.	
	
Photo 5	
Power steering	OK
Ball and socket joints	OK
Tie rods, drag links	OK
SUSPENSION 3 / 3 (100%)	
U-bolts and spring hangers	OK
Spring assembly	OK
Tongue, radius or tracking components	OK
TIRES 3 / 3 (100%)	
Condition	OK
Air pressure	OK
Chains	OK
WHEELS 3 / 4 (75%)	
Wheels and rims	OK
Lock or side rings	Needs Repair
Side rings are dirty.	
	
Photo 6	
Fasteners	OK
Welds	OK

WINDSHIELD

2 / 2 (100%)

Glass free of cracks, discoloration

OK

Wiper power unit, blades

OK

MISCELLANEOUS

6 / 6 (100%)

Transmission fluid

OK

Clutch free play

OK

Heater/defroster

OK

Mirrors

OK

Frame

OK

Body

OK

SUMMARY

List any other conditions which may prevent safe operation of this vehicle

1. Watch for leaks
2. Regular maintenance
3. Gas cap required

Enter any other observations

None

Rate the overall condition of the vehicle

Average

Recommendations

Enter recommendations here

1. Regularly check the vehicle components.
2. Check for leaks.
3. Inspect tire pressures.
4. Be mindful of the steering system.
5. Clean the brake dust off of the wheels.
6. Check oil levels.

COMPLETION

Full Name and Signature of Inspector

Jason Reyes
21 Jun 2023 12:59 PST

Media summary



Photo 1



Photo 2




Photo 3




Photo 4



Photo 5



Photo 6