



Ozark Import Specialists, Inc.

3802 Kelley Avenue
Springdale, AR. 72762
Phone: 479-751-0800


INVOICE

24170

Invoice from History

Printed Date: 05/18/2026

Work Completed: 05/12/2022



1991 Mazda - MX-5 Miata - 1.6L, In-Line4 (98CI) VIN(1)

Lic # : 309TFN

Odometer In : 89573

Odometer Out : 89573

VIN # : JM1NA3516 M1224685

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
Shock Absorber-Rear 341127	2.00	93.01	186.02	Replace rear struts and strut mounts.	385.00
Strut Mount-Front SM5077	2.00	88.26	176.52	Replace front struts and strut mounts.	385.00
Strut Mount-Rear SM5077	2.00	88.26	176.52	We were supposed to disable seatbelt sound but it's still going. Please install customer supplied driver's seat seatbelt receiver.	n/c
Shock Absorber-Front 341143	2.00	107.50	215.00		
Shop Supplies			30.48		

Org. Estimate 0.00 Revisions 0.00 Current Estimate 0.00

Labor:	770.00
Parts:	784.54
SubTotal:	1,554.54
Tax:	151.57
Total:	1,706.11
Bal Due:	\$0.00

[Payments - MasterCard - \$1,706.11]

Vehicle Received: 5/11/2022

Customer Number : 8197

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Parts and Labor warranty is 12 months or 12,000 miles, whichever comes first. I understand that there is no labor or parts warranty provided for customer supplied or used parts or as otherwise noted on this document. No warranty is provided for any aftermarket performance modifications intended for off road use only. Aftermarket performance parts are intended solely for legally organized and sanctioned, closed course, off-road competition use only and not for use on vehicles that are driven on public streets, roads, or highways. We do not guarantee customer diagnosed issues. Warranty work must be performed at our facility and cannot exceed the original cost of repair. Warranty does not cover abuse or negligence in vehicle operation. Warranty is non-transferable and applies to the original purchaser only.

Nichols, Steve Paid \$ 1,706.11 Card#: Transaction: Approval: Date/Time: 5/12/2022 11:45:35AM

Signature x

05/12/2022

Buyer agrees to pay total amount above according to cardholder's agreement with issuer.

Visit us on the web: <https://ozarkimport.com>




Ozark Import Specialists, Inc.
 3802 Kelley Avenue
 Springdale, AR. 72762
 Phone: 479-751-0800

INVOICE

23616

Invoice from History

Printed Date: 05/18/2026 Work Completed: 01/14/2022



1991 Mazda - MX-5 Miata - 1.6L, In-Line4 (98CI) VIN(1)
 Lic # : 309TFN Odometer In : 88461
 Odometer Out : 88461
 VIN # : JM1NA3516 M1224685

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
Brake Fluid 500ML DOT3 500	1.00	7.92	7.92	Customer concern: List provided of needed repairs and diagnostics.	n/c
Oil Filter 72230WS	1.00	8.68	8.68	Check and advise.	
Synthetic Motor Oil. Size: QUART 5w30mob1	3.60	11.95	43.02	Perform oil, lube, and filter service.	52.50
Gear Oil GEAR 300 75W90 1L 3374650 003399	2.00	33.07	66.14	Change engine oil and oil filter.	
Coolant/Antifreeze Yellow Universal 1G LD4330/50201	2.00	22.12	44.24	Lubricate chassis if necessary and visually inspect.	
Gear Oil-Rear Differential MOTYLGEAR 75W90 1L 109055	1.00	24.20	24.20	Check all fluid levels and adjust if necessary.	
Brake Disc-Front B25Y-33-25XB	2.00	47.21	94.42	Check Wipers.	
Brake Pad Set-Front and Shims BP525	1.00	77.73	77.73	Check and adjust tire pressures if necessary.	
Brake Disc-Rear Zinc Coated NA01-26-251D	2.00	41.57	83.14	Perform visual brake inspection.	
Brake Pad Set-Rear and Shims BP458	1.00	66.13	66.13	Visually inspect cooling system for leaks and integrity of hoses and mechanical components.	
Ignition Wire Set NGK-ZE21 9160	1.00	76.40	76.40	Visually inspect engine compartment and undercarriage for leaks.	
Spark Plug FR8DCX+ 7957	4.00	6.38	25.52	Visually inspect belts and pulleys.	
Tie Rod End-Front Outer 2600-66997	2.00	18.57	37.14	Reset onboard maintenance indicators and check for upcoming maintenance items if listed in computer.	
Clutch Pedal Stop Pad B001-43-029	1.00	5.06	5.06	Perform brake fluid exchange.	110.00
Air Filter 6097	1.00	21.70	21.70	Replace transmission gearbox fluid.	55.00
Shop Supplies			44.73	Replace coolant.	110.00
				Lubricate squeak in left door.	n/c
				Check wheel bearings.	n/c
				Replace differential fluid.	55.00
				Replace front brake pads, and rotors.	220.00
				Replace rear brake pads and rotors.	220.00
				Customer concern: Cruise control does not work.	110.00
				Check and advise.	
				Perform level 1 diagnostics. Includes up to 1 hour of diagnostic time.	
				Perform road test if possible and confirm complaint, note any illuminated warning indicators, perform visual inspection, scan for data trouble codes and data anomalies, check for TSB's, and determine root cause of failure using standard diagnostic procedures.	
				Check suspension and shocks for needed repairs or maintenance.	n/c
				Customer concern: Horn does not function.	55.00
				Check and advise.	
				Perform 4 wheel alignment and balance tires.	100.00
				Replace spark plugs and ignition wires and perform compression test.	165.00
				Customer requests disable seatbelt sound.	55.00
				TIE ROD &/OR END - Remove & Replace - Both	137.50
				Labor to replace clutch pedal stop	55.00
				Replace air filter.	55.00
				Check windshield washers to confirm they function properly.	n/c
				Check exhaust system for leaks or holes.	n/c
				Slight leak at back of converter.	

Visit us on the web: <https://ozarkimport.com>