

Precision Autosport

74 Spring Lake Dr, Rear Left Unit
New Britain, PA 18901
+12677423500
info@precisionautosport.net
www.precisionautosport.net

**INVOICE**

BILL TO

SHIP TO

INVOICE 3838
DATE 04/03/2026
DUE DATE 04/03/2026

QTY	PRODUCT	DESCRIPTION	RATE	AMOUNT
1	memo	1987 Fiero Vin - HP214641 Mileage - 33,503	0.00	0.00
1	Revivify Full	Revivify Self Healing Paint Protection Package - Full Vehicle	2,000.00	2,000.00T
SUBTOTAL				2,000.00
TAX				120.00
TOTAL				2,120.00
BALANCE DUE				\$2,120.00

PSI Proformance

Customer Signature _____

Precision Autosport

74 Spring Lake Dr, Rear Left Unit
New Britain, PA 18901
+12677423500
info@precisionautosport.net
www.precisionautosport.net



INVOICE

BILL TO

SHIP TO

INVOICE 3862
DATE 04/16/2026
DUE DATE 04/16/2026

QTY	PRODUCT	DESCRIPTION	RATE	AMOUNT
1	Accessory Labor	Accessory Installation Labor - Wrap Grills for Fiero	100.00	100.00
SUBTOTAL				100.00
TAX				0.00
TOTAL				100.00
BALANCE DUE				\$100.00

Customer Signature _____

JON MILLER CAR CARE CENTER

330 EAST MAIN STREET (Rt. 9)

Tuckerton, NJ. 08087

Phone: 609-296-4400 Fax: 609-296-4440

QUALITY, SERVICE, INTEGRITY

REPAIR ORDER #

074244

PIF: 001067

ERF: 003279

REPAIR ORDER - RO

Scheduled : 03/21/2026 08:09 AM

Print Date : 3/21/2026

1987 Pontiac - Fiero GT - 2.8L, V6 (173CI) VIN(9)

Lic # : C65294 - PA

VIN # : 1G2PG1194 HP214641

MFG Date : 1/2/2026

Last Service : 2/16/2026

Previous Odom : 33184

Current Odom : 0

Elapsed : 0

Labor Requested / Part Description	Qty	Parts List	Extended
Safety Inspection & Brake Inspection			
NEWYALL LEFT AND RIGHT HEADLIGHT MOTORS	1.00	171.58	171.58
INSTALL NEW HEADLAMP MOTOR ASSEMBLIES			247.10
Discount			
\$25.00 off parts, \$25.00 off labor			
Shop Supplies			23.32
Hazardous Materials			2.50

[Recommendations]

Next oil change occurs at 83,161 Miles - Premium Motor Oil

THANKS, PLEASE REVIEW OUR SERVICE ON FACEBOOK AND GOOGLE.

Parts: 171.58

Supplies: 23.32

HazMat: 2.50

Labor: 247.10

Discount: 50.00

Tax: 26.13

Total: 420.63

Balance: 420.63

TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within 7 days of the date shown above if I choose not to authorize the service recommended. All Parts removed will be discarded unless instructed otherwise: Some parts have to be returned to our suppliers for rebuilding or proper recycling. Those parts can be inspected but not released to customer.

SAVE ALL ELIGIBLE PARTS

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE.

STORAGE FEES \$50 PER DAY AFTER 5 DAYS OF COMPLETION.

UNPAID INVOICES WILL ACCRUE 5% INTEREST COMPOUNDED DAILY.

Authorized By

Date

Time

Service Advisor : SCHERLIN, BRYAN

Page 1 of 1

Copyright (c) 2026 Mitchell Repair Information Company, LLC ropartdetail2 dj 7.2.18

JON MILLER CAR CARE CENTER

330 EAST MAIN STREET (Rt. 9)

Tuckerton, NJ. 08087

Phone: 609-296-4400 Fax: 609-296-4440

QUALITY, SERVICE, INTEGRITY

REPAIR ORDER #

073726

PIF: 001067

ERF: 003279

REPAIR ORDER - RO

Scheduled : 02/16/2026 01:01 PM

Print Date : 2/16/2026

1987 Pontiac - Fiero GT - 2.8L, V6 (173CI) VIN(9)

Lic # : C65294 - PA

VIN # : 1G2PG1194 HP214641

MFG Date : 1/2/2026

Last Service : 1/26/2026

Previous Odom : 33116

Current Odom : 0

Elapsed : 0

Labor Requested / Part Description	Qty	Parts	List	Extended
REPLACE TRANSDUCER IN EGR SOLENOID. NO WARRANTY!!!!				131.78
EGR SOLENOID PRESSURE TRANSDUCER	1.00		44.00	44.00
Shop Supplies				13.84
Hazardous Materials				2.50

[Recommendations]

Next oil change occurs at 83,161 Miles - Premium Motor Oil

Revision # 1, Previous Estimate Amount: 2.50, Additional Cost: 204.85, Revised Estimate: 207.35, Parts: \$44.00 Labor: \$131.78 Sublet: \$0.00 Taxes & Fees: \$29.07 Authorized by - ESHLEMAN, JEFF, Date - 2/16/2026, Time - 1:01 PM, Initiated By - Shop, Written By - GUENTHER, JOHN, Phone Number - In Person

THANKS, PLEASE REVIEW OUR SERVICE ON FACEBOOK AND GOOGLE.**Parts: 44.00****Supplies: 13.84****HazMat: 2.50****Labor: 131.78****Tax: 12.73****Total: 204.85****Balance: 204.85**


TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within 7 days of the date shown above if I choose not to authorize the service recommended. All Parts removed will be discarded unless instructed otherwise: Some parts have to be returned to our suppliers for rebuilding or proper recycling. Those parts can be inspected but not released to customer.

SAVE ALL ELIGIBLE PARTS

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE.

STORAGE FEES \$50 PER DAY AFTER 5 DAYS OF COMPLETION.

UNPAID INVOICES WILL ACCRUE 5% INTEREST COMPOUNDED DAILY.

Authorized By 

Date _____ Time _____

Service Advisor : GUENTHER, JOHN

Page 1 of 1

Copyright (c) 2026 Mitchell Repair Information Company, LLC ropartdetail2 dj 7.2.18

JON MILLER CAR CARE CENTER

330 EAST MAIN STREET (Rt. 9)

Tuckerton, NJ. 08087

Phone: 609-296-4400 Fax: 609-296-4440

QUALITY, SERVICE, INTEGRITY

INVOICE

73003

PIF: 001067
ERF: 003279

INVOICE

Printed Date: 01/26/2026

Work Completed: 01/26/2026

1987 Pontiac - Fiero GT - 2.8L, V6 (173CI) VIN(9)

Lic # : C65294

Odometer In : 33116

VIN # : 1G2PG1194 HP214641

Part Description	Qty	Sale	Ext	Labor Description	Ext
Brake Flush Fluid and Brake Fluid	1.00	34.50	34.50	LEVEL 1 MECHANICAL DIAGNOSIS	99.95
VALVOLINE SEMI SYNTHETIC 5W30 Motor Oil	5.00	6.39	31.95	CUSTOMER STATES: FIERO EVALUATION	
Partsmaster spin-on lube filter	1.00	5.80	5.80	CUSTOMER UNDERSTANDS ADDITIONAL TIME/ CHARGES MAY BE REQUIRED.	
BG COOLANT FLUSH KIT AND ENGINE COOLANT	1.00	99.95	99.95	LIST OF NEEDS, THE MUST DO LIST FIX LEAK, LEFT TURN SIGNAL, 4WAY FLASHERS, ROUND SILVER THING THATS LOOSE UNDER DASH, MUST PASS PA INSPECTION, RATTLE IN DRIVERS DOOR, CHANGE FLUIDS, NEW SPARK PLUGS, OIL PRESSURE LIGHT OUT, HEADLIGHT SPEED DIFFERENCE	n/c
Engine Coolant Thermostat Housing Cap	1.00	23.92	23.92	LIST OF OPTIONAL NEEDS, MILDEW SMELL WHEN HEAT OR AC IS ON, POP SOUND RR SPEAKER, SPACE ABOVE OIL AND VOLT METER, BRAKES, HOSES, BATTERY.	n/c
Engine Coolant Thermostat	1.00	26.63	26.63	LIST OF QUESTIONS, THE SHIFTER IS VAGUE, IS THAT THE WAY IT'S SUPPOSED TO BE? UNKNOWN IF A/C IS OPERATING	n/c
Radiator Cap	1.00	16.99	16.99	Brake fluid flush	99.95
SYNCHROMESH FLUID	3.00	24.95	74.85	Check brake fluid for moisture and contamination. Inspect all hydraulic line and hoses. Inspect calipers and wheel cylinders. Inspect master cylinder and cap. Flush entire brake system including master cylinder, calipers, wheel cylinders until clean.	
COOLANT BOTTLE RESEVOIR	1.00	87.89	87.89	Change Motor Oil, and Lube Chassis	19.95
FRONT CONTROL ARM BUSHING SET	1.00	131.89	131.89	Reset Oil Maintenance Light if Applicable	n/c
REAR POLY CONTROL ARM BUSHING SET	1.00	98.89	98.89	Drain and flush cooling system	89.95
camber kit	2.00	44.00	88.00	Inspect hoses and clamps. Pressure test cooling system. Flush engine, radiator, and heater core in both directions. Bring antifreeze to -35 degrees. PH balance coolant to between 9.8 to 10.5. Check thermostat and electric cooling fan operation. Chec	
ALUMINUM CRADLE BUSHING SET	1.00	282.70	282.70	REPLACE TRANSMISSION FLUID	98.84
Suspension Stabilizer Bar Link (Front)	1.00	34.39	34.39	REPLACE COOLANT BOTTLE	49.42
BRAKE HOSE SET SS	1.00	323.10	323.10	REPLACE ALL FRONT AND REAR SUSPENSION BUSHINGS WITH POLYURETHANE.	1,812.03
Spark Plug	6.00	9.62	57.72	FIERO COMPLETE ALIGNMENT.	189.95
Distributor Cap	1.00	47.19	47.19	Road test vehicle. Check all suspension and steering parts for wear. Check tire pressure and condition. Check riding height. Check alignment of all four wheels. Adjust caster, camber, toe-in, and thrust angle as needed on all four wheels. Center steering wheel. (DOES NOT INCLUDE COMPUTER RECALIBRATION. ADDITIONAL CHARGES MAY APPLY IF VEHICLE REQUIRES RECALIBRATION AFTER ALIGNMENT.)	
Distributor Rotor	1.00	27.28	27.28	REPLACE CRADLE BUSHINGS WITH ALUMINUM. DOES NOT INCLUDE CRADLE DETAILING.	576.56
TAYLOR SPARK PLUG WIRES	1.00	180.38	180.38	REPLACE BRAKE HOSE SET	164.73
MISC ENGINE GASKETS	1.00	44.00	44.00	TUNE UP	329.46
Air Filter	1.00	19.74	19.74	HOTSYS ENGINE COMPARTMENT AND UNDERSIDE OF ENGINE.	329.46
Fuel Filter (High quality)	1.00	38.49	38.49		
Ignition Control Module	1.00	188.67	188.67		
Ignition Coil	1.00	111.45	111.45		
Distributor Mounting Gasket	1.00	2.84	2.84		
Distributor Ignition Pickup	1.00	54.08	54.08		
Automatic Transmission Mount (Front Left)	1.00	29.97	29.97		
Automatic Transmission Mount (Rear Left)	1.00	29.97	29.97		
DOG BONE MOUNT	1.00	125.29	125.29		
Back Up Light Bulb AND ALSO REAR TURN SIGNAL LIGHTS	2.00	1.39	2.78		
"PONTIAC" TAIL LIGHT Light Bulb	4.00	1.93	7.72		
Tail Light Bulb	4.00	1.39	5.56		
194 BULB	6.00	1.55	9.30		
SELECT CABLE	1.00	242.30	242.30		
FASTBACK TRUNK WEATHERSTRIP	1.00	219.89	219.89		

Visit us on the web: www.JMCarCare.com

Service Advisor : SCHERLIN, BRYAN, Tech : Guenther (Tech), John

Page 1 of 3

Copyright (c) 2026 Mitchell Repair Information Company, LLC invhrs 5.12.21r

JON MILLER CAR CARE CENTER

330 EAST MAIN STREET (Rt. 9)

Tuckerton, NJ. 08087

Phone: 609-296-4400 Fax: 609-296-4440

QUALITY, SERVICE, INTEGRITY

INVOICE

73003

PIF: 001067
ERF: 003279

INVOICE

Printed Date: 01/26/2026

Work Completed: 01/26/2026

1987 Pontiac - Fiero GT - 2.8L, V6 (173CI) VIN(9)

Lic # : C65294

Odometer In : 33116

VIN # : 1G2PG1194 HP214641

Part Description	Qty	Sale	Ext	Labor Description	Ext
Battery - NAPA Legend - Professional - OE Exac	1.00	213.84	213.84	REBUILD DISTRIBUTOR AND REPLACE O RING FOR OIL LEAK.	362.41
4X6 PYLE SPEAKERS	1.00	58.89	58.89	INCLUDES REPLACE ALL PRIMARY IGNITION COMPONENTS AND COIL.	
HEADLIGHT GEAR REBUILD KIT	2.00	34.50	69.00	REPAIR CRADLE WHERE IT IS BENT FROM HITTING ROAD DEBRIS.	164.73
HVAC Heater Core	1.00	94.73	94.73	REPLACE BOTH TRANSMISSION MOUNTS	395.35
R134A FREON, OIL, AND DYE PACKAGE	1.00	99.95	99.95	REPLACE DOGBONE	32.95
AC CONVERSION FITTING	2.00	23.00	46.00	REPLACE ALL TAIL LIGHT, BRAKE LIGHT, AND BACKUP LIGHT BULBS IN REAR HOUSING. (NOT INCLUDING THIRD BRAKE LIGHT)	164.73
A/C Clutch Cycle Switch	1.00	78.52	78.52	REPLACE ALL 4 MARKER LIGHT BULBS	65.89
A/C Orifice Tube	1.00	2.84	2.84	REPLACE TURN SIGNAL INDICATOR BULB, AND OIL PRESSURE GAUGE ILLUMINATION BULB.	214.15
DISTRIBUTOR CORE	1.00	150.00	150.00	REPLACE SHIFTER SELECT CABLE	411.83
5 BAND EQ RADIO USED WORKING. NO WARRANTY OR GUARANTEE. USED ELECTRICAL PART. TAPE DECK UNTESTED.	1.00	250.00	250.00	TIGHTEN AND ADJUST SHIFT LINKAGE AT TRANS	49.42
Accessory Drive Belt (Water Pump and Alternator)	1.00	46.86	46.86	REPLACE TRUNK WEATHERSTRIP AND SEAL CORNERS	65.89
Accessory Drive Belt (Air Conditioning)	1.00	42.09	42.09	INSTALL BATTERY AND SERVICE TERMINALS AS NEEDED.	49.95
PCV Valve	1.00	26.13	26.13	INCLUDES MIDTRONICS BATTERY AND CHARGING SYSTEM TEST, BATTERY TERMINAL CLEANING AND TERMINAL PROTECTING AGENT FOR ACID BUILD UP	
LEFT SEAT TRIM	1.00	54.89	54.89	REPLACE REAR SPEAKERS	164.73
Shop Supplies			36.27	REBUILD BOTH HEADLIGHT MOTORS	329.46
				REPLACE HEATER CORE (PREVENTATIVE MAINTENANCE)	247.10
				RE SEAL AC COMPRESSOR. (NO GUARANTEE ON REPAIR)	296.51
				Air conditioning service	149.95
				Service air conditioner. Check condition of all belts and lines. Evacuate and recharge with reclaimed R-134 with dye added to assist in finding any leaks in system. Test system performance.	
				Customer is advised that, if new charge is lost, vehicle should be returned to shop for complimentary leak check. Small A/C leaks often cannot be detected during initial air conditioning service.	
				REPLACE ORIFICE TUBE AND REPLACE CLUTCH CYCLE SWITCH FOR 134A	197.68
				REPLACE RADIO.	82.37
				NOTE: FOUND UPPER TWO SCREW HOLES CRACKED ON RADIO FACEPLATE AND CONSOLE SKELETON BROKEN AROUND RADIO FROM PREVIOUS SERVICE.	
				REPLACE BELTS	82.37
				REPLACE SEAT BELT MECHANISM COVER LH	98.84
				Hazardous Materials	2.50

Visit us on the web: www.JMCarCare.com

Service Advisor : SCHERLIN, BRYAN, Tech : Guenther (Tech), John

INVOICE

Printed Date: 06/10/2026 **Work Completed: 06/10/2026**

1987 Pontiac - Fiero GT - 2.8L, V6 (173CI) VIN(9)
 Lic #: C65294 Odometer In : 34026

VIN #: 1G2PG1194 HP214641

Part Description	Qty	Sale	Ext	Labor Description	Ext
HEADLINER KIT	1.00	395.00	395.00	LEVEL 1 MECHANICAL DIAGNOSIS	99.95
Engine Intake Manifold Gasket Set	1.00	128.22	128.22	CUSTOMER STATES: OIL LEAK	
Engine Valve Cover Gasket Set	1.00	47.56	47.56	CUSTOMER UNDERSTANDS ADDITIONAL TIME/	
BG COOLANT FLUSH KIT AND	1.00	99.95	99.95	CHARGES MAY BE REQUIRED.	
ENGINE COOLANT				OIL PAN AND GASKET ORDERED IN PREVENTION. DID NOT	
VALVOLINE SEMI SYNTHETIC 5W30	5.00	6.39	31.95	DIAGNOSE YET.	
Motor Oil				APPT JUNE 10 8:00AM.	
Partsmaster spin-on lube filter	1.00	5.80	5.80	C/O RIGHT FRONT SPEAKER GRILL SQUEAKING.	n/c
Shop Supplies			36.27	CUSTOMER ADDED AN EXPANSION FOAM IN AN	
				ATTEMPT TO STOP THE NOISE BUT THAT DID NOT	
				WORK.	
				C/O ROOF LINER	n/c
				LABOR TO REPLACE HEADLINER	494.19
				REPLACE LOWER INTAKE GASKETS	658.92
				Drain and flush cooling system	99.95
				Inspect hoses and clamps. Pressure test cooling system. Flush	
				engine, radiator, and heater core in both directions. Bring antifreeze	
				to -35 degrees. PH balance coolant to between 9.8 to 10.5. Check	
				thermostat and electric cooling fan operation. Chec	
				Change Motor Oil, and Lube Chassis	24.95
				Reset Oil Maintenance Light if Applicable	n/c
				Safety Inspection & Brake Inspection	n/c
				Hazardous Materials	2.50

[Recommendations]

Next oil change occurs at 83,161 Miles - Premium Motor Oil

JON MILLER CAR CARE CENTER
330 EAST MAIN STREET (Rt. 9)
Tuckerton, NJ. 08087
Phone: 609-296-4400 Fax: 609-296-4440
QUALITY, SERVICE, INTEGRITY

INVOICE

74996

PIF: 001067
ERF: 003279

INVOICE

Printed Date: 06/10/2026 **Work Completed: 06/10/2026**

1987 Pontiac - Fiero GT - 2.8L, V6 (173CI) VIN(9)

Lic #: C65294

Odometer In : 34026

VIN #: 1G2PG1194 HP214641

Part Description	Qty	Sale	Ext	Labor Description	Ext
------------------	-----	------	-----	-------------------	-----

Org. Estimate 379.43 Revisions 2,200.77 Current Estimate 2,580.20

Revision # 1, Previous Estimate Amount: 379.43, Additional Cost: 2200.77, Revised Estimate: 2580.20, Parts: \$708.48 Labor: \$1278.01 Sublet: \$0.00
Taxes & Fees: \$214.28 Authorized by - ESHLEMAN, JEFF. Date - 6/10/2026, Time - 8:52 AM, Initiated By - Shop, Written By - GUENTHER, JOHN

Labor:	1,377.96
Parts:	744.75
HazMat:	2.50
SubTotal:	2,125.21
Tax:	140.80
Total:	2,266.01
Bal Due:	\$0.00

[Payments - MasterCard - \$2,266.01]

Vehicle Received: 6/10/2026

Customer Number : 12379

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection.
All Parts removed will be discarded unless instructed otherwise: Some parts have to be returned to our suppliers for rebuilding or proper recycling. Those parts can be inspected but not released to customer.

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE.
STORAGE FEES \$50 PER DAY AFTER 5 DAYS OF COMPLETION.
UNPAID INVOICES WILL ACCRUE 5% INTEREST COMPOUNDED DAILY.

An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is TWO YEARS OR 24,000 miles whichever comes first. Warranty is provided by Confidence Plus North American Warranty. For claims: 1-877-230-0369

Signature

Date

Visit us on the web: www.JMCarCare.com

Service Advisor : FORRESTER, MATT, Tech : Guenther (Tech), John

JON MILLER CAR CARE CENTER
330 EAST MAIN STREET (Rt. 9)
Tuckerton, NJ. 08087
Phone: 609-296-4400 Fax: 609-296-4440
QUALITY, SERVICE, INTEGRITY

INVOICE

76372

PIF: 001067
ERF: 003279

INVOICE

Printed Date: 07/21/2026

Work Completed: 07/21/2026

1987 Pontiac - Fiero GT - 2.8L, V6 (173CI) VIN(9)

Lic # : C65294

Odometer In : 34279

VIN # : 1G2PG1194 HP214641

Part Description	Qty	Sale	Ext	Labor Description	Ext
------------------	-----	------	-----	-------------------	-----

Org. Estimate 2.67 Revisions 1,460.95 Current Estimate 1,463.62

Revision # 1, Previous Estimate Amount: 2.67, Additional Cost: 1460.95, Revised Estimate: 1463.62, Parts: \$687.27 Labor: \$644.14 Sublet: \$0.00
Taxes & Fees: \$129.54 Authorized by - ESHLEMAN, JEFF, Date - 7/21/2026, Time - 8:40 AM, Initiated By - Shop, Written By - GUENTHER, JOHN,
Phone Number - In Person

Labor:	644.14
Parts:	723.54
HazMat:	2.50
SubTotal:	1,370.18
Tax:	90.77
Total:	1,460.95
Bal Due:	\$0.00

[Payments - MasterCard - \$1,460.95]

Vehicle Received: 7/21/2026

Customer Number : 12379

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection.
All Parts removed will be discarded unless instructed otherwise: Some parts have to be returned to our suppliers for rebuilding or proper recycling. Those parts can be inspected but not released to customer.

NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE.
STORAGE FEES \$50 PER DAY AFTER 5 DAYS OF COMPLETION.
UNPAID INVOICES WILL ACCRUE 5% INTEREST COMPOUNDED DAILY.

An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is TWO YEARS OR 24,000 miles whichever comes first. Warranty is provided by Confidence Plus North American Warranty. For claims: 1-877-230-0369

Signature Jeff Eshleman Date _____

Visit us on the web: www.JMCarCare.com

Service Advisor : SCHERLIN, BRYAN, Tech : Guenther (Tech), John

JON MILLER CAR CARE CENTER
330 EAST MAIN STREET (Rt. 9)
Tuckerton, NJ. 08087
Phone: 609-296-4400 Fax: 609-296-4440
QUALITY, SERVICE, INTEGRITY

INVOICE

76372

PIF: 001067
ERF: 003279

INVOICE

Printed Date: 07/21/2026 **Work Completed: 07/21/2026**

1987 Pontiac - Fiero GT - 2.8L, V6 (173CI) VIN(9)
Lic # : C65294 Odometer In : 34279

VIN # : 1G2PG1194 **HP214641**

Part Description	Qty	Sale	Ext	Labor Description	Ext
R134A FREON, OIL, AND DYE PACKAGE	1.00	99.95	99.95	PRELIMINARY DIAGNOSIS (SIMPLE CONCERNS ONLY. NO INVASIVE PROCEDURES OR COMPUTER SCANS)	n/c
A/C Compressor	1.00	587.32	587.32	CUSTOMER STATES: A/C ISSUE, COMPRESSOR? NO REVISION BUT MAY HAVE BEEN CONVERSATION	
Shop Supplies			36.27		
				CUSTOMER UNDERSTANDS ADDITIONAL TIME/ CHARGES MAY BE REQUIRED. FOUND FRONT SEAL ON A/C COMPRESSOR BLOWN OUT. NEED TO REPLACE A/C COMPRESSOR.	
				Air conditioning service	149.95
				Service air conditioner. Check condition of all belts and lines. Evacuate and recharge with reclaimed R-134 with dye added to assist in finding any leaks in system. Test system performance.	
				Customer is advised that, if new charge is lost, vehicle should be returned to shop for complimentary leak check. Small A/C leaks often cannot be detected during initial air conditioning service.	
				REPLACE A/C COMPRESSOR	494.19
				Safety Inspection & Brake Inspection	n/c
				BATTERY TESTED VERY GOOD, WOULD CONSIDER A BATTERY MAINTAINER. DID NOT NOTICE ANY ISSUES WITH SEEN SMOKE ON START UP	
				Hazardous Materials	2.50
				[Recommendations] Next oil change occurs at 83,161 Miles - Premium Motor Oil	

Visit us on the web: www.JMCarCare.com

Service Advisor : SCHERLIN, BRYAN, Tech : Guenther (Tech), John