



Savannah, GA 31405

(912) 417-4353

Invoice

Date	Invoice #
9/18/2026	JF9751

Name / Address
HAGERTY Attn: Accounts Payable PO BOX 87 Traverse City, MI 49685 Marvin Waters II-Hagerty Marketplace

Vehicle Info
1979 Porsche 924 Turbo Rally Car 93A0190001

P.O. No.	Tech	Tech 2
	JOHN	

Item	Description	Qty	Rate	Total
Cust Issue	924 Rally Car - Wake Up	1	0.00	0.00
Repair Labor	PICKUP AT HAGERTY - INITIAL INSPECTION	1	95.00	95.00
	924 Helped load the car up on the tow truck. Brought to JFrazar. Inspected the car for needs to get running. Fuel tank has a leak and rust To replace involves taking the exhaust down. Fuel injection needs full overall along with water pump and cooling system.			
	FUEL DIST AND WUR REMOVAL - THIS WAS DONE 3 WEEKS PRIOR TO PICKUP			
Repair Labor	Fuel distributor and regulator removal @ Hagerty - Pre Job	2	168.00	336.00
Sublet	Shipping Warm Up Reg and Fuel Dist 3629 924 Rally	1	44.89	44.89
Sublet	SPT - Porsche CIS Fuel Dist Overhaul - 4292/10010E - Cross 0438100048	1	527.50	527.50
Sublet	SPT - Porsche CIS WUR overhaul 0438140062	1	365.95	365.95
	TEAR DOWN			

		Subtotal
		Sales Tax (0.0%)
		Total
		Payments/Credits
		Balance Due



Savannah, GA 31405

(912) 417-4353

Invoice

Date	Invoice #
9/18/2026	JF9751

Name / Address
HAGERTY Attn: Accounts Payable PO BOX 87 Traverse City, MI 49685 Marvin Waters II-Hagerty Marketplace

Vehicle Info
1979 Porsche 924 Turbo Rally Car 93A0190001

P.O. No.	Tech	Tech 2
	JOHN	

Item	Description	Qty	Rate	Total
Repair Labor	Removed the intercooler and complete fuel injection system. Removed the fuel injectors and cleaned and serviced them. Pulled the spark plugs and poured lubricant into the cylinders. Drained the coolant and removed the radiator hoses. Removed the water pump. Dropped the exhaust system to gain access to the fuel tank. Removed the fuel tank. Flushed the engine block and radiator.	9	168.00	1,512.00
Parts	924 OR Mavel Mystery Oil ENGINE	1	33.99	33.99T
Repair Labor	Installed new parts on engine, Water Pump, Timing belt, Thermostat, Plugs, wires, cap and rotor. Installed Warm up regulator, Fuel Dist, injectors and flushed fuel lines from fuel dist to injectors. Drain engine oil, replace filter and fill with new. Installed new lower Rad hose and water pump bypass hose - Metal crossover pipe was rusted and was replaced with rubber heater hose - new pipe will need to be made. Deep cleaned the Coolant Resv.	8.5	168.00	1,428.00
Parts	924 Conti TB017K1 Timing belt Kit	1	39.79	39.79T
Parts	924 SSF Graf Water Pump PA233 list \$154.99	1	63.82	63.82T

		Subtotal
		Sales Tax (0.0%)
		Total
		Payments/Credits
		Balance Due



Savannah, GA 31405

(912) 417-4353

Invoice

Date	Invoice #
9/18/2026	JF9751

Name / Address
HAGERTY Attn: Accounts Payable PO BOX 87 Traverse City, MI 49685 Marvin Waters II-Hagerty Marketplace

Vehicle Info
1979 Porsche 924 Turbo Rally Car 93A0190001

P.O. No.	Tech	Tech 2
	JOHN	

Item	Description	Qty	Rate	Total
Parts	924 SSF Water Hose 046121051 list \$83.61	1	48.68	48.68T
Parts	924 Heater Hose HH0304 list \$27.00 - For Bypass Pipe	1	20.99	20.99T
Parts	924 Lower Radiator Hose 21609 list \$38.00	1	25.02	25.02T
Parts	924 SSF Thermostat 059121113B list \$140.18	1	16.82	16.82T
Parts	924 Bosch 03010 Dist Cap	1	29.11	29.11T
Parts	924 Bosch 04038 Dist Rotor	1	13.33	13.33T
Parts	924 Bremi 924 Spark Plug Wire Set	1	48.79	48.79T
Parts	924 NGK 5534 Spark Plug	4	6.27	25.08T
Parts	OR Wix Oil Filter 51516 list \$25.00	1	16.95	16.95T
13x1075	SSF 978710 V Belt 13x1075 - NOT ON INVOICE SENT TO HAGERTY	1	0.00	0.00T
LM 22127 20w50	Liqui Molly Touring Tech High Zinc 20w50 Engine Oil	6	10.88	65.28T
ANTIFREEZE	Green Antifreeze per Gallon	1	24.99	24.99T
Shop Supplies	Shop Supplies - Cleaners, Sealers, Clamps and MSC Hardware	1	75.00	75.00
Shipping	Shipping	1	28.10	28.10
Repair Labor	FUEL TANK Remove fittings and level sensor - deep clean and try to get original level sensor working - Looks like it worked. - Install Level sensor in new tank - Instal new tank filter, Install new breather and vent lines. Instal Fuel tank.	2.5	168.00	420.00

		Subtotal
		Sales Tax (0.0%)
		Total
		Payments/Credits
		Balance Due



Savannah, GA 31405

(912) 417-4353

Invoice

Date	Invoice #
9/18/2026	JF9751

Name / Address
HAGERTY Attn: Accounts Payable PO BOX 87 Traverse City, MI 49685 Marvin Waters II-Hagerty Marketplace

Vehicle Info
1979 Porsche 924 Turbo Rally Car 93A0190001

P.O. No.	Tech	Tech 2
	JOHN	

Item	Description	Qty	Rate	Total
Parts	924 477201021F FUEL TANK	1	644.14	644.14T
Parts	924 WP Fuel Screen 928 201 081 04 list 498.14	1	98.72	98.72T
Shipping	Shipping	1	44.18	44.18
Shop Supplies	Shop Supplies - Level Sensor Gasket - From Stock - Choline Hose - From Stock - MSC Clamps and Hardware	1	95.00	95.00
Repair Labor	FUEL PUMP ASYM - REBUILD Remove Complete Fuel pump, Filter and Accumulator asym - All Hoses and pump bad. Smell awful and needs complete rebuild - Complete asym in right storage well - Replace fuel pumps, Filter, Accumulator is not available currently - Fits Early Euro 928 per the bosch number. Flushed accumulator might have effect on warm restart - Had to convert banjo attachment of lines - Remade all fuel lines - Ran all new hoses from tank to fuel pumps - Filled Tank - checked for leaks - ran fuel pumps and flushed lines from rear to front of car. Hooked up line to fuel dist. Fuel systm ready to go.	6.5	168.00	1,092.00
Parts	924 SSF Dansk Classic Fuel Pump 91160810204 list \$590.37	2	168.39	336.78T
Parts	924 SSF Fuel Pump Cap Nut 1239900053	2	9.53	19.06T

		Subtotal
		Sales Tax (0.0%)
		Total
		Payments/Credits
		Balance Due



Savannah, GA 31405

(912) 417-4353

Invoice

Date	Invoice #
9/18/2026	JF9751

Name / Address
HAGERTY Attn: Accounts Payable PO BOX 87 Traverse City, MI 49685 Marvin Waters II-Hagerty Marketplace

Vehicle Info
1979 Porsche 924 Turbo Rally Car 93A0190001

P.O. No.	Tech	Tech 2
	JOHN	

Item	Description	Qty	Rate	Total
Parts	SSF Fuel Hose 21340800 9.5mm ID X 15.5mm OD Smooth High Press	1	12.12	12.12T
Parts	SSF Fuel Hose 21340600 7.5mm ID 13.5mm OD Smooth High Press	2	14.22	28.44T
Shop Supplies	Shop Supplies - HIGH Press Crimp Clamps	1	35.00	35.00
Fuel Charges	Fuel Charges	1	30.00	30.00
Repair Labor	BATTERY AND FIRST START Cleaned all engine and body grounds in engine bay and at battery - Clean all power supply connections - Install New Battery - Crank engine to build oil pressure - Activate fuel system and bleed injections - Crank car and it started right up - Ran very very well.	2	168.00	336.00
Parts	924 SS Premium Flooded Battery 47PRM List \$322.00	1	169.18	169.18T
Repair Labor	IGNITION LOCK Remove Lock asym from steering column - Drill out Ignition Lock and install new ignition lock and tumbler - Reinstall lock asym and put column back together.	3	168.00	504.00
Parts	Lock Cylinder with Key LC14600 Ignition	1	28.64	28.64T
	READY TO GO BACK TO HAGERTY COMPLETE TICKET			

		Subtotal
		Sales Tax (0.0%)
		Total
		Payments/Credits
		Balance Due



Savannah, GA 31405

(912) 417-4353

Invoice

Date	Invoice #
9/18/2026	JF9751

Name / Address
HAGERTY Attn: Accounts Payable PO BOX 87 Traverse City, MI 49685 Marvin Waters II-Hagerty Marketplace

Vehicle Info
1979 Porsche 924 Turbo Rally Car 93A0190001

P.O. No.	Tech	Tech 2
	JOHN	

Item	Description	Qty	Rate	Total
	EMAIL SENT 09/18/26			

		Subtotal	\$8,778.34
		Sales Tax (0.0%)	\$0.00
		Total	\$8,778.34
		Payments/Credits	-\$8,778.34
		Balance Due	\$0.00