

FLR-001452 CT 120080104 0768
9-NORMAL, NA, 101452, 7M18, 000006266 BLEND

CMC U R BM
CERT CERT CERT TRD RAMP BUMP CAMP BOOK AFV HG

1ZVHT82H7 85164031 NA



www.fordvehicles.com

VEHICLE DESCRIPTION

MUSTANG

2008 GT COUPE PREMIUM
4-PASSENGER SPORTS CAR
4.6L 3V OHC V8 ENGINE
5-SPEED MANUAL TRANSMISSION

EXTERIOR
HIGHLAND GREEN CLEARCOAT
INTERIOR
DARK CHARCOAL LEATHER

85 164031

PRICE INFORMATION

Manufacturer's
Suggested Retail Price

STANDARD VEHICLE PRICE \$27,020.00

INCLUDED ON THIS VEHICLE

ORDER CODE 140A-PREM GT COUPE
•GT REAR DECKLID SPOILER
•AM/FM STEREO/6-CD IN DASH/MP3
•17" PREMIUM PAINTED CAST ALUM
•SHAKER 500 AUDIO SYSTEM
•ANTI-LOCK BRAKES
•POWER 6-WAY DRIVER'S SEAT

OPTIONAL EQUIPMENT

235/50/ZR18 TIRE	NO CHARGE
GUN METAL OVER ALUMINUM PANEL	
REAR SPOILER DELETE	NO CHARGE
ACTIVE ANTI-THEFT SYSTEM	325.00
WHEEL LOCKING KIT	50.00
MUSTANG VPC SHIP THRU	NO CHARGE
50 STATE EMISSIONS	NO CHARGE
SIRIUS SAT RADIO W/6 MOS SVC	195.00
HID HEADLAMPS	525.00
BULLITT PACKAGE	3,310.00
•BULLITT INTERIOR PACKAGE	
•3.73 RATIO LIMITED SLIP AXLE	
•18" BULLITT WHEEL	
•PACKED EXHAUST TIPS	
WTHR FLR MTS *DLR-INSTLD-ACC	75.00
PONY CENTER CAP	
AMBIENT LIGHTING	295.00

TOTAL VEHICLE & OPTIONS 31,795.00
DESTINATION & DELIVERY 745.00

TOTAL MSRP \$32,540.00

GOVERNMENT SAFETY RATINGS

Frontal Crash Driver Passenger ★★★★★★
★★★★★

Star ratings based on the risk of injury in a frontal impact.
Frontal ratings should ONLY be compared to other vehicles of similar size and weight.

Side Crash Front seat ★★★★★★
Rear seat ★★★★★

Star ratings based on the risk of injury in a side impact.

Rollover ★★★★★★
Star ratings based on the risk of rollover in a single vehicle crash.

Star ratings range from 1 to 5 stars (★★★★★), with 5 being the highest.
Source: National Highway Traffic Safety Administration (NHTSA).

www.safercar.gov or call 1-888-327-4236

STANDARD EQUIPMENT INCLUDED AT NO EXTRA CHARGE

EXTERIOR

- 17" PREMIUM PAINTED CAST ALUMINUM WHEELS
- P235/55ZR 17 Z-TIRES
- REAR DECKLID SPOILER
- FRONT FOG LAMPS
- STAINLESS STEEL DUAL EXH
- DUAL POWER MIRRORS
- VARIABLE INTERVAL WIPERS
- REAR WINDOW DEFROSTER

INTERIOR

- SHAKER 500 AUDIO SYSTEM AM/FM W/ CDX6 & MP3
- AUXILIARY AUDIO INPUT JACK
- AIR CONDITIONING
- LEATHER TRIM SPORT SEATS
- POWER 6-WAY DRIVERS SEAT
- SPLIT FOLD REAR SEAT
- CENTER CONSOLE W/ARMREST
- SPEED CONTROL/TILT WHEEL

- POWER DOOR LOCKS & WINDOWS
- DUAL VANITY MIRRORS

FUNCTIONAL

- BRAKES, POWER 4-WHEEL DISC
- POWER RACK PINION STEERING
- POWER POINTS (2)

SAFETY/SECURITY

- AIR BAGS, DRIV/FRONT PASS
- SIDE-MOUNTED AIRBAGS
- DRIVER & FRONT PASS SEATS
- ABS/TRACTION CONTROL
- FRONT/REAR OUTBOARD THREE POINT SHOULDER/LAP BELTS
- SECURILOCK
- REMOTE KEYLESS ENTRY

WARRANTY

- 3YR/36000 BUMPER TO BUMPER
- 5YR/60,000 POWERTRAIN
- 5YR/60,000 ROADSIDE ASSIST

EPA Fuel Economy Estimates

These estimates reflect new EPA methods beginning with 2008 models.

CITY MPG

15

Expected range
for most drivers
12 to 18 MPG

HIGHWAY MPG

23

Expected range
for most drivers
19 to 27 MPG

Estimated
Annual Fuel Cost

\$2,335

based on 15,000 miles
at \$2.80 per gallon

Combined Fuel Economy

This Vehicle

18

12 32

All Subcompacts

Your actual
mileage will vary
depending on how you
drive and maintain
your vehicle.

See the FREE Fuel Economy Guide at dealers or www.fueleconomy.gov

SOLD TO	ONE	DEALER NO.	METHOD OF TRANSP. CONVOY
	CM5P		ITEM #: 13-B001 O/T 1
SHIP TO (IF OTHER THAN SOLD TO)	TWO	1ZVHT82H785164031	
	CO41		
SHIP THROUGH	FINAL ASSEMBLY POINT	This label is affixed pursuant to the Federal Automobile Information Disclosure Act, General, Limited, and Title Fees. State and Local taxes are not included. Dealer installed options or accessories are not included unless listed above.	
	FLAT ROCK	7M181 N RA 2X 830 001452 12 18 07	



Ford Extended Service Plan is the only service contract backed by Ford and honored at all Ford and Lincoln Mercury Dealers. Ask your dealer for prices and additional details or see our website at www.ford-esp.com.



12/04/2011

1200801040768



HITACHI
Inspire the Next

© Hitachi Automotive Products (USA), Inc.
Los Angeles Plant
475 Alaska Avenue, Torrance, CA 90503
Tel: 310.212.0200 Fax: 310.212.0222
URL: <http://www.hitachi-hap-la.com>

KEEP YOUR RECEIPT!

TOKICO's warranty is limited to the original purchaser. Processing any warranty claim requires a copy of the original invoice and/or your warranty card that will be on file after mailing back. Please see warranty card for more specifics of coverage and claim procedures.

INSTALLATION NOTES:

Removal and installation of complete struts / shocks are best done by professional technicians. When performing installation please follow according to factory manual. Many TOKICO shocks come with dust covers, while others are designed to re-use the original equipment dust cover. Failure to use dust covers where called for could cause premature failure and void the warranty.

When removing the shocks, be certain that any mounting hardware, which must be re-used, is in good condition. If the piston rod is damaged as the result of using tools directly on the rod during installation or removal, warranty will be denied. Stem mount bushings should not be over tightened as this can cause bushing failure or top stem snapping off.

LOWERING CAUTIONS:

If you are lowering your vehicle or installing shocks on a lowered vehicle, please read the following recommendations:

1. Do not remove or operate your vehicle without bumpstops. If you need extra suspension travel, please shorten your bumpstops. A good guideline is 1/3" or 1/2" (maximum) of the bumpstop length.
2. Do not lower your vehicle too far. It will give you a harsh ride and can damage shocks and other suspension parts. It can also make alignment difficult to impossible.
3. Avoid lowering in areas where severe rough roads are common.

YOUR TOKICO WARRANTY WILL BE VOID IF:

1. You lower your vehicle too far (most cars can handle 1" to 1 3/4" maximum; some trucks can be lowered over 4" depending upon method).
2. You modify the shock or strut (an example would be aftermarket adjustable spring seats and collars).

*PLEASE SEE TOKICO WARRANTY CARD FOR MORE DETAIL.

HP
SERIES

illumina
Adjustable-5

TREK MASTER R/T

illumina
Adjustable-5



HITACHI
Inspire the Next

© Hitachi Automotive Products (USA), Inc.
Los Angeles Plant
475 Alaska Avenue, Torrance, CA 90503
Tel: 310.212.0200 Fax: 310.212.0222
URL: <http://www.hitachi-hap-la.com>

INSTALLING THE D-SPEC by TOKICO

Parts list

Front shocks/struts - 2
Front piston rod (shaft) top nuts - 2

Adjuster tool - 1



Rear shocks/struts - 2
Rear piston rod (shaft) nuts - 2

Protection caps - 4



Users manual - 1

Shocks and struts should be removed/installed according to guidelines in the car's factory manual except for torque settings for the piston rod top nut.

CAUTION - The D-Spec adjustable shock/strut uses a hollow piston rod for the adjusting rod. As a result impact wrenches should never be used on the piston rod top nut. Torque settings for the D-Spec shock and strut piston rod top nut are as follows:

Shock absorbers (12mm piston rod) 25-32 lb/ft.

Struts (14mm piston rod) 38-49 lb/ft.

Using an impact wrench or too much torque can break the top of the piston rod.

ADJUSTMENT - The D-Spec units come from the factory at or near the Firm or Hard setting. Double-check the settings front and rear by turning the adjuster clockwise until it is snug. Then turn the adjuster 5 complete revolutions in a counter clockwise direction. This is a good starting point.



CAUTION - Because of the wide adjustment range, experimenting with various adjustments should only be done after reading the D-Spec users manual. The manual explains how various suspension components work together and the possible effects of various D-Spec adjustments.

INSTALLERS - Please install protection caps to keep dirt and debris out of the adjuster hole. Also please be certain that the D-Spec users manual is given to the vehicle owner and driver with the caution to read the manual.

For technical questions please call - (800) 548-2549

HP
SERIES

illumina
Adjustable-5

D SPEC

TREK MASTER R/T




illumina
Adjustable-5

SB444

CARE AND USE INSTRUCTIONS

Your new custom cover is made using a non-woven, ultrasonically laminated 4-layer composite fabric, that helps protect the vehicles exterior and interior from UVR exposure and exterior from dust and environmental contaminants.

The non-woven inner layer is soft against the paint finish.



HOW TO INSTALL YOUR SB444 COVER

The front of the cover is marked with a pattern number and/or logo and the word "front" to help in positioning the cover on the vehicle.

1. Place the folded cover on the vehicle in the center and unfold towards the front and rear of the vehicle.

2. Begin to unfold the cover towards the sides of the vehicle.

NOTE: If your cover is equipped with mirror pockets (most late-model custom-fit patterns only), it is very important that the mirror pockets be placed over the side mirrors before the ends of the cover are stretched over the front and rear of the vehicle.

3. Complete the installation by covering the front and rear of the vehicle.

NOTE: The elastic that is sewn in to the front and rear of the cover will keep it in place under normal conditions. A tie-down rope is included for temporarily securing the cover. Additional accessories for securing your cover are available for purchase.

www.covercraft.com

sales@covercraft.com

HOW TO CLEAN YOUR SB444 COVER WITH A WASHING MACHINE

1. Place the cover in a large, commercial washing machine without an agitator.
2. Fill the tub with WARM water.
3. Pour in 1/4 cup of Simple Green All-Purpose Cleaner.
4. Use the GENTLE cycle, if available.
5. Rinse the cover twice (2x) to remove all of the cleaner.
6. Air dry.

HOW TO CLEAN YOUR SB444 COVER ON THE VEHICLE

1. Install your cover inside-out on the vehicle.
2. Mix one ounce (1oz) of Simple Green All-Purpose Cleaner per quart of WARM water.
3. Spray or sponge the mixture onto cover.
4. Rinse with plain water until there are no suds on the cover.
5. Air dry.

Car cover fabric performance can be severely affected by contaminants (dirt, dust, grease, etc.) that build up on and within the material. It can cause the windshield and paint to become dirty and "fogged" as well as create "wicking"; a process where the contaminants actually pull water through the fabric. This may nullify any water resistant properties the fabric may have had. Cleaning your cover will help to keep your vehicle clean and increase the service life of the cover.

Simple Green All-Purpose Cleaner is available in most automotive and home-improvement stores. If you have questions about Simple Green, call 1-800-228-0709 or visit www.simplegreen.com for more information.



LIMITED ONE (1) YEAR WARRANTY

SB444 fabric covers are warranted for one (1) year from the date of purchase, to the original purchaser. Be sure to save your original purchase receipt. Warranty coverage protects against defects in material and workmanship, as well as the fabric becoming unserviceable during normal use. After factory inspection, we will repair or replace the cover or specific panels judged to be unusable. This Limited Warranty does not cover fading, which occurs naturally on all products used outdoors.

To process a warranty claim, contact:

CAR COVER DIVISION
100 Enterprise Blvd.
Pauls Valley, OK 73075
405-238-9651
M-F 8am to 4pm CST
sales@covercraft.com

Be sure to review the CAUTIONS AND WARNINGS section of this manual for important information regarding the proper use of your cover.

www.covercraft.com

sales@covercraft.com



Salesperson Delivery Checklist

VEHICLE IDENTIFICATION NUMBER (VIN)

Congratulations on your purchase of a Ford Quality Checked Pre-owned vehicle! Our dealership's Quality Commitment is a promise to do our best to satisfy your total transportation needs. As part of our commitment, we certify that all the inspection items on the Vehicle Inspection Checklist have been checked to help ensure your satisfaction with your Pre-owned vehicle.

Quality Vehicle Check

- ☒ 115-point inspection performed

Delivery Document Review

- ☒ Explanation of delivery process
☒ Title document
☒ Registration work progress/procedures
☒ Financing documents
☒ Optional Extended Service Plan (if applicable)
☒ 24-Hour Roadside Assistance benefits
☒ Owner Guide
☒ Delivered copy of vehicle history summary report
☒ Delivered copy of 115-Point Vehicle Inspection Checklist
☒ Limited Warranty Statement

Service Department Introduction

- ☒ Explanation of how to obtain service
☒ Service department tour
☒ Introduction to service department personnel
☒ Explanation of scheduled maintenance requirements
☒ Set the first routine scheduled maintenance appointment:

Appointment date and time: _____

Follow-Up

- ☒ Desired date and time of call: _____
☒ Phone number: _____
☒ E-mail address: _____
☒ Preference of e-mail over phone call

Vehicle Presentation Operating Features (as applicable)

Some operating features are optional and may not be included with your Ford Quality Checked Pre-owned vehicle.

- ☒ Keyless entry/key fobs
☒ Seat Adjustment, memory seat and 3rd row, if applicable
☒ Flexible seating/storage positions
☒ Driver side or driver-and passenger-side air bag
☒ Supplemental Restraint System (SRS)/side air bags/side air curtain
☒ Safety belts (adjustable D-rings)
☒ Child seat anchors
☒ Operation of mirrors
☒ Visors and front seat SRS warning for children
☒ Door locks/windows (window lock switch/flip-out windows/power locks/childproof rear door lock)
☒ Internal hood, trunk and fuel-filler door release/operation
☒ Audio system, set stations; clock operation, set time, antenna location/operation

- ☒ Temperature, compass, statistics displays
☒ Navigation system
☒ Security system operation
☒ Proper tightening of gas cap to seal
☒ Tire pressure review
☒ Spare tire/jack location and operation
☒ Fuel inertia switch
☒ Adjustable steering wheel and pedal operations
☒ Vehicle starting procedures (starter interlock)
☒ Brake/shift interlock (automatic transmission)
☒ Anti-lock Brake System (ABS)/Traction Control System
☒ Operation of headlights, high beam, flasher, parking, interior and fog lights
☒ Climate control and front/rear defroster operation
☒ Wiper and washer operation
☒ Rear-window defroster operation
☒ Speed control operation
☒ Liftgate operation
☒ Explained any other operating features that are unique to this vehicle

Orientation Drive

- ☒ Customer orientation drive
☒ Full tank of fuel provided
☒ Two sets of keys provided

Checklist Review Customer Sign-Off

- ☒ I have personally explained the Certified Powertrain Limited Warranty coverage. Specific warranty coverage provisions are included in the Limited Warranty Statement.

DEALER/GENERAL MANAGER SIGNATURE _____ DATE _____
SALES/DELIVERY PERSON SIGNATURE _____ DATE _____

- ☒ I acknowledge that all items checked on this delivery form have been reviewed with me by my delivery person to my satisfaction.

A warranty card will be mailed to you within 15 business days after the date of the sale.

Original: Owner Copy: Dealer



Prior to delivery of your vehicle, the following checks and inspections were performed. Any item(s) that did not pass our 115-point inspection have been replaced or repaired.

VEHICLE HISTORY

- 1 VINs match on vehicle and paperwork
2 Recalls (OASIS) and scheduled maintenance performed; Vehicle History Report performed

ROAD TEST

ENGINE

- 3 Starts (cold/hot)
4 Idles
5 Accelerates & cruises, smoothly
6 Engine noise normal (cold/hot and high/low speeds)

TRANSMISSION/TRANSAXLE

- 7 Auto/manual operation/shifts/noise normal (cold/hot)
8 Shift interlock operates
9 Clutch operates (smoothly and with proper adjustment)
10 Drive axle/transfer case operation, noise normal

STEERING & SUSPENSION

- 11 Steers normal (proper response, centering, free play)
12 Struts, shocks operate

BRAKES/ABS

- 13 Operate (pedal effort/height appropriate, no pulling, pulsating) Note: ABS pulsates w/hard braking

ACCESSORIES - Operate

- 14 All gauges, speedometer, tachometer, odometer
15 Speed control

VEHICLE EXTERIOR

- 16 No evidence of flood, hail, fire or any major damage

BODY PANELS & BUMPERS

- 17 No visible damage or misalignment; paint not mismatched or poor

DOORS, HOOD, DECK LID, TAILGATE

- 18 Not visibly damaged; paint not mismatched or poor quality
19 Hood release, prop rod/gas struts operate

GRILL, TRIM & ROOF RACK

- 20 Components free from visible damage; attached

GLASS, OUTSIDE MIRRORS, WIPERS

- 21 Windshield free from visible cracks, visible pits, wiper marks
22 Side/rear windows free from visible cracks, visible pits
23 Mirrors not cracked, visibly damaged
24 Replace wiper blades

EXTERIOR LIGHTS - Operate, lenses not visibly damaged

- 25 Headlights aligned, auto on/off
26 Fog, driving lights
27 Parking lights
28 Hazard lights
29 Turn signal, side marker lights
30 Brake lights, high-mount brake light
31 License plate lights
32 Reverse lights

VEHICLE EXTERIOR

AIR BAG & SAFETY BELTS

- 33 Air bags intact, no codes, dash light works
34 Safety belts operate, free from cuts or wear

Customer 115-Point Vehicle Inspection Checklist

AUDIO & ALARM SYSTEMS - Operate

- 35 Radio, cassette, CD, speakers, antenna
36 Alarm/theft deterrent system

HEAT/VENT/AC/DEFOG/DEFROST - Operate

- 37 Air conditioning and heating systems
38 Defog/defrost (front, rear, outside mirrors)

INTERIOR AMENITIES - Operate, no damage

- 39 Tilt/telescopic steering wheel, column lock
40 Steering wheel controls
41 Horn
42 Wipers & washers operate in all modes, no streaks
43 Lights (instrument panel, courtesy, dome, map)
44 Mirror controls (rear view, side mirrors)
45 Lighter, power outlet(s)
46 Ashtrays
47 Glove box, glove box light
48 Sun visors, vanity mirror & light

CARPET, TRIM, MATS - Clean, no stains or damage

- 49 Carpet (check for rust under it due to flood damage)
50 Floor mats
51 Door trim, panels attached
52 Fold-down latches work
53 Headliner

SEATS

- 54 Upholstery clean; not stained, worn, cut, cracked
55 Seats & head restraints operate
56 Integrated child safety seats operate
57 Heated seat operates

MOONROOF, CONVERTIBLE TOP

- 58 Moonroof operates in all modes
59 Convertible top & cover operate; not damaged

WINDOWS, DOOR LOCKS - Operate as designed

- 60 Door locks & handles (manual, power modes)
61 Window controls (manual, power modes)
62 Remote deklid & fuel door releases

LUGGAGE COMPARTMENT

- 63 Carpet, trim, cargo net; clean, not damaged
64 Luggage compartment light works
65 Jack, spare tire tools operate
66 Weatherstripping intact, not leaking
67 Spare tire correct size/type, at least 50% tread remaining, no sidewall damage, air pressure correct

UNDERHOOD

ENGINE CONTROL SYSTEM

- 68 No active or stored codes (perform system check)
69 Emission controls work

FLUIDS - Check condition, level; add or change as required

- 70 Engine oil & filter (change)
71 Coolant (freeze point)
72 Brake fluid
73 Automatic transmission/transaxle fluid
74 Power steering fluid
75 Washer fluid

ENGINE

- 76 Fluid leaks (record what is leaking, where)
77 Hoses, lines: coolant, fuel, brake, steering, vacuum, A/C (check condition, leaks)
78 Belts (check wear, cracks, fraying, proper adjustment)
79 Power steering pump (check for leaks, noise)
80 Master cylinder and booster (check for leaks)
81 Engine mounts not broken/separated
82 Cylinder compression/power balance readings (check if necessary)

COOLING SYSTEM

- 83 Radiator (perform pressure check, inspect for leaks, condition of tubes, fins)
84 Water pump (free from leaks or unusual noise)
85 Coolant recovery tank level sensor works

FUEL SYSTEM

- 86 Fuel pump pressure reading correct
87 Fuel filter (replace per Maintenance Schedule)
88 Air filter (replace per Maintenance Schedule)

ELECTRICAL SYSTEM

- 89 Battery type, condition, fluid level, load test correct
90 Alternator output correct
91 Ignition system works
92 Starter operates

UNDERBODY

FRAME

- 93 No visible damage, signs of past repairs, no visible abnormal tire wear
94 Fuel lines, fuel tank, hoses and couplings not leaking

EXHAUST SYSTEM

- 95 Entire exhaust system not damaged or leaking

TRANSMISSION, TRANSAXLE, DIFFERENTIAL, TRANSFER CASE

- 96 Automatic transmission/transaxle not leaking
97 Manual trans., differential, transfer case, no leaks; check fluid levels; fill/change as required
98 Universal joints, CV joints, boots not damaged, leaking, or excess wear/looseness

TIRES AND WHEELS

- 99 All tires & wheels match, correct size
100 Tread depth, at least 50% remaining
101 Normal tire wear, no alignment or sidewall problems
102 Pressures are correct
103 Wheels/finish free from damage, run-out normal

SUSPENSION/STEERING

- 104 Chassis lubricated (per Maintenance Schedule)
105 Rack & pinion, linkage, boots not visibly damaged, leaking
106 Control arms, ball joints, bushings not visibly damaged, worn
107 Sway bars, links, bushings operate to factory specs
108 Springs have proper ride height (not sagged)
109 Struts, shocks not leaking
110 Wheel alignment correct (check if necessary)

BRAKES


- 111 Calipers, cylinders operate with no leaks
112 Pads, shoes, at least 50% thickness remaining
113 Rotors, drums at least 50% of thickness spec; not scored; run-out within factory specs
114 Brake lines, hoses, fittings not worn or leaking
115 Parking brake operates/adjusted

1ZVHT82H785164031
VIN

7-22-10
TECHNICIAN SIGNATURE _____ DATE
7-22-10
SERVICE MANAGER SIGNATURE _____ DATE
7/22/10
CERTIFIED PRE-OWNED VEHICLE MANAGER _____ DATE

09002 F207 10/04 014

Original: Owner Copy: Dealer



CUSTOMER COPY

**DOWLING
FORD**1011 SOUTH MAIN STREET
CHESHIRE CT 06410
Phone: 203-272-2772

07/14/2011 09:32:58

Customer No.	164031	License #	429YEZ	Stock #		Dealer #	03658	Invoice Date	07/14/2011	Invoice #	67328
		Mileage In	7811	Mileage Out	7811	Lot #/Hat #		Color	GREEN	Delivery Date	//
		Year/Make/Model	2008 FORD Mustang			Prod Date	//	R.O. Date	07/14/2011		
		Vehicle ID #	1ZVHT82H785164031			Tech #		P.O. #			
		Override		Service Write Up	JACKIE FROST	S.W. INT. EST.	0.00				
Extended Warranty Co.		Policy #		Deductible		Auth. #		Adjustor			
		Business Phone	Service Writer Delivery Signature								

Type: C JOB #1 Labor Rate: C 80.00 PO:
Complaint: CUSTOMER REQUESTS CHANGE OIL AND FILTER AND INSPECT FLUIDS,BELTS AND HOSES AND WIPERS,LIGHTS,RESET MAINTANENCE REMINDER LIGHT IF VEHICLE EQUIPPED.
Correction: CHANGED OIL AND FILTER. INSPECT ALL HOSES, BELTS AND FILTERS. TOP OFF FLUIDS. SET TIRE PRESSURE.
Part: FL 820 S FILTER ASY - OIL Qty: 1 \$6.50
Part: XO 5W20 QFS OIL - ENGINE Qty: 6 \$43.50
Part: SOLVENT SOLVENT Qty: 1 \$1.44
JOB TOTALS Labor:\$15.00 Parts:\$51.44 Tax:\$4.22 TOTAL:\$70.66

Type: C JOB #2 Labor Rate: C 80.00 PO:
Complaint: customer states that there is a buzz when going engine is at 3500rpm's
Correction: customer had tech adjust heat shield on exhaust,did not road test to confirm repair.customer to drive and let us know
Misc: ENVIRONMENTAL FEE \$1.25
Tax:\$0.08 Misc:\$1.25 TOTAL:\$1.33
JOB TOTALS

Type: W JOB #3 Labor Rate: W 87.01 PO:
Complaint: perform campaign 08c02
Correction: reprogram RSM to latest calibration
TOTAL:

CUSTOMER TOTALS: \$71.99
Labor:\$15.00 Parts:\$51.44 Sublet:\$0.00 Misc:\$1.25 Tax:\$4.30

Customer Signature X _____

Extended Warranty Pay

All labor charges are billed on
flat rate hours unless otherwise
noted.Total Customer Pay
\$71.99**Bob Thomas**

2215 dixwell ave./hamden/connecticut 06514

SEE REVERSE
SIDE FOR WARRANTY INFORMATION
ALL PARTS NEW EXCEPT AS NOTED
P & A CODE 03691Service Dept. Hours Monday - Friday 8:00 AM - 4:30 PM (203) 281-7501
Body Repair Shop Hours Monday - Friday 8:00 AM - 4:30 PM (203) 281-3532

CUSTOMER NO.	36102	ADVISOR	EDWARD LIEBEL	TAG NO.	918	INVOICE DATE	03/19/12	INVOICE NO.	FOCS126441
		LABOR RATE	105.00	LICENSE NO.		MILEAGE	9,020	STOCK NO.	P6620
		YEAR / MAKE / MODEL	08/FORD/MUSTANG/2DR CPE GT			DELIVERY DATE	07/23/10	DELIVERY MILES	3,480
		VEHICLE I.D. NO.	1 Z V H T 8 2 H 7 8 5 1 6 4 0 3 1			SELLING DEALER NO.		PRODUCTION DATE	
		R.T.E. NO.		P.O. NO.		R.O. DATE	03/19/12		
		COMMENTS							

MO: 9020

LABOR & PARTS
J# 1 05FOZ-07 SUSPENSION/RIDE HOURS: 6.00 TECH(S):927 570.00
REPLACE FRONT AND REAR SHOCKS
AND SPRINGS ALIGNMENT,HOOD BOUNCES
REPLACE OWNERS FRONT AND REAR STRUTS,SHOCKS SPRINGS
FRONT END ALIGNMENT

JOB # 1 TOTAL LABOR & PARTS 570.00

J# 2+00FOZ99P MULTIPT HOURS: TECH(S):927 0.00
PERFORM MULTI POINT INSPECTION
ADJUST HOOD STOPS

JOB # 2 TOTAL LABOR & PARTS 0.00

J# 3+00FOZGBATT BATTERY GREEN HOURS: TECH(S):927 0.00
PERFORMED BATTERY TEST, TESTED GOOD

JOB # 3 TOTAL LABOR & PARTS 0.00

J# 4+00FOZGTIRE TIRES GREEN HOURS: TECH(S):927 0.00
TIRES 7/32 AND GREATER

JOB # 4 TOTAL LABOR & PARTS 0.00

MISC-----CODE-----DESCRIPTION-----CONTROL NO-----
JOB # A SS SUNDRIES
TOTAL : MISC 34.20

ESTIMATE-----
CUSTOMER HEREBY ACKNOWLEDGES RECEIVING
ORIGINAL ESTIMATE OF \$700.00 (+TAX)
TOTALS-----

TOTAL LABOR.... 570.00
TOTAL PARTS.... 0.00
TOTAL SUBLET.... 0.00
TOTAL G.O.G.... 0.00
TOTAL MISC CHG. 34.20
TOTAL MISC DISC 0.00
TOTAL TAX..... 38.37

TOTAL INVOICE \$ 642.57

CUSTOMER SIGNATURE _____

Bob Thomas

2215 dixwell ave./hamden/connecticut 06514



SEE REVERSE
SIDE FOR WARRANTY INFORMATION
ALL PARTS NEW EXCEPT AS NOTED
P & A CODE 03691

Service Dept. Hours Monday - Friday 8:00 AM - 4:30 PM (203) 281-7501
Body Repair Shop Hours Monday - Friday 8:00 AM - 4:30 PM (203) 281-3532

CELL: 860-573-5726

CUSTOMER NO.	36102	ADVISOR	MIKE	TAG NO.	981	INVOICE DATE	03/01/13	INVOICE NO.	FOCS134785
		LABOR RATE	105.00	LICENSE NO.		MILEAGE	11,807	COLOR	GREEN/
		YEAR / MAKE / MODEL	08/FORD/MUSTANG/2DR CPE GT			DELIVERY DATE	07/23/10	DELIVERY MILES	3,480
		VEHICLE I.D. NO.	1 Z V H T 8 2 H 7 8 5 1 6 4 0 3 1			SELLING DEALER NO.		PRODUCTION DATE	
		F.T.E. NO.		P.O. NO.		R.O. DATE	03/01/13		
COMMENTS									MO: 11807

TOTALS

TOTAL LABOR....	12.24
TOTAL PARTS....	59.95
TOTAL SUBLET....	0.00
TOTAL G.O.G....	0.00
TOTAL MISC CHG.	0.73
TOTAL MISC DISC	0.00
TOTAL TAX.....	4.63
TOTAL INVOICE \$	77.55

CUSTOMER SIGNATURE

FA
MAR 1 2013
BY: _____

Bob Thomas

2215 dixwell ave./hamden/connecticut 06514



SEE REVERSE
SIDE FOR WARRANTY INFORMATION
ALL PARTS NEW EXCEPT AS NOTED
P & A CODE 03691

Service Dept. Hours Monday - Friday 8:00 AM - 4:30 PM (203) 281-7501
Body Repair Shop Hours Monday - Friday 8:00 AM - 4:30 PM (203) 281-3532

CELL: 860-573-5726

CUSTOMER NO.	36102	ADVISOR	MIKE	TAG NO.	981	INVOICE DATE	03/01/13	INVOICE NO.	FOCS134785
		LABOR RATE	105.00	LICENSE NO.		MILEAGE	11,807	COLOR	GREEN/
		YEAR / MAKE / MODEL	08/FORD/MUSTANG/2DR CPE GT			DELIVERY DATE	07/23/10	DELIVERY MILES	3,480
		VEHICLE I.D. NO.	1 Z V H T 8 2 H 7 8 5 1 6 4 0 3 1			SELLING DEALER NO.		PRODUCTION DATE	
		F.T.E. NO.		P.O. NO.		R.O. DATE	03/01/13		
COMMENTS									MO: 11807

J# 1 00F0Z LUBE OIL FILTER HOURS: TECH(S):928 12.24
CUSTOMER REQUESTS: LUBE OIL & FILTER,CHECK & TOP
ALL FLUID LEVELS.
USE FULL SYN. OIL
CHANGE ENGINE OIL & FILTER
CHECK ALL FLUID LEVELS , FILL WINDSHIELD WASHER RESIVIOR..

PARTS	QTY	FP-NUMBER	DESCRIPTION	LIST PRICE	UNIT PRICE	PRICE
JOB # 1	1	FL-820-S	FILTER 966738	8.61	7.15	7.15
JOB # 1	6	XO-5W20-QFS	OIL - E 846098	8.80	8.80	52.80
JOB # 1 TOTAL PARTS						59.95
JOB # 1 TOTAL LABOR & PARTS						72.19

J# 2 00F0Z99P MULTIPT HOURS: 0.00 TECH(S):928 0.00
PERFORM MULTI POINT INSPECTION
SET TIRES AT 35

PARTS	QTY	FP-NUMBER	DESCRIPTION	LIST PRICE	UNIT PRICE	PRICE
JOB # 2 TOTAL PARTS						0.00
JOB # 2 TOTAL LABOR & PARTS						0.00

J# 3+00F0ZGBATT BATTERY GREEN HOURS: TECH(S):928 0.00
PERFORMED BATTERY TEST, TESTED GOOD

PARTS	QTY	FP-NUMBER	DESCRIPTION	LIST PRICE	UNIT PRICE	PRICE
JOB # 3 TOTAL PARTS						0.00
JOB # 3 TOTAL LABOR & PARTS						0.00

J# 4+00F0ZYTIRES TIRES YELLOW HOURS: TECH(S):928 0.00
TIRES 4/32 TO 6/32

PARTS	QTY	FP-NUMBER	DESCRIPTION	LIST PRICE	UNIT PRICE	PRICE
JOB # 4 TOTAL PARTS						0.00
JOB # 4 TOTAL LABOR & PARTS						0.00

J# 5+00F0ZGBK BRAKES GREEN HOURS: TECH(S):928 0.00
OVER 5MM OR 7/32 (DISC) OR OVER 2MM OR 3/32 (DRUM)

PARTS	QTY	FP-NUMBER	DESCRIPTION	LIST PRICE	UNIT PRICE	PRICE
JOB # 5 TOTAL PARTS						0.00
JOB # 5 TOTAL LABOR & PARTS						0.00

MISC	CODE	DESCRIPTION	CONTROL NO
JOB # A	SS	SUNDRIES	
TOTAL - MISC			0.73

ESTIMATE
CUSTOMER HEREBY ACKNOWLEDGES RECEIVING
ORIGINAL ESTIMATE OF \$90.00 (+TAX)



CROWLEY FORD LINCOLN

225 New Britain Ave., Plainville CT 06062
Service: (860) 793-8886 Parts: (860) 793-8887
Body Shop: (860) 261-3041 Fax: (860) 747-6364
CrowleyAuto.com

Page
2

Year/Make/Model: 2008 Ford Mustang		A/R Number:	Inv. Num	615095
VIN: 1ZVHT82H7 85164031		Customer Number: 1606766	Printed: MAR 29 18 12:29 PM	
License Number:		PO Number:	Copy # 1	
Stock Number:		Auth Number:	Date Opened: 03/29/18	
Tag Number: 989		Service Writer: Eric Dionne	Date Notified: 03/29/18	
Mileage In: 27672		Estimate Amount: \$ 709.05	Date Delivered:	
Mileage Out: 27672		Terms & Conditions:	Date Complete: 03/29/18	
Type of Sale: Retail		Customer Signature		

Description	QtyOrd	Qty Del	Price	Ext Total	Grand Total
-------------	--------	---------	-------	-----------	-------------

4. Customer statement of problem

Customer States install BG MOA oil conditioner and BG CF5 fuel conditioner

BGBEST -

1 - Correction/Action Taken

Completed

997199 0.00 0.00

Part Number	Failed	Description	1	1	19.11	19.11
K110		MOA OIL ADDITIVE	1	1	20.37	20.37
K203		C5 FUEL TREATMENT				

Sub Total Parts 39.48
SubTotal Job # 4 39.48

5. Customer statement of problem

THROTTLE BORE SVC

1 - Cause/Action to Take

24 - DESLUDGE THROTTLE BORE

1 - Correction/Action Taken

COMPLETED

998627 5... 30.00

Part Number	Failed	Description	1	1	19.95	19.95
BG4068		THROTTLE BODY CLEAN				

Sub Total Parts 19.95
SubTotal Job # 5 49.95

6. Customer statement of problem

Customer States Replace Battery

BATT -

1 - Correction/Action Taken

Completed replacement of battery.

998627 2... 12.50

Part Number	Failed	Description	1	1	129.95	129.95
BXT96R590		BATTERY				

Sub Total Parts 129.95
SubTotal Job # 6 142.45



CROWLEY FORD LINCOLN

225 New Britain Ave., Plainville CT 06062
Service: (860) 793-8886 Parts: (860) 793-8887
Body Shop: (860) 261-3041 Fax: (860) 747-6364
CrowleyAuto.com

Page
3

Year/Make/Model: 2008 Ford Mustang		A/R Number:	Inv. Num	615095
VIN: 1ZVHT82H7 85164031		Customer Number: 1606766	Printed: MAR 29 18 12:29 PM	
License Number:		PO Number:	Copy # 1	
Stock Number:		Auth Number:	Date Opened: 03/29/18	
Tag Number: 989		Service Writer: Eric Dionne	Date Notified: 03/29/18	
Mileage In: 27672		Estimate Amount: \$ 709.05	Date Delivered:	
Mileage Out: 27672		Terms & Conditions:	Date Complete: 03/29/18	
Type of Sale: Retail		Customer Signature		

Description	QtyOrd	Qty Del	Price	Ext Total	Grand Total
-------------	--------	---------	-------	-----------	-------------

7. Customer statement of problem

BRAKE FLUID FLUSH

1 - Cause/Action to Take

09 - PERFORM BRAKE FLUID FLUSH SERVICE

1 - Correction/Action Taken

BRAKE SYSTEM FLUSH COMPLETED

998627 1... 72.00

Part Number	Failed	Description	1	1	32.99	32.99
85032		DOT 3 BG FLUID				

Sub Total Parts 32.99
SubTotal Job # 7 104.99

8. Customer statement of problem

POWER STEER FLUSH

11 -

1 - Correction/Action Taken

PERFORM POWER STEERING FLUSH SERVICE

998627 1... 60.00

Part Number	Failed	Description	1	1	59.95	59.95
K6700		POWER STEERING FLSH				

Sub Total Parts 59.95
SubTotal Job # 8 119.95

Miscellaneous Charges and Deductions For All Jobs

ANY WARRANTIES ON THE PRODUCTS SOLD HEREIN ARE THOSE OF THE MANUFACTURES OF THOSE PRODUCTS. THE DEALERSHIP HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EITHER EXPRESS OR IMPLIED, INCLUDING AND IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE REGARDING AND PRODUCTS OR SERVICES PROVIDED, UNLESS OTHERWISE INDICATED ON THE SERVICE REPAIR ORDER. THIS DEALERSHIP NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF SAID PRODUCTS OR SERVICES. THIS DISCLAIMER BY THE DEALERSHIP IN NOW WAY AFFECTS THE TERMS OR PERFORMANCE OF THE MANUFACTURERS WARRANTY.

YOUR SURVEY REPSONSE IS VERY IMPORTANT TO US. PLEASE COMPLETE AND RETURN THE SURVEYS. ANY QUESTIONS PLEASE CALL 860-793-8886

THANK YOU FOR CHOOSING
CROWLEY FORD LINCOLN!
Make your next appointment
online at:
www.crowley-ford.com

Total Labor	316.20
Total Parts	350.51
Total Sublet	0.00
Misc. Chrgs	0.00
Car Rental	0.00
Freight	0.00
Deductible	0.00
Special Tax	0.00
Haz Mat Chrg	0.00
Sales Tax	42.34
AMOUNT DUE	709.05



Ford Motor Company
Ford Customer Service Division
P.O. Box 1904
Dearborn, Michigan 48121

0014905B 0042
2008 Mustang
1ZVHT82H785164031

September 2010

John

Ford Motor Company would like to remind you that your 2008 Mustang has not had the following no charge recall completed.

You received this notice because our records, which are based primarily on state registration and title data, indicate that you are the current owner.

Recall Number and Description: 08C02 - Reprogram Restraint Control Module

What Are We Asking You To Do? Please contact your dealer to schedule an appointment to have this important service procedure completed. If you do not already have a servicing dealer, you can access <http://www.FordOwner.com> for dealer addresses, maps and driving instructions.

Service Assistance: The vehicle owner is responsible for having this service action performed. Ford Motor Company reserves the right to deny coverage for any vehicle damage that may result from failure to have this recall performed on a timely basis. Therefore, please have this recall performed as soon as possible.

If you have additional questions, please contact the Ford Motor Company Customer Relationship Center at 1-866-436-7332 and one of our representatives will be happy to assist you. For the hearing impaired call 1-800-232-5952 (TDD). Office Hours are Monday through Friday: 8:00AM - 5:00PM (Your Local Time).

If you wish to contact us through the Internet, our address is:
www.FordOwner.com.

If your authorized dealer has recently completed this recall repair, please disregard this reminder.

We apologize for any inconvenience this may cause and want to assure you that, with your assistance, we will correct this condition. Our commitment, together with your dealer, is to provide you with the highest level of service and support.

Thank you for your attention to this important matter.

Ford Customer Service Division



Drive one. LINCOLN

CROWLEY FORD LINCOLN

225 New Britain Ave., Plainville CT 06062
Service: (860) 793-8886 Parts: (860) 793-8887
Body Shop: (860) 261-3041 Fax: (860) 747-6364


CrowleyAuto.com

Page
1

A/R Number:	Inv. Num	615095
Customer Number: 1606766	Printed:	MAR 29 18 12:29 PM
PO Number:	Copy #	1
Auth Number:	Date Opened:	03/29/18
Service Writer: Eric Dionne	Date Notified:	03/29/18
Estimate Amount: \$ 709.05	Date Delivered:	
Terms & Conditions:	Date Complete:	03/29/18
Type of Sale: Retail		
Customer Signature		

Year/Make/Model: 2008 Ford Mustang
VIN: 1ZVHT82H7 85164031
License Number: Color:
Stock Number: Mileage In: 27672
Tag Number: 989 Mileage Out: 27672

Description	Qty	Ord	Qty Del	Price	Ext Total	Grand Total
1. Customer statement of problem						
Perform Oil Service						
***** Reset oil minder if so equipped *****						
Initials						
01 -						
1 - Correction/Action Taken						
Oil Service Completed	998627			2...		15.50
Part Number	Failed	Description				
XO5W20BSP		MOTORCRAFT	6	6	1.74	10.44
FL820S		FILTER ASY - OIL	1	1	4.00	4.00
Sub Total Parts						14.44
SubTotal Job # 1						29.94
2. Customer statement of problem						
INJECTOR CLEANING						
1 - Cause/Action to Take						
23 - PERFORM HIGH PRESSURE FUEL INJECTOR CLEANING						
SERVICE						
1 - Correction/Action Taken						
COMPLETED	998627			2...		126.20
Part Number	Failed	Description				
K21		INDUCTION	1	1	53.75	53.75
Sub Total Parts						53.75
SubTotal Job # 2						179.95
3. Customer statement of problem						
MULTI-POINT INSP.						
1 - Cause/Action to Take						
Q99P - PERFORM MULTI-POINT INSPECTION						
1 - Correction/Action Taken						
INSPECTION COMPLETED - PLEASE SEE INSPECTION REPORT	997199			0.00		0.00
Sub Total Parts						0.00
SubTotal Job # 3						0.00



CJ Pony Parts Inc.7461 Allentown Blvd
Harrisburg, PA 17112
(717) 657-8888**SALES ORDER**ORDER # **42743572**
ORDER DATE 01/19/2020
CUSTOMER # 1999570
SHIPPING VIA: **Best Way Ground -
Flat Fee Shipping**

W13158276

Order# 42743572

SHIP VIA: Best Way Ground - Flat Fee Shipping

PO # 2001858846



W13158276

O# 42743572

SHIP VIA: Best Way Ground - Flat Fee Shipping

PO #: 2001858846



PO #	Order No.	Entered By	Billing Terms					
2001858846	42743572	WEB	NET 0					
Qty Ordered	Qty Shipped	Stock #	UPC	Description	Unit Price	Ext. Price	Bin Location	
1	1	M9601B	756122100981	FRPP REPLACEMENT AIR FILTER REPLACEMEN	\$26.99	\$26.99	B71	B71D02
1	1	CAF1	800022P 1	2005-2014 CABIN AIR FILTER	\$11.99	\$11.99	E24	E24E05

Merchandise Charge: \$38.98
Tax Charge: \$2.86
Shipping Charge: 6.00
Invoice Amount: \$47.84
Amount Paid: \$47.84
Total Due: \$0.00RPM Loyalty Points Earned: 19
Total RPM Loyalty Points Balance: 19
*RPM Points expire 90 days from your shipment date.*Line Items: 2
Est Weight: 1.85**CRUTCHFIELD**1 Crutchfield Park
Charlottesville, Virginia 22911 -9097
www.crutchfield.com**A message from Bill Crutchfield**

Thank you for coming back to us to place another order — it's truly gratifying. It means we're earning your confidence and trust. I want you to know we don't take it for granted. Please let us know how we can help you enjoy your new gear.

Bill Crutchfield

CID: 20661138

Order number	Invoice number	Order date	Date processed	Shipping method	Your advisor
46918249	27918485	1/25/2020	1/26/2020	STANDARD	Conrad

Quantity ordered	Quantity backordered	Quantity shipped	Item number	Description	Unit price	Amount
1	0	1	264PASCON	ReadyHarness Service	24.99	24.99
1	0	1	0000190011	FORD MUSTANG 05-09 MS		EMAILED
1	0	1	000SXMV20	SiriusXM SXV300 MIR		ATTACHED
1	0	1	120995807	Ford/Lincoln/Mercury Kit 2004-	7.85	7.85
1	0	1	220SXV300	SiriusXM SXV300V1	69.99	69.99
1	0	1	127C2RFRD1	PAC C2R-FRD1	41.89	41.89
1	0	1	113DMX906S	Kenwood Excelon DMX906S	449.00	449.00
1	0	1	12040CR10	Chrysler/GM/Ford Antenna Adapt	5.23	5.23
1	0	1	126CR3NGL	Bojo ATH-CR3-NGL	11.99	11.99

Special messages

Below are some phone numbers to call if you need help. Please see the back of this invoice for information about our guarantee and how to return an item.

Need help?
Tech Support 1-800-955-9094
Customer Support 1-800-955-9091
¿Habla español? 1-800-955-9039


27918485-01

INFRONT March 2012

Invoice summaryMerchandise Total: 610.94
Tax: 37.20
Order Total: 648.14Payments:
Visa 648.14

8:36 AM

Gmail - AmericanMuscle.com Invoice



AmericanMuscle.com Invoice

5 messages

AmericanMuscle.com <americanmuscle@em.americanmuscle.com>
Reply-To: Support@americanmuscle.com

Thank you for visiting AmericanMuscle.com



American Muscle

600 N. Cedar Hollow Rd.
Paoli, PA 19301
(866) 727-1266

<https://www.americanmuscle.com>

Order Number:

1-38910430

Order Date:

Jan 28 2020

Shipping Method:

Standard Shipping

Customer Information

Product Information

Payment Type:

Payment Date:

Payment Amount:

Visa
01/28/2020
\$1,630.21

Payment Type:

Payment Date:

Payment Amount:

Visa
01/28/2020
(\$104.09)

Product Total:

\$1,487.89

<https://mail.google.com/mail/u/0/?ik=cc8321c56b&view=pt&search=all&permthid=thread-f:1807456709771233143&simpl=msg-f:>

1/7

8/15/24, 8:36 AM

Gmail - AmericanMuscle.com Invoice

Discount Total:

(\$50.00)

Shipping Total:

\$0.00

Tax Total:

\$88.23

Grand Total:

\$1,526.12

SKU: 28264G05

Item Name: Deep Dish Bullitt Black Wheel;
18x9 (05-09 GT, V6)

Price: \$144.00

Quantity: 2

Backorder: 0

Line Total: \$288.00

SKU: 28267

Item Name: Deep Dish Bullitt Black Wheel;
Rear Only; 18x10 (05-09 GT, V6)

Price: \$154.00

Quantity: 2

Backorder: 0

Line Total: \$308.00

SKU: 390740

Item Name: Chrome 6 Spline Lug Nut Kit - 1/2
in. x 20 (79-14 All)

Price: \$29.99

Quantity: 1

Backorder: 0

Line Total: \$29.99

SKU: 397432

Item Name: Tire Road Hazard Protection for
Tire Kits

Price: \$49.96

Quantity: 1

Backorder: 0

Line Total: \$49.96

SKU: 407827-AQ

Item Name: Sumitomo Maximum Performance
HTR Z5 Tire - 255/45R18

Price: \$162.00

Quantity: 2

Backorder: 0

Line Total: \$324.00

SKU: 407827-AR

Item Name: Sumitomo Maximum Performance
HTR Z5 Tire - 275/40R18

Price: \$142.00

Quantity: 2

Backorder: 0

Line Total: \$284.00

SKU: 76115

Item Name: TPMS Sensor Syncing Tool (07-20
All)

Price: \$47.98

Quantity: 1

Backorder: 0

Line Total: \$47.98

SKU: 76133

Item Name: Valve Stem-Mounted TPMS
Sensor (07-09 All)

Price: \$38.99

Quantity: 4

<https://mail.google.com/mail/u/0/?ik=cc8321c56b&view=pt&search=all&permthid=thread-f:1807456709771233143&simpl=msg-f:>

2/7

8:36 AM

Gmail - AmericanMuscle.com Invoice

NORTH HAVEN, CT 06473
United StatesNORTH HAVEN, CT 06473
United States

Product Information

Payment Type: Visa
Payment Date: 07/28/2020
Payment Amount: \$24.12

Payment Type: Visa
Payment Date: 07/30/2020
Payment Amount: \$311.88

Payment Type: Visa
Payment Date: 07/30/2020
Payment Amount: (\$7.41)

Product Total: \$328.97
Discount Total: (\$20.00)
Shipping Total: \$0.00
Tax Total: \$19.62
Grand Total: \$328.59

SKU: 100176
Item Name: Raxiom Coyote Tail Lights and Sequential Tail Light Kit; Smoked (05-09 All)
Price: \$293.98
Quantity: 1
Backorder: 0
Line Total: \$293.98

SKU: 398337
Item Name: Axial LED Third Brake Light; Smoked (05-09 All)
Price: \$34.99
Quantity: 1
Backorder: 0
Line Total: \$34.99

Balance Due: \$0.00

Need additional assistance? LiveChat with a Sales Tech!

8:36 AM

Gmail - AmericanMuscle.com Invoice

Product Information

Payment Type: Visa
Payment Date: 07/26/2020
Payment Amount: \$280.73

Product Total: \$263.97
Discount Total: \$0.00
Shipping Total: \$0.00
Tax Total: \$16.76
Grand Total: \$280.73

SKU: 389342
Item Name: SpeedForm Standard Custom-Fit Car Cover (05-09 GT Coupe, V6 Coupe)
Price: \$149.99
Quantity: 1
Backorder: 0
Line Total: \$149.99

SKU: 389853
Item Name: SpeedForm Adjustable Length Antenna; Black (79-09 All)
Price: \$33.99
Quantity: 1
Backorder: 0
Line Total: \$33.99

SKU: 73035
Item Name: SpeedForm No-Drill Splash Guards; Front and Rear (05-09 GT)
Price: \$79.99
Quantity: 1
Backorder: 0
Line Total: \$79.99

Balance Due: \$0.00

Need additional assistance? LiveChat with a Sales Tech!

AMERICANMUSCLE

My Account Saved For Later Change Your Vehicle

AmericanMuscle | 600 Cedar Hollow Rd | Paoli, PA 19301 | United States



Ford Motor Company
Ford Customer Service Division
P. O. Box 1904
Dearborn, Michigan 48121-1904



done 12/2018

12/14/2018 GENORAS FORD
PLAINVILLE, CT
@29,477 miles March 2018
(see carfax)

*** IMPORTANT SAFETY RECALL ***

Safety Recall Notice 17S01 / NHTSA Recall 17V-024

2008 Mustang

Your Vehicle Identification Number (VIN): 1ZVHT82H785164031



**AIRBAG
RECALL**

A REPAIR IS AVAILABLE FOR YOUR VEHICLE

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Ford Motor Company has decided that a defect which relates to motor vehicle safety exists in your vehicle, with the VIN shown above.

We apologize for this situation and want to assure you that, with your assistance, we will correct this condition. Our commitment, together with your dealer, is to provide you with the highest level of service and support.

What is the issue?

The passenger airbag inflator in your vehicle may explode in the event of a crash that causes deployment of the passenger airbag. If an inflator explodes, sharp metal fragments could strike the passenger or other occupants causing serious injury or death.

What will Ford and your dealer do?

Parts are now available to repair your vehicle. Ford Motor Company has authorized your dealer to replace the passenger airbag inflator free of charge (parts and labor).

How long will it take?

The time needed for this repair is less than one-half day. However, due to service scheduling requirements, your dealer may need your vehicle for a longer period of time.

Simoniz Garage
283 PARK RD

WEST HARTFORD, CT 06119
(860)512-2222



Ticket: 12934

Date: July 29, 2020 16:32

Crew:

Customer Information		Vehicle Information				
SWI GLASS 290 PROSPECT AVE HARTFORD, CT 06106	YEAR 2008 MAKE FORD MODEL MUSTANG ENGINE	VIN LICENSE AW74304 MILEAGE 31,000 OIL TYPE				
Fleet Information		Service History				
		SALE DATE MILEAGE SERVICE 07/29/20 31,000 SDP;				
		P.O. Number:				
SERVICE CHECKLIST		DESCRIPTION	PART	QTY	PRICE	AMOUNT
		SIMONIZ DIAMOND PLATE 2yr.	SDP	1.00		

Ticket Notes:

SubTotal 450.00
Coupon 0.00
Discount 0.00
Sale 450.00
Taxable Amt 450.00
Sales Tax 28.58
Total 478.58

Check 11120 (478.58)

Signed X

Recommended next service on 10/29/2020 or 34,000 miles.

Balance Due 0.00
Change Due 0.00

ALL STAR AUTOMOTIVE
45 STATE ST
North Haven, CT. 06473
Phone: 203-891-5122 Fax: 203-234-0002

INVOICE
10131
Org. Est. # 016584

INVOICE

Printed Date: 09/19/2022 Work Completed: 09/19/2022

2008 Ford - Mustang GT - 4.6L V8 (281CI) VIN(H)
Lic # : AW74304 Odometer In : 32847

VIN # : 1ZVHT82H7 85164031

Part Description / Number	Qty	Sale	Ext	Labor Description	Ext
Full Synthetic Motor Oil OIL	6.00	9.95	59.70	Drain and Fill Engine Oil and Change Oil Filter	20.00
Engine Oil Filter FILTER	1.00	6.95	6.95		
Shop Supplies			2.00		
Hazardous Materials			1.33		

[Recommendations]
WINDSHIELD IS CRACKED

Org. Estimate 95.69 Revisions 0.00 Current Estimate 95.69

Labor: 20.00
Parts: 68.65

HazMat: 1.33

SubTotal: 89.98
Tax: 5.71
Total: 95.69
Bal Due: \$0.00

[Payments - Visa - \$95.69]

Vehicle Received: 9/19/2022

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty work has to be performed in our shop & cannot exceed the original cost of repair. Warranty period is 90 days on parts and labor unless otherwise specified in writing.

Signature _____ Date _____

Service Advisor : RHEAUME, BEN, Tech : SANCHEZ, ALCIDES 005

Page 1 of 1

Copyright (c) 2022 Mitchell Repair Information Company, LLC invhrs 5.12.21kr



38000 AMRHEIN
LIVONIA, MI 48150-1016

SHIP TO:

SOLD TO:

DIVERSIFIED PRODUCTS MARKETING, I
9980 Joy Road
PLYMOUTH, MI 48170

Page 1 of 1

Customer PO Number	Invoice Number	Order Date
4944	0556201	11/21/2011

Line No.	Part Number	Description	Initial Qty Ordered	Prior Total Shipped	Qty This Shipment	Back Ordered
1	M-5230-S	FR500S MUSTANG MUFFLER KIT	1	0	1	0
2	M-11622-BFSE	2-1/16" VACUUM/BOOST FSE	1	0	1	0

PLEASE HOLD THE M-11622-BFSE FOR PICK UP FROM DPM. - THANK YOU.

Safelite® AutoGlass

SAFELITE AUTOGLASS
459 WASHINGTON AVE
NORTH HAVEN, CT 06473
** SERVICE QUESTIONS **
** CALL 203-239-6040 **

Date & Time: 07/22/24 4:46PM

LIC# GLZ.0001509-AG1

Year 2008	Make FORD	Model MUSTANG
License AW74304	Style 2 DOOR COUPE	Stock/Unit#
Mileage 35000	VIN 1ZVHT82H785164031	
Purchase Order#	Claim # MK24062244	

Qty	Part	List Price	Selling Price	Flat Labor	Kit	MTRL
1	CPI RELIEF	12.00	12.00	0.00	0.00	0.00
1	DW01570 GTYOEM	662.40	364.32	127.32	40.00	0.00

Urethane Brand: DuPont
Urethane Product: 4 DuPont APEX
Urethane Lot Number: D243M7EUEC

Technician Name	Technician ID
steven	1871-080

Technician Notes

Part Subtotal:	416.32
Flat Labor Subtotal:	127.32
Subtotal:	543.64
Sales Tax:	34.51
Total:	578.15

Deductible: 0.00

Deductible Paid: 0.00

Deductible Remaining: 0.00

Amount to Collect: 0.00

Payment Amount: 0.00

Amount Due: 0.00

Your vehicle has been vacuumed!
Your exterior windows have been cleaned!

Authorized By Phone: BIRAN, ERIC
Authorization Time: 07/22/24 4:10PM
Phone Number: 860-573-5726

Vehicle may be driven after 05:11 PM



M Sport Motorwerx
7 Industrial Rd
Prospect, CT 06712
(203) 592-8744
lawrence@msportmotorwerx.com
www.msportmotorwerx.com

Invoice #1969

Created: 8/8/2024 10:57 AM EDT
Invoiced: 8/8/2024 11:19 AM EDT
Payment Term: On Receipt
Service Writer: Ben Bshara

2008 Ford Mustang GT (Green)

VIN: 1ZVHT82H785164031
Mileage In: 34,712
Mileage Out: 34,712

Customer Comments

Oil Change
Rear differential Oil service

Recommendations

Oil change and Rear diff oil change performed.

Oil Change

Oil Change with Liqui Moly 5W-20, and Ford oil filter.

Description	Price	QTY	HRS	Subtotal
1 Oil Change R&R			0.6	\$101.40
2 5W-20	\$14.31	6		\$85.86
3 Oil Filter	\$13.67	1		\$13.67
EPA (1%): \$2.01 Tax (6.35%): \$12.89				Total: \$215.83

Drive Axle Assembly Drain & Refill

Rear Differential Oil Change, Found a good amount of clutch material on magnetic fill plug. Customer advised there was a leak, I advised the leak could be wearing the clutches down faster, depending on how severe the leak is. Recommended to inspect the rear differential gear, and change the leaking input shaft seal.

Description	Price	QTY	HRS	Subtotal
1 Drive Axle Assembly Drain & Refill			0.75	\$126.75
2 Differential Fluid Type Note: Red Line 75W-140 GL-5	\$41.13	3		\$123.39
EPA (1%): \$2.50 Shop Supplies (4.25%): \$10.63 Tax (6.35%): \$16.72				Total: \$279.99

Thank you for your business. The work is complete and your payment is due upon pickup of the vehicle. Mechanics liens may be placed on vehicles until repairs are paid for in full. Please contact us promptly if you have any questions about anything we did.

Signature _____

Parts	\$222.92
Labor	\$228.15
Subtotal	\$451.07
Shop Supplies	\$10.63
EPA	\$4.51
Tax	\$29.60
Grand Total	\$495.81
Paid To Date	(\$495.81)

REMAINING BALANCE \$0.00



M Sport Motorwerx
7 Industrial Rd
Prospect, CT 06712
(203) 592-8744
lawrence@msportmotorwerx.com
www.msportmotorwerx.com

Estimate #1970

Created: 8/8/2024 11:50 AM EDT
Payment Term: On Receipt
Service Writer: Ben Bshara

2008 Ford Mustang GT (Green)

VIN: 1ZVHT82H785164031
Last Recorded Mileage: 34,712

Customer Comments

Pinion Seal is leaking

Recommendations

Replace pinion seal, and fluid if fluid has excessive clutch material in it.

Differential Pinion Seal R&R

Labor and Parts for the job

Description	Price	QTY	HRS	Subtotal
1 Differential Pinion Seal R&R			1.2	\$202.80
2 Differential Fluid Type Note: 75W-140/All TEMPS, SAE 75W-140 synthetic, Synthetic oil is required. , Traction-Lok axles add 4oz of friction modifier Ford P/N XL-3 or equivalent meeting Ford spec EST-M2C118-A.	\$41.31	3		\$123.93
3 Differential Pinion Seal Note: Rear	\$19.71	1		\$19.71

EPA (1%): \$3.46 Shop Supplies (4.25%): \$14.72 Tax (6.35%): \$23.15 Total: \$387.77

Estimates provided are an approximation of timing and charges to you for the services requested. They are based on the anticipated work to be done. It is possible for unexpected complications to cause some deviation from the original quote. You hereby authorize the repair work described in this estimate to be done along with the procurement of the necessary material(s), including permission to operate the vehicle for on-road testing or inspection. If any additional repairs are required, we will prepare a revised work order providing the cost of additional parts and labor and total revised cost. All parts are new unless specified otherwise.

Deposits are non-refundable. No returns or refunds on special ordered items or electrical parts. There is no warranty for used parts or customer supplied parts.

You agree that we are not responsible for loss or damage to your vehicle, including loss of articles left in the vehicle, including, without limitation, in case of fire, theft, or any other cause(s) beyond our control.

We are not responsible for any delays caused by unavailability of parts or delays in delivery of parts by the supplier or transporter. You have the right to know before authorizing any additional repairs what those repairs will be and what they will cost. If required repairs exceed the authorized estimated amount, we must obtain your approval to perform the repairs. We will keep you informed and perform only repairs authorized by you.

Signature _____

E-signed by Eric Biran 8/8/2024 at 12:10 PM EDT

Parts	\$143.64
Labor	\$202.80
Subtotal	\$346.44
Shop Supplies	\$14.72
EPA	\$3.46
Tax	\$23.15
Grand Total	\$387.77
Paid To Date	(\$0.00)

REMAINING BALANCE \$387.77