

1998

CORVETTE

VIN 1G1YY22G1W5124123

Equipment SEBRING SILVER METALLIC EXT. BLACK LEATHER INTERIOR
345 HP 5.7L LITER SFI, V8, 4-SPD AUTO. TRANS. W/OVERDRIVE

Purchase Date July 7, 2000

Mileage 17220

SERVICE RECORD

MILEAGE	DATE	
19290	10/28/00	OIL (MOBIL 1 , 5w-30, 6.5 qt.), OIL FILTER (AC UPF44)
19510	3/10/01	Chrome Exhaust Tips (Christmas Present)
21032	8/4/01	Replace left front tire, Goodyear P245/45ZR17, due to sidewall impact damage
21998	11/25/01	OIL (MOBIL 1 , 5w-30, 6.5 qt), OIL FILTER (MOBIL 1 M1-107) Cleaned Bottom 67% Oil left
22010	4/6/02	Installed threshold protectors, First outing
22147	6/8/02	Installed Chrome Wheels from Mid America Direct Installed at Lansing Goodyear / Just Tires
22600	6/28/02	Detailed bottom McGuires Gel cleaner and Engine Kote McGuires Clay/Gold Class
22725	7/7/02	Cleared all computer codes
24033	9/28/02	Flushed Brake system GM Fluid 1 Qt. Drained DexCool antifreeze 1.25gal antifreeze/1.25 gal water
24104	10/11/02	Flush Trans & Refill Serviced at Bill Kay Chevrolet Service Rear Differential Four Wheel Alignment Replace Right Front Tire
24470	11/24/02	OIL (MOBIL 1 , 5w-30, 6.5 qt), OIL FILTER (MOBIL 1 M1-107) 36% oil left 2years

24475	3/15/03	Delco Battery, Positive Battery Cable
25815	9/13/03	Replace Both rear tires TireRack
26613	11/22/03	OIL (MOBIL 1, 5w-30, 6.5 Quarts), Oil FILTER. (MOBIL 1M1-107) Wax Zimol
26620	3/26/04	Reinstalled Battery, First outing
28231	10/24/04	OIL (MOBIL 1, 5w-30, 6.5 qt), Oil FILTER, (Percolator PureONE PL14006) Oil Life 54%
29951	11/15/05	OIL (MOBIL 1, 5w-30, 6.5 Quarts), Oil FILTER. (MOBIL 1M1-107)
	10/12/06	Optima Battery from Battery Web
32313	5/18/07	OIL (MOBIL 1, 5w-30, 6.5 Quarts), Oil FILTER, (MOBIL 1M1-107) 2362 mi Optima Battery from Van Senus
33889	10/07	Initiated battery charger
33890	4/5/08	First Outing
34026	4/12/08	OIL (MOBIL 1, 5w-30, 6.5 Quarts), Oil FILTER, (MOBIL 1M1-107) Oil Life 80%, 1714 mi. Washed Bottom
39030	04/22/10	Oil (Mobil 1, 5w30, 6.5 qts, Oil Filter
42852	10/6/11	Oil (Mobil 1, 5w-30, 6.5 quarts), oil filter, (Fram Tough Guard 3506), Oil Life 55% 3822mi
42602	11/6/2011	Put away
43013	8/09/12	Fram Air Filter CA3914
43861	9/29/12	Flushed Brake fluid all wheels. New AC Delco DuraLast Ceramic Brake pads on all wheels. Turned rotors Detailed frame and suspension all around.
44104	5/13/13	Oil (MOBIL 1, 5w-30, 6.5 qts), Oil Filter, (Fram Tough Guard 3506), Oil Life 80% 1252 mi
44676	8/21/13	Drained antifreeze refilled with Prestone DexCool, circulated drained and refilled 4+ gallons used total.
47882	3/17/14	Fuel Filter replaced Van Chevrolet, Scottsdale
49951	6/2/14	Oil (Mobil 1, 5w-30, 6.5 qt.), Oil Filter Mobil 1 M1-107, Oil Life 37%, 5846 Mi, replaced both front turn sig. bulbs 4157 NA , Cleaned oily bottom, washed rest of bottom
50510	6/26/14	A/C belt, idler pulley, tensioner ... all AC Delco

50775	7/4/14	Main accessory belt, idler pulley ... all AC Delco
50902	7/7/14	(2) 245/45 R17 Michelin Pilot Sport AS+ZP 95Y Runflat Tires (2) 275/40 R18 Michelin Pilot Sport AS+ZP 99Y Runflat Tires (4) Schrader TPMS senders Tire Rack South Bend
51200	7/16/14	Front end alignment M&M Car Care Service... all ok
56542	4/01/15	Oil (Mobil 1, 5w-30, 6.5qt.), Oil Filter Mobil 1 M1-107, Oil Life 32%, 6591 mi
56871	7/16/15	Replaced accessory belt tensioner GM 12559325, replaced driver seat carrier bushings from C & S Corvette, and installed aluminum gas pedal. Oil Life 96%
62862	5/23/16	Oil (Mobil 1, 5w-30, 6.5qt.), Oil Filter Mobil 1 M1-107, Oil Life 34%, 6177 mi. clay bar, Ultimate Polish, Ultimate Wax.
63007	8/05/16	Reset B trip odometer read 6323.3 146 miles since oil change
63540	5/10/17	New Optima battery 8078-109 Amazon
63755	6/23/17	Replaced rear exhaust pipes, mufflers and tips at Bloomington Gold
64595	4/13/18	Cleared codes. Repaired LED's in HVAC Control
64632	5/03/18	Flushed and bled brakes, Changed diff lube. ACDelco 75W-90 Synthetic Axle Gear oil and ACDelco Limited Slip Axle Lube additive
65259	5/30/18	Oil (Mobil 1, 5w-30, 6.5 qt.), Oil Filter Fram Ultra Synthetic XG3506, Oil Life 72%, 2251.2mi
67220	11/8/18	Changed Diff lube. Put in 2 anti chatter additives. Legends Lux. Auto
69141	2/28/20	Oil Dexos. 5w-30, Oil filter. Oil life 52%, 3882.4 miles. Cooling system flush. Quick Cool added for addl. cooling. Legends Luxury Auto
70008	11/29/21	Rear stabilizer lubricated. Reduced noise. Legends Luxury Auto
70102	01/20/22	Complete brake job, all rotors and pads, replaced water pump and thermostat, dex cool and quick cool, replaced harmonic balancer and both belts. Legends Luxury Auto
71924	11/29/22	Oil Dexos 5w-30, Oil filter. Oil life 62%, 2782.5 miles. Rev X zinc additive. Legends Luxury Auto
73905	06/19/24	Optima Battery Red top 34/78-980 Advanced Auto DCB
74251	01/09/25	Oil Dexos 5w-30, oil filter. Oil life 65%, 2327 mi. Zinc additive. Evac. & Recharge A/C Legends Luxury Auto

75212

03/02026

Replace hood support cylinders DCB

W5124123

3 6 5 7 6 4

INVOICE



601 Ogden Avenue
Lisle, IL 60532
(630) 968-2900

PAGE 1

SERVICE ADVISOR: 6 MARK BOWLING

COLOR	YEAR	MAKE/MODEL		VIN	LICENSE	MILEAGE IN/ OUT		TAG
	98	CHEVROLET CORVETTE		1G1YY22G1W5124123		24104/24104		T3270
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE	
			WAIT 11OCT02			CASH	11OCT2002	
R.O. OPENED		READY		OPTIONS: ENG:5.7_Liter_V8_MFI				
11OCT02		11OCT02						

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
A	TRANS FLUSH W/KIT AND COMPLETE TRANS FLUID CHANGE						
	7F TRANS FLUSH W/KIT AND COMPLETE TRANS FLUID CHANGE						
	11 CPM					85.00	85.00
	15 12378470B TRANS FLUID				1.58	1.58	23.70

B	CK FRONT TIRE RT SIDE CUPPING/FRONT TIRE LT NEW REPLACED						
	57 REPLACE RIGHT FRT TIRE AND BALANCE						
	11 CPM					42.50	42.50
	1 31013815 TIRE				293.71	280.35	280.35
	1 TIRETAX				1.00	1.00	1.00

C	CK WHEN BRAKES APPLIED FROM HIGHWAY SPEEDS OR LOCAL DRIVING GETS VIBRATING NOISE FROM REAR OF VEH.						
	57 ALIGN FRONT END						
	11 CPM					255.00	255.00

D**	SERVICE REARR						
	57 SERVICE REAR DIFFERENTIAL						
	11 CPM					85.00	85.00
	3 12345977 LUBRICANT				4.83	4.83	14.49
	1 1052358 LUBRICAN				6.86	6.86	6.86

	CUSTOMER PAY SHOP CHARGE FOR REPAIR ORDER						9.15

OCT 11 2002

BILL KAY CHEVROLET

CC
DSC

Extended Hours:

Monday-Thursday
7:00 a.m. - 7:00 p.m.Friday
7:00 a.m. - 7:00 p.m.Saturday
8:00 a.m. - 1:00 p.m.GM QUALITY
SERVICE PARTST
H
A
N
KY
O
U
!

STATEMENT OF DISCLAIMER

The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties, either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.

CUSTOMER SIGNATURE

DESCRIPTION	TOTALS
LABOR AMOUNT	467.50
PARTS AMOUNT	326.40
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	0.00
MISC. CHARGES	9.15
TOTAL CHARGES	803.05
LESS INSURANCE	0.00
SALES TAX	22.65
PLEASE PAY THIS AMOUNT	825.70
	- 79.00
	746.70



CUSTOMER COPY

10/11/02 11:21 AM

10/11/02

746.70

CUSTOMER #: 665115

1016999



INVOICE

8585 E. Frank Lloyd Wright Blvd.

Scottsdale, Arizona 85260

(480) 991-4567

Fax (480) 905-1659

PAGE 1

SERVICE ADVISOR: 2616 STEVEN KUCINSKI

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/OUT	TAG
	98	CHEVROLET CORVETTE	1G1YY22G1W5124123		47882/47882	T7910
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT
01JAN98 DD			WAIT 17MAR14		0.00	COU1
						17MAR14
R.O. OPENED	BOOKED	OPTIONS: DLR:39017 ENG:5.7_Liter_V8_MFI				
10:04 17MAR14	14:53 17MAR14					

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A CUST SWTS THERES A STRONG FUEL ODOR, WHEN CUST LOOKED UP UNDER VEH
THERE WAS QUITE A BIT OF MOISTURE ON PANS UNDER SEATING AREA
AND TRUNK AREA

S313 LIGHT LINE

567 COOPER, JASON LIC#: 567

CPC

119.88 119.88

1 10287788 F-(S) FILTER

28.00

28.00

28.00

47882 1.00 CHECKED AND FOUND FUEL FILTER LEAKING. REPLACED AND
RECHECKED OK AT THIS TIME...

B PERFORM VISUAL MULTIPOINT INSPECTION INCLUDING TIRE & BRAKE
MEASUREMENTS, FLUID LEVELS, FLUID CONDITIONS, FLUID LEAKS,
EXHAUST SYSTEM, SUSPENSION & STEERING, BATTERY, & OVERALL
DRIVETRAIN INSPECTION

DEC CUSTOMER DECLINED REPAIRS

567 COOPER, JASON LIC#: 567

CPC

0.00

0.00

47882 CUSTOMER DECLINED OIL LEAK REPAIRS AT THIS TIME... EST
\$1978.00 TO RESEAL FRONT ENGINE COVER AND ENGINE OIL PAN + 199.95 FLUSH
ENGINE COOLANT SYSTEM.

RECYCLE, DISPOSAL AND SHOP MATERIALS

8.88

We offer a wide variety of service specials
and discounts over the Internet. If you have
an E-mail address be sure we have it in our
data base. Any of our service staff can
assist you with adding it to our records.
Thank your for your patronage.

ON BEHALF OF SERVING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE UNLESS OTHERWISE SHOWN. SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO OWNER. THERE WAS NO INDICATION FROM THE APPEARANCE OF THE VEHICLE OR OTHERWISE, THAT ANY PART REPAIRED OR REPLACED UNDER THIS CLAIM HAD BEEN CONNECTED IN ANY WAY WITH ANY ACCIDENT, NEGLIGENCE OR MISUSE. RECORDS SUPPORTING THIS CLAIM ARE AVAILABLE FOR (1) YEAR FROM THE DATE OF PAYMENT NOTIFICATION AT THE SERVING DEALER FOR INSPECTION BY MANUFACTURER'S REPRESENTATIVE.	*Customer agrees that any controversy or claim by or between Customer and Dealer (including any of its agents and representatives) of any kind or nature whatsoever shall be settled by arbitration in accordance with the rules of the American Arbitration Association. There shall be no class action arbitration or relief. The arbitration award and/or shall be final and binding on the parties to the arbitration. Unless the arbitrator that enforceability of this Arbitration Clause requires otherwise, each party shall bear its own costs and expenses in connection with any arbitration proceeding. Both Customer and Dealer retain the right to exercise self-help remedies and to seek provisional remedies from a court. If any part of this Arbitration Clause is deemed or found to be unenforceable for any reason the rest of the Arbitration Clause remains enforceable.	STATEMENT OF DISCLAIMER The factory warranty constitutes all of the warranties with respect to the sale of this item/items. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.	DESCRIPTION	TOTALS
			LABOR AMOUNT	119.88
			PARTS AMOUNT	28.00
			GAS, OIL, LUBE	0.00
			SUBLET AMOUNT	0.00
			MISC. CHARGES	8.88
			TOTAL CHARGES	156.76
			LESS INSURANCE	14.78
CUSTOMER SIGNATURE			SALES TAX	2.94
			PLEASE PAY THIS AMOUNT	144.92

CUSTOMER COPY

M&M Car Care Center, Inc.
3903 W.83RD PL UNIT F
MERRILLVILLE, IN. 46410
Phone - 219-769-2475 Fax - 219-769-2538
Expert Service You Can Depend On

INVOICE

20033

Org. Est. # 042611
26-0679120

INVOICE

Print Date : 07/16/2014

1998 Chevrolet - Corvette - 5.7L, V8 (350CI)

Lic # : - IN

Odometer In : 0

Unit # :

51,200 mi

Vin # :

Hat # :

Ref # :

Part Description / Number	Qty	Sale	Extended	Labor Description	Extended
				CHECK ALIGNMENT	
				PERFORM 4 WHEEL COMPUTERIZED	75.00
				ALIGNMENT CHECK	

Org. Estimate \$ 75.00 Revisions \$ 0.00 Current Estimate \$ 75.00

Labor:	75.00
Parts:	0.00
Sublet:	\$0.00
Sub:	75.00
Tax:	0.00
Total:	75.00
Bal Due:	\$0.00

[Payments - Visa - \$75.00]

I acknowledge that I am receiving the final invoice and that I have inspected the vehicle printed on this invoice and that I agree with and accept all work performed. Warranty on NEW parts is one year-labor is 90 DAYS from date on invoice . Warranty work has to be performed in our shop. There is no Warranty on used parts or labor unless specified. M&M Car Care Center is not liable for missing or lost articles from the vehicle on this invoice.

Signature: _____

Signature _____ Date _____ Time _____

Pfadt Corvette Alignment Recommendations

These settings are a guide based on the experience and testing of Pfadt Race Engineering.
Toe specs listed in inches are intended to be measured using a toe plate with approximately 21-5/8" between notches for tape measures. Negative toe measurements indicate toe-in.



PFADT
RACE ENGINEERING

Performance Street

Front	min	max
Camber (deg)	-0.7	-0.9
Caster (deg)	7.5	8.5
Total Toe	-1/16" (0.17")	0 (0°)
Rear		
Camber (deg)	-0.4	-0.6
Total Toe	-1/16" (0.17")	0 (0°)
Notes These settings will provide good performance and good tire wear		

Performance Street - Track Use with Street Tires

Front	min	max
Camber (deg)	-1.1	-1.3
Caster (deg)	7.5	8.5
Total Toe	-1/16" (0.17")	0 (0°)
Rear		
Camber (deg)	-0.7	-0.9
Total Toe	-1/8" (0.33")	-1/16" (0.17")
Notes These settings will provide good all around performance. The tires will wear the inside edges in street use and the outside edges on the race track. This is a good dual purpose alignment.		

Performance Street - Track Use with Race Tires

Front	min	max
Camber (deg)	-1.6	-1.8
Caster (deg)	7.5	8.5
Total Toe	-1/16" (0.17")	0 (0°)
Rear		
Camber (deg)	-0.9	-1.1
Total Toe	-1/8" (0.33")	-1/16" (0.17")
Notes These settings will provide great track performance. The tires will wear the inside edges in street use, and the car may tend to grab the lanes of the road. Race tires will wear well at the track and provide high levels of grip. This alignment is compromised towards track use.		

Dedicated Track Car - DOT Tires, poly bushings

Front	min	max
Camber (deg)	-2.8	-3.0
Caster (deg)	6.5	7.5
Total Toe	-1/16" (0.17")	0 (0°)
Rear		
Camber (deg)	-1.5	-1.7
Total Toe	-1/8" (0.33")	-1/16" (0.17")
Notes These settings are a good starting point for a car with polyurethane or stock control arm bushings. This alignment requires DOT race tires to function appropriately. This is a starting point only, testing and monitoring tire temperatures and pressures are required to optimize any setup.		

Dedicated Track Car - DOT Tires, Spherical Bearings

Front	min	max
Camber (deg)	-2.4	-2.6
Caster (deg)	6.5	7.5
Total Toe	-1/16" (0.17")	0 (0°)
Rear		
Camber (deg)	-1.2	-1.4
Total Toe	-3/16" (0.50")	-1/8" (0.33")
Notes These settings are a good starting point for a car with mono-ball or spherical control arm bushings. This alignment requires DOT race tires to function appropriately. This is a starting point only, testing and monitoring tire temperatures and pressures are required to optimize any setup.		

Dedicated Track Car - Race Slicks, Spherical Bearings

Front	min	max
Camber (deg)	-3.0	-3.2
Caster (deg)	6.5	7.5
Total Toe	-1/16" (0.17")	0 (0°)
Rear		
Camber (deg)	-2.0	-2.3
Total Toe	-3/16" (0.50")	-1/8" (0.33")
Notes These settings are a good starting point for a car with mono-ball or spherical control arm bushings. This alignment is designed and tested with race slicks, not DOT tires. This is a starting point only, testing and monitoring tire temperatures and pressures are required to optimize any setup.		

Bill Kay Chevrolet
601 Ogden Avenue
Lisle, IL. 60532
(630) 968-2900
Thank you for your business.

Name _____
Address _____

Telephone _____
Vehicle (VIN) _____
License _____
Technician _____
Mileage _____
Time Printed 10/11/02 11:23 AM

Front : Left

Actual	Before	Specified Range	
✓ 0.0°	0.1°	-0.2°	0.2°
✓ 6.4°	5.6°*	6.0°	7.0°
0.07°	0.01°	-0.05°	0.15°
8.0°	8.2°		
8.0°	8.3°		
.....			

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range	
-0.1°	-0.4°*	-0.2°	0.2°
6.4°	7.4°*	6.0°	7.0°
0.04°	0.03°	-0.05°	0.15°
8.2°	8.4°		
8.1°	8.1°		
.....			

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range	
0.1°	0.5°*	-0.3°	0.3°
0.1°	-1.8°*	-0.3°	0.3°
-0.2°	-0.3°		
0.11°	0.04°	-0.10°	0.30°
.....			

Rear : Left

Actual	Before	Specified Range	
-0.1°	-0.1°	-0.5°	-0.1°
0.03°	-0.02°	-0.10°	0.10°

Camber
Toe

Rear : Right

Actual	Before	Specified Range	
-0.3°	0.0°*	-0.5°	-0.1°
0.03°	-0.06°	-0.10°	0.10°

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range	
0.1°	-0.1°		
0.06°	-0.07°	-0.20°	0.20°
0.00°	0.02°	-0.10°	0.10°

PACKING LISTOrder Number: **23642282** placed Monday, June 23, 2014 06:18 PMShip Via: **Ground****From:**

RockAuto, LLC
Attn: Jason F
30 Seaview Blvd
Port Washington, NY 11050
US

Ship To:

<u>Manufacturer</u>	<u>Part Number</u>	<u>AutoPart Category</u>	<u>Quantity (This Box)</u>	<u>Quantity Ordered</u>	<u>Shipped</u>
1998 CHEVROLET CORVETTE 5.7L V8					
ACDELCO	35 4K420	Belt	1	1	
ACDELCO	15 12560345@U05	Belt Tensioner	1	1	
ACDELCO	15 15-4669@X01	Idler Pulley	1	1	

Thank you for choosing us as your parts supplier! If you need to return something, visit <http://www.rockauto.com/orderstatus> for instructions. If you have questions, please call 1-608-661-1376 or e-mail service@rockauto.com with the Order Number above and as much detail as possible to help us assist you (the part number, pictures which illustrate your concern, etc.).

Packed By: _____ Date: ____/____/____

GMPartsOutlet

GMPartsOutlet.net**Billing Information**

PayPal Express Order - Billing Information at PayPal

Shipping Information-----
3**Order ID: 31040****Created at: 07/09/2015 -
02:52:31 PM****Last status change:
07/09/2015 - 03:09:35 PM**GMPartsOutlet.net
5321 W Maryland Ave,
Glendale, Arizona 85301
USAEmail: info@gmpartsoutlet.net

Website:

<http://www.gmpartsoutlet.net>

Product ID	Product Name	List Price	Your Price	Quantity	Total
12559325 Chevrolet VIN: 1G1YY22G1W5124123	TENSIONER Selected Car: 1998 Chevrolet Corvette Base - 5.7L V8 - Gas	\$113.88	\$79.19 (not taxable)	1	\$79.19
Subtotal :					\$79.19
Shipping (Free Shipping 3-7 days (most orders)) :					\$0.00
Handling :					\$8.95
Total :					\$88.14

Payment Information

Method : Real-time, PayPal Express Checkout

Gateway : PayPal Express Checkout

Completed at : 07/09/2015 - 02:52:31 PM

Invoice ref #: 153030



7101 Vorden Parkway
South Bend, IN 46628-8422
Phone: (574) 287-2345
800: (800) 428-8355
Customer Service: Ext. 4360
Fax: (574) 236-7707

INVOICE

INVOICE NUMBER	INVOICE DATE	PAGE
P454651	7/05/14	1
PURCHASE ORDER NUMBER		

070514
13:39:22

BILL TO:
1010001-000

SHIP TO:
1010001-000

SHIP-TO PHONE: 219-713-7021

SHIP METHOD: Customer Pick-Up

Plan 2316752 Team PICK Wave 001 Prcl 255


Plan 2316752 Team PICK Wave 001 Pric 255

ORDER DATE	SALES REP. NAME/PHONE EXT	TERMS	MAKE, MODEL AND YEAR	WHSE		
6/26/14	Kyle (ext.4663)	Cash Payment	CORVETTE 98	SB		
PART NUMBER	QUANTITY ORDERED	QUANTITY SHIPPED	GROUP	DESCRIPTION	UNIT PRICE	EXTENSION
445YR7PSASZP 15335	2	2	89	245/45R17 MI PILOT SPRT AS+ZP 15335 95Y RUNFLAT	224.00	448.00
REGCARDR REGISTRATIONR	1	1		Tire DOT Number registration has been filed electronically	N/C	
74YR8PSASZP 37542	2	2	90	275/40R18 MI PILOT SPRT AS+ZP 37542 99Y RUNFLAT	286.00	572.00
REGCARDR REGISTRATIONR	1	1		Tire DOT Number registration has been filed electronically	N/C	
				FIND WARRANTY DETAILS @ WWW.TIRERACK.COM/MI1212		
LABOR	2	2	89	LABOR	15.00	30.00
S009 28006	2	2	90	SCHRDR 315MHZ SENSOR 7 NM 1PC. SENSOR 7NM=62IN.LBS	70.00	140.00
LABOR	2	2	89	LABOR	15.00	30.00
S009 28006	2	2	90	SCHRDR 315MHZ SENSOR 7 NM 1PC. SENSOR 7NM=62IN.LBS	70.00	140.00
				ADD FREIGHT TO AN ORDER	28.00	28.00
				INDIANA TIRE FEE	1.00	1.00
These tires may be eligible for Road Hazard Program coverage until 14 days following invoice date.						
				Subtotal		1389.00
				SALES TAX-INDIANA		92.96
				Cash Payment	1481.96-	
				Total Payment		1481.96-
				Total Amount Due		\$.00 USD
				Payable in U.S. Funds		
50902mi ~						
Weight	130					

50902mi

ALL PAST DUE ACCOUNTS ARE SUBJECT TO A FINANCE CHARGE OF 1 1/2% PER MONTH, WHICH IS AN ANNUAL PERCENTAGE RATE OF 18%.

Order Receipt



C&S Corvettes

5317-A Ashton Ct.
Sarasota, FL 34233

Tel. 800-886-5064

Fax. 941-923-7592

<http://corvettepartscenter.com>

Bill To:	Ship To:	Invoice Number	426
		Date Issued	July 9, 2015
		Payment Method	PayPal
		Customer Email	dcbehrens66@yahoo.com

Code	Description	Quantity	Price	Total
CS900L	Drivers Side Seat Track Repair Kit, 1997-04	1	\$77.00	\$77.00

Subtotal **\$77.00**

Total **\$77.00**

Legends Luxury Automotive Repair LLC

2412 North Scottsdale Road

Tempe, AZ 85281

Shop Phone: (480) 947-2848

Invoice

5149

Estimate Ref #0

Date Printed: 11/08/2018

Printed Time: 11:10 am

Hat/Ref:

Legends Luxury Auto Repair

Time Promised:

1998 CHEVROLET CORVETTE V8 5.7L 350CID FI GAS N G

VIN: 1G1YY22G1W5124123

License:

Mileage In: 67,220

Date Written: 11/08/2018

Unit #:

Mileage Out: 67,220

Written By:

DOM:

Save Old Parts: No

Job Name	Description	Technician	Qty	List	Extended
DIF	Flush rear differential				
Labor c	Work Requested - DIF				49.05
	Work Performed - Flush rear differential fluid with full synthetic gear oil				
Part ad1000	Full Synthetic Gear Oil		1.00	32.95	32.95
Part DEL104003	Limited Slip Additive		2.00	13.46	26.92
Job Total:					108.92

Payment Date	Type	Method	Amount
Payment Totals:			

Parts: \$59.87

Labor: \$49.05

Sublet: \$0.00

Misc: \$0.00

Hazmat: \$2.99

Supplies: \$0.00

Tax Total: \$4.85

Invoice Total: **\$116.76**

Thank You For Your Business

Legends Luxury Automotive Repair LLC

2412 North Scottsdale Road

Tempe, AZ 85281

Shop Phone: (480) 947-2848

Invoice

6281

Estimate Ref #0

Date Printed: 02/28/2020

Printed Time: 10:10 am

Hat/Ref:

Legends Luxury Auto Repair

Time Promised:

1998 CHEVROLET CORVETTE V8 5.7L 350CID FI GAS N G

VIN: 1G1YY22G1W5124123

License:

Mileage In: 69,141

Date Written: 02/28/2020

Unit #:

Mileage Out: 69,141

Written By:

DOM:

Save Old Parts: No

Job Name	Description	Technician	Qty	List	Extended
CSS	Flush cooling system, replace coolant and ins...				
Labor c	Work Requested - CSS				52.56
	Work Performed - Flush cooling system, replace coolant and install quick cool additive that can reduce your cylinder head as much as 10-20 degrees fahrenheit				
Part 10-101	dex cool		1.00	10.49	10.49
Part AD60	quick cool		1.00	22.95	22.95
Job Total:					86.00
LOF	LOF				
Labor c	Work Requested - LOF				19.00
	Work Performed - Remove and install new engine oil and filter. Check tire pressure.				
Part Synthetic Motot Oil	Full Synthetic Motor Oil		6.50	6.58	42.77
Part PF46	Oil Filter		1.00	8.08	8.08
Job Total:					69.85

Payment Date	Type	Method	Amount
Payment Totals:			

Parts: \$84.29

Labor: \$71.56

Sublet: \$0.00

Misc: \$0.00

Hazmat: \$4.21

Supplies: \$2.79

Tax Total: \$6.83

Invoice Total: **\$169.68**

Thank You For Your Business

Legends Luxury Automotive Repair LLC

2412 North Scottsdale Road

Tempe, AZ 85281

Shop Phone: (480) 947-2848

Invoice

7798

Estimate Ref #0

Date Printed: 01/20/2022

Printed Time: 11:43 am

Hat/Ref:

Legends Luxury Auto Repair

Time Promised:

1998 CHEVROLET CORVETTE V8 5.7L 350CID FI GAS N G

VIN: 1G1YY22G1W5124123

License:

Mileage In: 70,102

Date Written: 01/17/2022

Unit #:

Mileage Out: 70,102

Written By:

DOM:

Save Old Parts: No

Job Name	Description	Technician	Qty	List	Extended
Front Brakes	Front Brakes				
Labor c	Work Requested - Front brakes and rotors worn.				170.00
	Work Performed - Inspect, replaced front brake pads and rotors. Clean and lube calipers.				
Part FVC731	Front Brake Pad		1.00	115.25	115.25
Part Black D-S	Black Drill & Slotted Rotor Kit		1.00	300.00	300.00
	Job Total:				585.25
Rear Brakes	Rear Brakes				
Labor c	Work Requested - Rear brakes and rotors worn.				150.00
	Work Performed - Inspect, replace rear brake pads and rotors. Clean and lube calipers.				
Part CEN10507320	Rear Brake Pad		1.00	105.76	105.76
Part Black D-S	Black Drill & Slotted Rotor Kit		1.00	300.00	300.00
	Job Total:				555.76
Job #1	Coolant leak				
Labor c	Work Requested - Coolant leak				375.00
	Work Performed - Test, replaced water pump and thermostat.				
Part 252846	Water Pump		1.00	263.86	263.86
Part 1510412	Thermostat		1.00	67.95	67.95
	Job Total:				706.81
CSS	Flush cooling system, replace coolant and ins...				
Labor c	Work Requested - CSS				55.05
	Work Performed - Flush cooling system, replace coolant and install quick cool additive that can reduce your cylinder head as much as 10-20 degrees fahrenheit				
Part 10-101	dex cool		1.00	25.91	25.91
Part AD60	quick cool		1.00	35.95	35.95
	Job Total:				116.91
Job #2	Harmonic balancer coming apart.				
Labor c	Work Requested - Harmonic balancer coming apart.				705.00
	Work Performed - Replaced harmonic balancer, bolt and both belts.				
Part 12560115	Balancer		1.00	143.65	143.65
Part 12557840	Bolt		1.00	7.00	7.00
Part 4K420	Belt		1.00	35.13	35.13
Part 6K802	Belt		1.00	63.23	63.23
	Job Total:				954.01

Legends Luxury Automotive Repair LLC

2412 North Scottsdale Road
 Tempe, AZ 85281
 Shop Phone: (480) 947-2848

Invoice

7798

Estimate Ref #0

Date Printed: 01/20/2022

Printed Time: 11:43 am

Hal/Ref:

Legends Luxury Auto Repair

Time Promised:

1998 CHEVROLET CORVETTE V8 5.7L 350CID FI GAS N G
 VIN: 1G1YY22G1W5124123

License:

Mileage In: 70,102

Date Written: 01/17/2022

Unit #:

Mileage Out: 70,102

Written By:

DOM:

Save Old Parts: No

.1

Payment Date	Type	Method	Amount
Payment Totals:			

Parts: \$1,463.69

Labor: \$1,455.05

Sublet: \$0.00

Misc: \$0.00

Hazmat: \$13.09

Supplies: \$22.23

Tax Total: \$118.56

Invoice Total: **\$3,072.62**

Thank You For Your Business

Legends Luxury Automotive Repair LLC

2412 North Scottsdale Road

Tempe, AZ 85281

Shop Phone: (480) 947-2848

Invoice

8533

Estimate Ref #0

Date Printed: 11/29/2022

Printed Time: 9:40 am

Hat/Ref:

Legends Luxury Auto Repair

Time Promised:

1998 CHEVROLET CORVETTE V8 5.7L 350CID FI GAS N G

VIN: 1G1YY22G1W5124123

License:

Mileage In: 71,924

Date Written: 11/29/2022

Unit #:

Mileage Out: 71,924

Written By:

DOM:

Save Old Parts: No

Job Name	Description	Technician	Qty	List	Extended
LOF	LOF				
Labor c	Work Requested - LOF				19.00
	Work Performed - Remove and install new engine oil and filter. Check tire pressure.				
Part Synthetic Motor Oil	Full Synthetic Motor Oil		6.50	8.90	57.85
Part PF46	Oil Filter		1.00	9.64	9.64
Part ZINC0201	Zinc Oil Additive		1.00	20.00	20.00

Job Total: 106.49

REBELX

FLAT TABLET CAM ADDITIVE

Payment Date	Type	Method	Amount
Payment Totals:			

Parts: \$87.49

Labor: \$19.00

Sublet: \$0.00

Misc: \$0.00

Hazmat: \$4.37

Supplies: \$4.26

Tax Total: \$7.09

Invoice Total: **\$122.21**

Thank You For Your Business

LEGENDS LUXURY AUTO REPAIR LLC

2412 N SCOTTSDALE RD STE 1

TEMPE, AZ 85281-1163

Tel: 480-947-2848

legendslar@gmail.com

Repair Order J010182

Date: 01-09-2025 08:59 AM

1998 CHEVROLET CORVETTE

5.7 - Silver

1G1YY22G1WS124123

License Plate: CNV0AD2 AZ

Miles In: 74,251

Miles Out: 74,251

WORK TO BE PERFORMED**Oil Change and Filter****Work Description**

Change engine oil and filter. Check tire pressure.

Labor	Tech	Hrs	Price	Total
Shop Labor		0.13	150.00	19.50
Parts	Part No	Qty	Price	Total
Oil Filter	ACDPF46	1.00	9.64	9.64
Additive	ZINZINC	1.00	20.00	20.00
Full Syn Motor Oil	OIL5/30 FULL SYN	6.50	8.90	57.85

SubTotal: Oil Change and Filter **\$106.99****Evac & Recharge****Work Description**

Leak test, evac & recharge and installed dye.

Labor	Tech	Hrs	Price	Total
Shop Labor		1.00	158.73	158.73
Parts	Part No	Qty	Price	Total
R134A Refrigerant	CNVR134A	4.00	20.00	80.00
R134 AC Dye	ACD10-5072	1.00	11.27	11.27

SubTotal: Evac & Recharge **\$250.00**

Labor	178.23
Parts	178.76
Hazmat*	5.00
Supplies*	9.05
Taxes	14.48

Repair Order Total **\$385.52**

* Shop Supply & Hazmat Fees: This charge represents costs and profits (where applicable) to this repair facility for miscellaneous shop supplies, and/or waste removal

AUTHORIZATION

Date/Time:	Authorizer	Method	Contact Details	Original Estimate Total
				0.00
X _____				
Customer Signature				