

## How to measure the full voltage of new model batteries



I. Normally, the voltage is measured only between pin 1 and 2.

II. Due to safety reasons, the new battery model gives out around 30 V. To measure the full voltage, you need to connect pin 1 & 5 with a small wire.



III. When you measure the voltage now again between pin 1 and 2, the multimeter should show a voltage around 50 V.