




1



2




3




A

x12




B

x23



C


x23



M4X14mm

D


x29



M4X28mm

E


x4



M4X40mm


F

x4




G

x2




H

x2



I


x1



M5X40mm

J


x6



M4X16mm

K




x4







L

x1






STEP 1





STEP 2








STEP 3





STEP 4







STEP 5




STEP 6







STEP 7






STEP 8

	G	X2
	K	X6



STEP 9



STEP 10

