

Is safety secured?

PRECAUTIONS FOR HOT WORK

1 Project approved



2 Firefighting equipment in the area, at least two fire extinguishers



Main hazards:



Welding, gas or electrical

3 Flammable materials, explosive atmosphere: Work prohibited



4 Flammable material moved in safe distance, protected or soaked in water



5 Use appropriate personal protective equipment (PPE)



6 Area safe: Work can begin



Angle grinder



Installation of waterproofing membrane with torch

7 Take caution when material is dried, heated or melted



8 There must be a fire watch while work is ongoing + 60 min.

