



AirLink OS 5.3.66 General Availability

OVERVIEW

DATE ISSUED:	15-Oct-2025
ISSUED BY:	Semtech Product Management
PRODUCTS AFFECTED:	AirLink [®] Operating System (OS) Routers: <ul style="list-style-type: none">• RX55, XR60, XR80, XR90
FOR DISTRIBUTION TO:	All AirLink OS Customers
RELEASE DETAILS:	<p>AirLink OS 5.3.66 is Generally Available. This is a minor release that supersedes AirLink OS 5.2, and delivers feature enhancements, bug fixes, and security updates.</p> <p>Feature highlights of this release include the ability to manage AirLink OS based devices on-premise using AirLink Mobility Manager, DHCP option 12 support, and the ability to disable the TAIP checksum.</p> <p>For the AirLink OS 5.3.66 release details, refer to the release notes available on The Source.</p> <p>This release is recommended for all AirLink OS routers.</p>



PRODUCT SUPPORT

WHEN IS THIS UPDATE AVAILABLE?	AirLink OS 5.3.66 will be available from ALMS and The Source on or before 15-Oct-2025
---------------------------------------	---

CONTACT

SUPPORT:	<p>Ask for support here:</p> <ul style="list-style-type: none">• sierrawireless.com/support <p>Sign up to the Source for product resources and subscribe to product bulletins here:</p> <ul style="list-style-type: none">• sierrawireless.com/sso/signup <p>Sign up for Security Bulletins here:</p> <ul style="list-style-type: none">• sierrawireless.com/company/iot-device-security/security-bulletins
-----------------	--

REVISION HISTORY

15-Oct-2025	Initial Release
--------------------	-----------------