

>> | ALEOS 4.10.1 Release Notes

ALEOS 4.10.1 is for AirLink LX60.

New Features

Radio Modules

Added support for the WP7607 radio module with the following firmware:

- Generic: SWI9X07Y_02.16.02.00

Security Enhancements

Added increased security controls to remote access operations

Bug Fixes

General

Improved the LX60 boot time

LAN

Restored the use of DHCP Option 33 for adding static routes

Wi-Fi

Resolved an issue where the LX60 may, under certain conditions, discontinue broadcasting its SSID when no clients are connected

Resolved an issue where the LX60 may not associate all clients when servicing 10 simultaneous client requests

Improved usability of the Wi-Fi tab in ACEmanager. Settings for the selected Wi-Fi configuration are now displayed without clicking Apply.