



## ALEOS 4.15.1

### RELEASE NOTES

## About ALEOS 4.15.1

This release of ALEOS 4.15.1 is for the AirLink® LX60 and LX40. These release notes describe new features and bug fixes that apply to this release.

Sierra Wireless encourages all customers to maintain their AirLink routers with the current ALEOS release and security patches via our AirLink Management Service (ALMS). Sierra Wireless tests and validates upgrades from the previous two major software releases. If you have routers running an ALEOS release older than the previous two major releases it is recommended that you follow the tested and supported upgrade path.

In addition, other than basic questions that can typically be answered in our existing product documentation, Sierra will only provide technical support for the current and the previous two major software releases via our technical support organization. For example, the current version of ALEOS is 4.15 and we continue to support ALEOS 4.14 and ALEOS 4.13. If you have a support issue with a version prior to ALEOS 4.13, you will be asked to upgrade to a supported version before engaging our technical support organization. Our testing of downgrades involves first performing a factory reset, then installing the downgraded version. We do not provide technical support on routers that have not been factory reset before a downgrade was performed. See the table below.

ALEOS Release	Support Level	Upgrade Path
<b>ALEOS 4.15</b>	Supported	n/a
<b>ALEOS 4.14</b>	Supported	Upgrade to 4.15
<b>ALEOS 4.13</b>	Supported	Upgrade to 4.14 or 4.15
<b>Previous ALEOS Releases</b>	Limited support. Upgrade to supported release for technical support	Upgrade to supported release

Sierra Wireless recognizes that our customers deploy devices in a wide range of network environments with varying configurations. It is always good practice to install a new ALEOS release with the planned operation workflow on a few trial devices to ensure that standard operation is maintained within your environment before deploying the new release across your fleet of AirLink devices.

---

*Note: For a complete list of new features, security enhancements, bug fixes and known issues between ALEOS 4.14.0 and 4.15.1, please see the ALEOS 4.15.0 Release Notes.*

---

## New Features

### ALEOS

Added a check that devices are set to data-only mode to ensure they are not affected by AT&T 3G sunset.

## Bug Fixes

### AT Commands

Resolved an issue where AT\*INTSTATE\_RAW?1 always returned ERROR.