

»» | **ALEOS 4.12.0.p31 Release Notes**

ALEOS patch release 4.12.0.p31 is for AirLink MP70 Series routers, LX60 routers, LX40 routers, RV50 Series gateways and the RV55 router. This release primarily resolves issues with operating on AirLink Management Service (ALMS).

Bug Fixes

ALMS

Resolved issues with applying ALEOS 4.12.0 templates, displaying tables, and transmitting data between the device and ALMS using LWM2M.

WAN/Cellular

Resolved an issue where values for Automatic SIM Switching could not be returned to default.