



AirLink OS 5.0.65 General Availability

OVERVIEW

DATE ISSUED:	19-Mar-2024
ISSUED BY:	Sierra Wireless Product Management
PRODUCTS AFFECTED:	AirLink [®] Operating System (OS) Routers: <ul style="list-style-type: none">• RX55, XR80 and XR90
FOR DISTRIBUTION TO:	All AirLink OS Customers
RELEASE DETAILS:	<p>AirLink OS 5.0.65 is Generally Available and is a patch release that supersedes AirLink OS 5.0.49 and delivers a fix to the user interface issue detailed in this bulletin.</p> <p>For the AirLink OS 5.0.65 release details, refer to the release notes available on The Source.</p> <p>This release is recommended for all RX55, XR80, and XR90 routers.</p>



PRODUCT SUPPORT

WHEN IS THIS UPDATE AVAILABLE?

AirLink OS 5.0.65 will be available from ALMS and [The Source](#) on or before 19-Mar-2024.

CONTACT

SUPPORT:

Ask for support here:

- sierrawireless.com/support

Sign up to the Source for product resources and subscribe to product bulletins here:

- sierrawireless.com/sso/signup

Sign up for Sierra Wireless Security Bulletins here:

- sierrawireless.com/company/iot-device-security/security-bulletins

REVISION HISTORY

19-Mar-2024

Initial Release