



AirLink® MGOS 4.4.2 General Availability

OVERVIEW

DATE ISSUED:	02-Dec-2022
ISSUED BY:	Sierra Wireless Product Management
PRODUCTS AFFECTED:	AirLink® MG90 4G and MG90 5G Routers
FOR DISTRIBUTION TO:	All AirLink® MG90 Customers
	Sierra Wireless is pleased to announce General Availability of MGOS 4.4.2 for all AirLink MG90 4G and 5G routers.
	<p style="text-align: center;">▼ IMPORTANT NOTE ON THE MGOS UPGRADE PATH ▼</p> <ul style="list-style-type: none">• All customers running MGOS 4.4.0 must first upgrade to 4.4.1 (AMM OTA or via USB drive) before upgrading to MGOS 4.4.2. Failure to do so may prevent the router from connecting to the carrier network.• If you upgraded directly from MGOS 4.4.0 to MGOS 4.4.2 and are experiencing network connectivity issues, please contact Support for further instructions. <p>This is an important release that includes new features, security enhancements and fixes/improvements that address a number of field-reported issues. Some of the highlights are:</p> <ul style="list-style-type: none">• Improved WAN-link policies (4G/5G)• AMM Multi-unit reboot• Enhanced VPN status broadcast• IKEv2 support for Cisco ASA



	<p>Note: MG90 5G will only connect to the Verizon network in 4G.</p> <p>We recommend all MG90 customers to upgrade to this latest release. For more information, please refer to the release notes available on the Source.</p>
--	---

PRODUCT SUPPORT

WHEN IS THIS UPDATE AVAILABLE:	MG0S 4.4.2 is available now.
---------------------------------------	------------------------------

CONTACT

SUPPORT:	<p>Support https://www.sierrawireless.com/support/ The Source https://source.sierrawireless.com/</p> <p>Sign up to the Source for product resources and subscribe to product bulletins here: https://www.sierrawireless.com/sso/signup</p>
-----------------	---

REVISION HISTORY

02-Dec-2022	Initial Release
--------------------	-----------------