



Application Note

Accessing ACEmanager using HTTPS

- Applies to:
- ALEOS 4.14.0
 - ACEmanager

Introduction

To increase system security, with the release of ALEOS 4.14.0, ACEmanager access changes to use HTTPS and the default port changes to 9443. After upgrading your router to ALEOS 4.14.0, the previous IP address and port that you used remain valid. However, if your router is reset to factory default settings after upgrading to ALEOS 4.14.0, you must use HTTPS.

- For devices with ALEOS 4.14.0 installed at the factory, or devices upgraded to 4.14.0 and reset to factory default, the new protocol and port must be used:
https://192.168.13.31:9443
- For devices upgraded to ALEOS 4.14.0 or previous (and not reset to factory defaults) the http log-in persists: **http://192.168.13.31:9191**

Using ACEmanager with HTTPS

When you first log in using HTTPS, your browser may display warnings related to the self-signed certificate (see [Figure 1](#)). Please accept any warnings and continue. Depending on your browser, the warnings may not appear on subsequent log ins.

Note: HTTPS log in does not apply to devices in Recovery Mode. When a device is in Recovery Mode, use http://192.168.13.31:9191 to log in to ACEmanager.




Figure 1: HTTPS browser warning

Reverting to HTTP

To configure your device to use HTTP for local ACEmanager access again, go to Services > ACEmanager > Local Access and select **Both HTTP and HTTPS**.




Figure 2: ACEmanager > Services > ACEmanager

Document History

| Revision number | Release date | Changes |
|-----------------|--------------|---------------|
| 1 | Sept. 2020 | First release |
| | | |
| | | |

Legal Notice

Limitation of Liability

The information in this document is subject to change without notice and does not represent a commitment on the part of Sierra Wireless. SIERRA WIRELESS AND ITS AFFILIATES SPECIFICALLY DISCLAIM LIABILITY FOR ANY AND ALL DIRECT, INDIRECT, SPECIAL, GENERAL, INCIDENTAL, CONSEQUENTIAL, PUNITIVE OR EXEMPLARY DAMAGES INCLUDING, BUT NOT LIMITED TO, LOSS OF PROFITS OR REVENUE OR ANTICIPATED PROFITS OR REVENUE ARISING OUT OF THE USE OR INABILITY TO USE ANY SIERRA WIRELESS PRODUCT, EVEN IF SIERRA WIRELESS AND/OR ITS AFFILIATES HAS BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES OR THEY ARE FORESEEABLE OR FOR CLAIMS BY ANY THIRD PARTY.

Notwithstanding the foregoing, in no event shall Sierra Wireless and/or its affiliates aggregate liability arising under or in connection with the Sierra Wireless product, regardless of the number of events, occurrences, or claims giving rise to liability, be in excess of the price paid by the purchaser for the Sierra Wireless product.

Copyright © 2020 Sierra Wireless. All rights reserved.

Trademarks Sierra Wireless®, AirLink®, AirVantage® and the Sierra Wireless logo are registered trademarks of Sierra Wireless.

Windows® and Windows Vista® are registered trademarks of Microsoft Corporation.

Macintosh® and Mac OS X® are registered trademarks of Apple Inc., registered in the U.S. and other countries.

Other trademarks are the property of their respective owners.

Contact Information

| | |
|---|--|
| Sales information and technical support, including warranty and returns | Web: sierrawireless.com/company/contact-us/ Global toll-free number: 1-877-687-7795 6:00 am to 5:00 pm PST |
| Corporate and product information | Web: sierrawireless.com |