

CAUTION

RADIAL ARM SAW WEAR APPROPRIATE PERSONAL PROTECTIVE EQUIPMENT

(ie. eye, face, hearing etc.)

- Never start machine unless all guards are in place, properly designed and adjusted.
- Beware of all dangerous moving machinery parts.
- Keep work area clean. Foreign materials may cause poor footing
- Dust collection system, if provided, is connected and operational.
- Saw must gently return to starting position when released.
- Use stick or brush to remove small scrap from work table.
- Use proper saw blade for material being cut.
- Replace dull, cracked, or excessively fouled saw blades.
- Do not use abrasive, cutoff, or wire wheels on radial arm saws.
- Saw blade must never travel beyond working edge of table; forward travel stop is properly adjusted.
- When cross-cutting, use workpiece clamps to prevent “kickback” hazards.
- When ripping, kickback dogs must be used and properly adjusted.
- Never exceed rated RPM of saw blade.
- Follow manufacturer requirements for cutting ferrous and nonferrous metals.
- De-energize and lockout all energy systems before making adjustments/ repairs.
- Do not wear gloves, jewelry, or loose clothing.
- Ensure that operator is properly trained and has read owners operation manual.
Note: Immediately report all machinery malfunctions to management