

CAUTION

IRONWORKER

WEAR APPROPRIATE PERSONAL PROTECTIVE EQUIPMENT

(ie. eye, face, hearing etc.)

- Never start machine unless all guards are in place, properly designed and adjusted.
- Foot pedal control must be protected against accidental activation.
- Beware of all dangerous moving machinery parts-all operating stations move at the same time.
- Keep work area clean. Foreign materials may cause poor footing.
- De-energize and lockout all energy systems before making adjustments/ repairs.
- Do not wear gloves, jewelry, or loose clothing.
- Ensure that operator is properly trained and has read owners operation manual.

Note: Immediately report all machinery malfunctions to management