

# CAUTION

## MULTIPLE SPINDLE “GANG DRILL” DRILL PRESS

### **WEAR APPROPRIATE PERSONAL PROTECTIVE EQUIPMENT**

(ie. eye, face, hearing etc.)

- Never start machine unless all guards are in place, properly designed and adjusted.
- Beware of all dangerous moving machinery parts.
- Keep work area clean. Foreign materials may cause poor footing
- Use workpiece clamps, vices, etc. to secure work to table.
- Do not use dull or damaged drill bits.
- Do not grab “quick-change chucks” while rotating, regardless of speed.
- De-energize and lockout all energy systems before making adjustments/ repairs.
- Do not wear gloves, jewelry, or loose clothing.
- Ensure that operator is properly trained and has read owners operation manual.

Note: Immediately report all machinery malfunctions to management