


# How to Measure a Brush

Brushes should always be measured while dry. Use the following guidelines to measure a brush you already own using our charts:

1. Lay your brush on the line so that the line is just above the edge of the ferrule. Use the vertical line to measure width or diameter and the horizontal line to measure length. Check each side to ensure it lays straight.
2. Do not apply pressure or tilt the brush. The brush hairs should not be spread.
3. Follow the line over to read the measurement.


To learn more about how to measure a brush, visit: [www.dickblick.com/lp/how-to-measure-a-brush/](http://www.dickblick.com/lp/how-to-measure-a-brush/)

Measure width or diameter of brush from right edge of chart. (Example: brush in lower right corner measures 7.938 mm wide.)



Measure length of brush from the bottom of chart. (Example: brush at left measures 22.225 mm long.)

Measure width or diameter of brush from right edge of chart. (Example: brush in lower right corner measures 10.312 mm wide.)



Measure length of brush from the bottom of chart. (Example: brush at left measures 21.438 mm long.)

Measure width or diameter of brush from right edge of chart. (Example: brush in lower right corner measures 6.781 mm wide.)



Measure length of brush from the bottom of chart. (Example: brush at left measures 8.331 mm long.)