

This list only contains POS terminal solutions that have been tested and verified by NETS IT-verification since 01.01.2018. For any questions related to the solution validity, function, acceptance etc., please contact the Supplier/owner.

Supplier /PSP	Manufactor	Model	Application	Pin Y/N	Note
<b>NETS A/S:</b>					
ID-2659	Ingenico	iCT220E/ iCT220EG/ iWL220G	PSAM Telium2 2.2.2.5 (414-5002)	Y	
ID-2660	Ingenico	iCT220EG+iPP350, iCT250E+iPP350	PSAM Telium2 2.2.2.5 (414-5002)	Y	(1)
ID-2661	Ingenico	iCT250E/ iCT250EG/ iWL250G/ iWL250B/ iWL250	PSAM Telium2 2.2.2.5 (414-5002)	Y	
ID-2662	Ingenico	iPP350	PSAM Telium2 2.2.2.5 (414-5002),Combridge	Y	(1)
ID-2698	Ingenico	iPP350	PSAM Telium2 2.2.2.5 (414-5002), SIL	Y	(1)
ID-2742	Ingenico	iPP350	PSAM Telium2, 3.0.0.8 (SIL)	Y	(1)
ID-2743	Ingenico	iPP350	PSAM Telium2, 3.0.0.8 (Combridge)	Y	(1)
ID-2744	Ingenico	iCT250E/ iCT250EG/ iWL250G/ iWL250B/ iWL250	PSAM Telium2, 3.0.0.8	Y	
ID-2745	Ingenico	iCT220EG/iPP350, iCT250E/iPP350	PSAM Telium2, 3.0.0.8	Y	(1)
ID-2780	Ingenico	iPP350	PSAM Telium2, 3.1.0.7 (SIL)	Y	(1)
ID-2779	Ingenico	iPP350	PSAM Telium2, 3.1.0.7 (Combridge)	Y	(1)
ID-2778	Ingenico	iCT250E/ iCT250EG/ iWL250G/ iWL250B/ iWL250	PSAM Telium2, 3.1.0.7	Y	
ID-2777	Ingenico	iCT220EG/iPP350, iCT250E/iPP350	PSAM Telium2, 3.1.0.7	Y	(1)
ID-2670	Ingenico	iWL286	SDI Nordic v.5.1	Y	
ID-2686	Ingenico	IUC180B+IUR250	Viking 6.12	N	
ID-2687	Ingenico	IUC150 + IUR250 + IUP250	Viking 6.12	Y	
ID-2688	Ingenico	IPP350/ICT250/ICMP/ISMP/IWL250/ IWL255G/IMP550/IMP627/IMP657	Viking 6.12	Y	(1)
ID-2689	Ingenico	IUC180B+IUR250	Viking 6.12	N	
ID-2690	Ingenico	IUC150 + IUR250 + IUP250	Viking 6.12	Y	
ID-2691	Ingenico	IPP350/ICT220/ICT250/IWL220/ IWL250/IWL255G	Viking 6.12	Y	(1)
ID-2692	Ingenico	IPP350/ICT250/ICMP/ISMP/IWL250 /IWL255G/IMP550/IMP627/IMP657	Viking 6.12	Y	(1)
ID-2746	Ingenico	IPP350/ICT250/ICMP/ISMP/IWL250 /IWL255G/IMP550/IMP627/IMP657	Viking 6.23	Y	(1)
ID-2747	Ingenico	IPP350/ICT220/ICT250/IWL220/ IWL250/IWL255G	Viking 6.23	Y	(1)
ID-2748	Ingenico	IPP350/ICT250/ICMP/ISMP/IWL250/ IWL255G/IMP550/IMP627/IMP657	Viking 6.23	Y	(1)
ID-2749	Ingenico	IUC150 + IUR250 + IUP250	Viking 6.23	Y	
ID-2750	Ingenico	IUC150 + IUR250 + IUP250	Viking 6.23	Y	
ID-2751	Ingenico	IUC180B+IUR250	Viking 6.23	Y	
ID-2752	Ingenico	IUC180B+IUR250	Viking 6.23	N	
ID-2776	Ingenico	Lane3000/Move3500/Desk3500	Viking7.0	Y	

ID-2825	Ingenico	IPP350/ICT250/ICMP/ISMP/IWL250/IWL255G/IMP550/IMP627/IMP657/IWL220	Viking 6.4	Y	(1)
ID-2826	Ingenico	IPP350/ICT220/ICT250/IWL220/IWL250/IWL255G	Viking 6.4	Y	(1)
ID-2827	Ingenico	IPP350/ICT250/ICMP/ISMP/IWL250/IWL255G/IMP550/IMP627/IMP657/IWL220	Viking 6.4	Y	(1)
ID-2828	Ingenico	IUC150 + IUR250 + IUP250	Viking 6.4	Y	
ID-2829	Ingenico	IUC150 + IUR250 + IUP250	Viking 6.4	Y	
ID-2830	Ingenico	IUC180B+IUR250	Viking 6.4	N	
ID-2831	Ingenico	IUC180B+IUR250	Viking 6.4	N	
ID-2788	Ingenico	Lane3000/Move3500/Desk3500	Viking7.0	Y	
ID-2864	Ingenico	IPP350/ICT250/ICMP/ISMP/IWL250/IWL255G/IMP550/IMP627/IMP657/IWL220	Viking 6.5	Y	(1)
ID-2865	Ingenico	IPP350/ICT250/ICMP/ISMP/IWL250/IWL255G/IMP550/IMP627/IMP657/IWL220	Viking 6.5	Y	(1)
ID-2866	Ingenico	IUC150 + IUR250 + IUP250	Viking 6.5	Y	
ID-2867	Ingenico	IPP350/ICT220/ICT250/IWL220/IWL250/IWL255G	Viking 6.5	Y	(1)
ID-2868	Ingenico	IUC180B+IUR250	Viking 6.5	N	
ID-2869	Ingenico	IPP350/ICT250/ICMP/ISMP/IWL250/IWL255G/IMP550/IMP627/IMP657/IWL220	Viking 6.5	Y	(1)
ID-2870	Ingenico	IPP350/ICT250/ICMP/ISMP/IWL250/IWL255G/IMP550/IMP627/IMP657/IWL220	Viking 6.5	Y	(1)
ID-2871	Ingenico	IUC150 + IUR250 + IUP250	Viking 6.5	Y	
ID-2872	Ingenico	IUC180B+IUR250	Viking 6.5	N	
ID-2893	Ingenico	IPP350/ICT250/ICMP/ISMP/IWL250/IWL255G/IMP550/IMP627/IMP657/IWL220	Viking 8.0	Y	(1)
ID-2894	Ingenico	IPP350/ICT220/ICT250/IWL220/IWL250/IWL255G	Viking 8.0	Y	(1)
ID-2895	Ingenico	Lane3000/Move3500/Desk3500/Link2500	Viking 8.0	Y	
ID-2896	Ingenico	IPP350/ICT250/ICMP/ISMP/IWL250/IWL255G/IMP550/IMP627/IMP657/IWL220	Viking 8.0	Y	(1)
ID-2897	Ingenico	IUC150 + IUR250 + IUP250	Viking 8.0	Y	
ID-2898	Ingenico	IUC180B+IUR250	Viking 8.0	N	
ID-2899	Ingenico	IPP350/ICT250/ICMP/ISMP/IWL250/IWL255G/IMP550/IMP627/IMP657/IWL220	Viking 8.0	Y	(1)
ID-2900	Ingenico	Lane3000/Move3500/Desk3500/Link2500	Viking 8.0	Y	
ID-2901	Ingenico	IPP350/ICT250/ICMP/ISMP/IWL250/IWL255G/IMP550/IMP627/IMP657/IWL220	Viking 8.0	Y	(1)
ID-2902	Ingenico	IUC150 + IUR250 + IUP250	Viking 8.0	Y	
ID-2903	Ingenico	IUC180B+IUR250	Viking 8.0	N	
ID-2943	Ingenico	IPP350/ICT250/ICMP/ISMP/IWL250/IWL255G/IMP550/IMP627/IMP657/IWL220	Viking 8.0.3	Y	(1)
ID-2944	Ingenico	IPP350/ICT220/ICT250/IWL220/IWL250/IWL255G	Viking 8.0.3	Y	(1)
ID-2945	Ingenico	Lane3000/Move3500/Desk3500/Link2500	Viking 8.0.3	Y	
ID-2946	Ingenico	IPP350/ICT250/ICMP/ISMP/IWL250/IWL255G/IMP550/IMP627/IMP657/IWL220	Viking 8.0.3	Y	(1)
ID-2947	Ingenico	IUC150 + IUR250 + IUP250	Viking 8.0.3	Y	
ID-2948	Ingenico	IUC180B+IUR250	Viking 8.0.3	N	
ID-2949	Ingenico	IPP350/ICT250/ICMP/ISMP/IWL250/IWL255G/IMP550/IMP627/IMP657/IWL220	Viking 8.0.3	Y	(1)
ID-2950	Ingenico	Lane3000/Move3500/Desk3500/Link2500	Viking 8.0.3	Y	
ID-2951	Ingenico	IPP350/ICT250/ICMP/ISMP/IWL250/IWL255G/IMP550/IMP627/IMP657/IWL220	Viking 8.0.3	Y	(1)
ID-2952	Ingenico	IUC150 + IUR250 + IUP250	Viking 8.0.3	Y	
ID-2953	Ingenico	IUC180B+IUR250	Viking 8.0.3	N	
ID-2995	Ingenico	IUC180B+IUR250	Viking 8.0.6	N	
ID-2994	Ingenico	IUC150B + IUR250 + IUP250	Viking 8.0.6	Y	
ID-2993	Ingenico	IPP350/ICT250/ICMP/ISMP/IWL250/IWL255G/IMP550/IMP627/IMP657/IWL220	Viking 8.0.6	Y	(1)

ID-2992	Ingenico	Lane3000/Move3500/Desk3500/Link2500	Viking 8.0.6	Y	
ID-2991	Ingenico	IPP350/ICT250/ICMP/ISMP/IWL250/IWL255G/I MP550/IMP627/IMP657/IWL22	Viking 8.0.6	Y	(1)
ID-2990	Ingenico	IUC180B+IUR25	Viking 8.0.6		
ID-2989	Ingenico	IUC150B + IUR250 + IUP250	Viking 8.0.6	Y	
ID-2988	Ingenico	IPP350/ICT250/ICMP/ISMP/IWL250/IWL255G/I MP550/IMP627/IMP657/IWL220	Viking 8.0.6	Y	(1)
ID-2987	Ingenico	Lane3000/Move3500/Desk3500/Link2500	Viking 8.0.6	Y	
ID-2986	Ingenico	IPP350/ICT220/ICT250/IWL220/IWL250/IWL25 5G	Viking 8.0.6	Y	(1)
ID-2985	Ingenico	IPP350/ICT250/ICMP/ISMP/IWL250/IWL255G/I MP550/IMP627/IMP657/IWL220	Viking 8.0.6	Y	(1)
ID-3048	Ingenico	IUC150B + IUR250 + IUP250	Viking 8.0.8	Y	
ID-3067	Ingenico	IPP350/ICT250/ICMP/ISMP/IWL250/IWL255G/I MP550/IMP627/IMP657/IWL220 - Ver. Viking 8.2.0	Viking 8.2.0	Y	(1)
ID-3082	Ingenico	Lane3000/Move3500/Desk3500/Link2500	Viking 8.2.5	Y	
ID-3060	Ingenico	Self 4000	Viking 8.3.0	Y	
ID-3096	Ingenico	Self 4000	Viking 1.01.0	Y	
ID-3095	Ingenico	Lane3000/Move3500/Desk3500/Link2500	Viking 1.01.0	Y	
ID-3117	Ingenico	Self 4000	Viking 2.0	Y	
ID-3116	Ingenico	Lane3000/Move3500/Desk3500/Link2500	Viking 2.0	Y	
ID-3146	Ingenico	IPP350/ICT250/ICMP/ISMP/IWL250/IWL255G/I MP550/IMP627/IMP657/IWL220	Viking 8.2.6	Y	
ID-3148	Ingenico	Lane3000/Move3500/Desk3500/Link2500	Viking 2.001	Y	
ID-3149	Ingenico	Self 4000	Viking 2.001	Y	
ID-3156	Ingenico	Lane3000/Move3500/Desk3500/Link2500	Viking 2.01	Y	
ID-3157	Ingenico	Self 4000	Viking 2.01	Y	
ID-3160	Ingenico	Lane3000/Lane5000	Viking 8.0	Y	
ID-3167	Ingenico	Lane3000/Move3500/Desk3500/Link2500	Viking 2.02	Y	
ID-3168	Ingenico	Self/4000	Viking 2.02	Y	
ID-3093	Ingenico	Lane3000/Lane5000	Onepa 7.0	Y	
ID-3118	Ingenico	Lane3000/Lane5000	Onepa 7.1	Y	
ID-3142	Ingenico	Lane3000/Lane5000	Onepa 7.1 Build 02	Y	
ID-3152	Ingenico	Self 4000	OnePA 8.0	Y	
<b>Verifone:</b>					
ID-3041	Verifone	P400, V400c	Engage GPA v1.1.01	Y	
N/A	Verifone	Vx680, Vx690, Vx820 and Vx520c	Version 3.7.31	y	
N/A	Atos	Yomani XR/ML, Yomani 1	Version 3.7.31	y	
N/A	Verifone	T650C, T650P, CM5P, CM5, P400+T650C, M424, M440, P630	Android GPA 3.30.3	y	
N/A	Verifone	V400M, P400, M400, V400C, E285, X10	Cobra 3.3.9	Y	
ID-3132	Verifone	P400, V400c	Engage GPA v1.2.01	Y	(3)
ID-3169	Verifone	V400m/P630/V660p/P400/M400/V400c/e285	Cobra 4.0.0.0	Y	
<b>Verifone Norway:</b>					
ID-2640	Verifone	Vx680, Vx690, Vx820, Vx520c	paypoint 5.15	Y	
ID-2641	Atos	Yomani XR/ML, Yomani 1	paypoint 5.15	Y	
ID-2642	Atos	Xenteo Eco	paypoint 5.15	Y	
ID-2684	Atos	Xenteo ECO	5.15	Y	
ID-2905	Verifone	Vx680, Vx690, Vx820 and Vx520c	paypoint 5.15	Y	
<b>Verifone Finland:</b>					
ID-2910	Wordlin e	Verifone II	Yomani 4.0	Y	

<b>Bambora:</b>					
ID-2598	Ingenico	ICT250/IPP350/IWL250	SP900-201 v2	Y	
ID-2736	Ingenico	Desk5000/Move5000/Lane3000 link2500	Bambora POS 1.0	Y	
ID-3123	Ingenico	DX8000/RX5000/EX8000	Samport AX 1.0.0	Y	
<b>N&amp;TS</b>					
ID-2540	Ingenico	ICT250, IPP350, IWL250	V. P2PE-Micro2, 1.0 01.68B	Y	
<b>Circle K:</b>					
ID-2643	Gilbarco	SPOT M7/M4	NC3 1.7.358	Y	
ID-2634	Atos	YOMANI II/ML	Statoil 17.04.06	Y	
ID-2836	Gilbarco	SPOTM7	N3 1.7.794	Y	
ID-2837	Atos	Yomani ML	Statoil 19.26.06	Y	
ID-2964	Yomani	Yomani ML	Statoil 21.02.02	y	
ID-3111	Gilbarco	SPOT M4	GVR NC3 1.9.852.0	Y	
ID-3112	Gilbarco	SPOT M7	GVR NC3 1.9.852.0	Y	
ID-3113	Atos	Yomani ML	Statoil 21.02.22	Y	
<b>RetailInMotion:</b>					
ID-2650	Datecs	Bluepad 500	Datecs bluepad 500 V. 2.4.39.45	y	
<b>Adyen:</b>					
ID-2718	Verifone	P400/V400M/V400c/M400/V200C/E285	EVO v. 1.36	y	
ID-2719	Verifone	Vx820/Vx690/Vx680/Vx675/e355/e315	VOS v. 1.31	y	
ID-3122	Verifone	P400Plus/P200/V200c/V205c/V200t/V210/e23 5/V240m/e280/e285/P400/V400c/V400m/M4 00/M424/M440	Adyen v1 V1_96	Y	(3)
ID-3144	Castles	AMS1/S1F2/S1U2/S1E2/S1E2	Adyen v1 V1_96	Y	(3)
<b>Dover:</b>					
ID-2714		Crypto VGA	V. 2.x	y	
ID-2832	Verifone	P400	52.06	y	
<b>WestPay:</b>					
ID-2470	XAC	8006, 103	West Transaction Engine v1.22	y	
ID-2723	XAC	xCL_AP-10 / xCL_AT-100	West Payment Application 2.0.0	y	
<b>Altapay:</b>					
ID-2655	Pax	S920	CB2 V. 1.0	y	
ID-2672	Ingenico	ICT250	CB2 V. 1.72W	y	
ID-2700	Pax	A920	A 1.0.1	y	
<b>Ingenico:</b>					
ID-2812	Ingenico	Move5000	Axis cross-border EU 2.2	y	
<b>3C Payment/Planet:</b>					
ID-3091	PAX	IM30	Integra 1.0	Y	
ID-2935	Pax	Pax A920, Pax A930, A30, A35, A50, A77, A80, A920, A920Pro and IM30	IntegraTE 1.0	Y	
<b>Logos Design A/S</b>					
ID-2683	Verifone	UX100 + 300 + 400	UXL 2.0	y	
ID-2971	Verifone	UX100 + 300 + 400	UXL 2.0	y	
ID-3071	Verifone	Valina	Wilma 1.6.0	y	

<b>Payex</b>					
ID-2769	Ingenico	IWL250	PayEx Nordic Payment 1.0.2260	Y	
ID-2720	Ingenico	IUR250+IUP250+IUC150	PayEx Nordic Payment v1.0.2220	Y	
ID-3127	Pax	A30, A35, 920 Pro	Payex 1.2.x	Y	
<b>TietoEvry</b>					
ID-3086	Wincor nixdorf	Cineo 2550	Multivendor MV 22.3.0	Y	
<b>Euronet 360 Finance Limited</b>					
ID-3058	NCR	Selfserv 6628	EFTS 3.4	Y	
<b>Multipay Global solutions</b>					
N/A	Pax	A920	Carte 3.4.38	Y	
N/A	Pax	Q30	Prolin 3.2.22	Y	
<b>Viva Wallet</b>					
ID-3076	Ciontek	CS50	Version 5.5.0	Y	
ID-3173	Sunmi	P2Lite	T6810 V5.19.2(10545)	Y	
<b>Softpay Aps</b>					
ID-3105	Softpay	Softpay TTP	Version 2.2.0	Y	
<b>Digital solutions AB:</b>					
ID-3145	Pax	Pax A920 PRO, A30, A35, A50, A60, A77, A80, A800, A910, A920, A920Mini, A930	POSitive 1.00.36.5870	Y	
<b>Diebold Nixdorf</b>					
ID-3133		CS2040	Proflex 4.3	Y	
<b>Hamag A/S</b>					
ID-3134	Cryptera	INT3520	PS 001	Y	
<b>S5</b>					
ID-3135	Pax	A920 Pro, A35	Carte A1.2.1.1	Y	

Notes:

- 1) iPP350 firmware must be minimum 2.2.1.7
- 2) Time limited approval, waiver granted until 31-12-2024
- 3) Time limited approval, waiver granted until 30-06-2024