

# Unattended/Semi-attended Terminal Integrations:

This list only contains Unattended and Semi-attended solutions that have been tested and verified by NETS IT-verification since 01.01.2018. For any questions related to the solution validity, function, acceptance etc., please contact the Supplier/owner.

Supplier/Owner	Solution type:	Brand & model	Application	PIN Yes/No	Note
<b>Circle K:</b>					
ID-2643	UPT	SpotM7	NC3 1.7.358	Y	
ID-2836	UPT	SpotM7	Octane 2000 - z0933_200	Y	
ID-3032	UPT	SpotM4	Octane 2000 - Z09.33_229	Y	
ID-3033	UPT	SpotM7	Octane 2000 - Z09.33_229	Y	
<b>Gordion:</b>					
ID-2677	UPT	Ingenico IUC150+IUR250+IUP250	Gordion Payment 2.6	y	
<b>Gunnebo Nordic:</b>					
ID-2680	Semi-attended	Ingenico IPP350	SafeCoin D – 3.1.0.0	y	(1)
<b>Almex:</b>					
ID-2682	UPT	Logos UX100 + 300 + 400	G2 4.x	y	
<b>GoApplicate:</b>					
ID-2693:	UPT	NETS UCM Flexi	DRS-Drop&go 2.0	N	
<b>Carus PBS:</b>					
ID-2694:	UPT	Logos UX110 + 300 + 400	Logos Kermit 2.0	Y	
<b>NPS:</b>					
ID-2728	UPT	UX110+300+400 – V. OTA 5.0.0	PaySys 6.0	Y	
ID-2729	UPT	UX110+300+400 – V. OTA 5.0.0	PaySys 6.0	y	
<b>Microlog:</b>					
ID-2735	UPT	Nets Viking IUC150 + IUR250 + IUP250	Microlog AS 1.0	Y	
<b>Nordisk Film:</b>					
ID-2685	UPT	Nets Viking IUC150 + IUR250 + IUP250	Vista Kiosk V. 4.5.7.6	Y	
<b>Locktech:</b>					
ID-2767	UPT	Logos UX110 + 300 + 400	Locktech userstation 1.3	Y	
<b>Acrelec:</b>					
ID-2785	Semi-attended	Nets IPP350	ATP 5.0	Y	(1)
<b>Probox24:</b>					
ID-2793		Nets Viking IUC150 + IUR250 + IUP250	Golfstore_frontend 2.0	Y	
<b>REC POS:</b>					
ID-2798	Semi-attended	Nets IPP350	RECPOS 1.1.649.0	Y	(1)
<b>Payvend:</b>					
ID-2842	UPT	UX100 + 300 + 400	Payvend.TMS.CommonACI1.3	N	
<b>Accessdata A/S:</b>					
ID-2851	UPT	Nets Viking IUC150 + IUR250 + IUP250	Galaxy Kiosk 1.0	Y	
<b>Advice-IT:</b>					
ID-2847	UPT	Nets Viking IUC150 + IUR250 + IUP250	Harbakiosk 1.2	Y	
ID-2887	UPT	Nets Viking IUC150 + IUR250 + IUP250	WCM Payment 10.6	Y	
<b>Future ordering Sweden:</b>					
ID-2849	UPT	WestPay xUPT-303	Kiosk Payment Service1.2	y	

ID-3097	Semi-attended	Nets Viking Lane3000/Move3500/Desk3500/Link2500	FO.PS Integrations Nets 1.3	Y	
ID-3109	UPT	Nets Viking IUC150b + IUR250 + IUP250	Future Ordering Kiosk 22+	Y	
ID-3108	Semi-attended	IPP350/ICT250/ICMP/ISMP/IWL250 /IWL255G/IMP550/IMP627/IMP657/IWL220	Future Ordering Kiosk 22+	Y	
<b>Gilbarco:</b>					
ID-2716	UPT	Gilbarco SPOT	3.01	N	
ID-2715	UPT	Gilbarco SPOT	3.01	N	
ID-2876	UPT	Gilbarco SPOT	Epsilon Host Server - EMVDB DLL 1.0.0	Y	
<b>Dover:</b>					
ID-2714	UPT	Crypto VGA	Fuel POS - 48	Y	
<b>JK-automat:</b>					
ID-2874	UPT	UX110 + 300 + 400	JK CAT - 3.0	Y	
<b>Tallykey A/S:</b>					
ID-2878:	UPT	IUC150 + IUR250 + IUP250	Tallyweb - 1.0	Y	
<b>Knowtronic APS:</b>					
ID-2880	UPT	UX100 + 300 + 400	UCMTerminal.exe - 13.0.3	Y	
<b>Intelligent AR</b>					
ID-2931	Semi-attended	IPP350/ICT250/ICMP/ISMP/IWL250 /IWL255G/IMP550/IMP627/IMP657/IWL220	IAR server - 2.7	Y	(1)
<b>Payex Norway</b>					
ID-2925	UPT	IUR250+IUP250+IUC150		Y	
<b>Bibliotheca</b>					
ID-2879	UPT	IUC150 + IUR250 + IUP250	Cordura Kiosk - 5	Y	
<b>Zaplox AB</b>					
ID-2938	Semi-attended	IPP350/ICT250/ICMP/ISMP/IWL250 /IWL255G/IMP550/IMP627/IMP657/IWL220	Kiosk 2.0	Y	(1)
<b>Danske Spil A/S</b>					
ID-2816	Semi-attended	IPP350/ICT250/ICMP/ISMP/IWL250 /IWL255G/IMP550/IMP627/IMP657/IWL220	Oddset Retail 3.0.8	Y	(1)
<b>Crunch IT</b>					
ID-2961	Semi-attended	Lane3000/Move3500/Desk3500/Link2500	CrunchOrder - 1.0.0	Y	
<b>Thales East-West Denmark ApS</b>					
ID-2963	UPT	Logos UX100 + 300 + 400	RVM software (RVM-SW-10-00) - DK_RVM_11.00.75.301	Y	
<b>Sunset Boulevard</b>					
ID-2975	Semi-attended	Verifone V400M, P400, M400, V400C, E285, X10	Sunset Kiosk 127	Y	
<b>Københavns Lufthavne A/S</b>					
ID-3010	UPT	IUC150 + IUR250 + IUP250	Orion – OR 3.3	Y	
<b>Carrus AB LTD</b>					
ID-3004	UPT	UX110 + 300 + 400	Car Checkin App - 3.6.3	Y	

<b>Logos</b>					
ID-3078	UPT	UX110 + 300 + 400	Logos Swaci - 1.0	y	
ID-3085	UPT	Logos Valina	Selfly Store IF3 1.0.0	y	
ID-3106	UPT	Logos Valina	Luca 1.0	Y	
ID-3143	UPT	Logos Valina	Levp 1.0	Y	
<b>alpitronic srl</b>					
ID-3042		Logos valina	HYC 1.6	y	
<b>InterCard</b>					
ID-3043	Semi-attended	Lane3000/Move3500/Desk3500/Link2500	iTellerPlus - 1.1.42	y	
<b>Delta Electronics</b>					
ID-3059	UPT	Logos Valina	ECP - 3.7.0 A7	y	
<b>Fibo Intercon A/S</b>					
ID-3066	UPT	Logos Valina	Fibo Collect - 1.0	y	
<b>Steigenberger hotels AG</b>					
ID-3087	Semi-attended	Lane3000/Move3500/Desk3500/Link2500	Kiosk 1.09	y	
<b>NNIT A/S</b>					
ID-3125	Semi-attended	Lane3000/Move3500/Desk3500/Link2500	DKEXE 9.2	Y	
<b>Navipartner København A/S</b>					
ID-3128	UPT	Self4000	NP retail 27.0	Y	
<b>VendingRobotics A/S</b>					
ID-3139		Self4000	GassAutomat Gen4 – 2.0.0	Y	
<b>EnerCharge</b>					
ID-3102	UPT	Logos Valina	Ecc320/500-1.3.1.28	Y	
<b>Nimpos</b>					
ID-3151	Semi-attended	Lane3000/Move3500/Desk3500/Link2500	Nimpos - V.2.9.136	Y	
<b>Surikat</b>					
ID-3182	UPT	Self4000	Surikat Lynx 5.7.0	Y	

Notes:

- 1) iPP350 firmware must be minimum 2.2.1.7