

HERITAGE ECONOMIC REGENERATION SCHEME (HERS)

COMPLETED FACELIFTING PROJECTS



Before



After

◀13 Little Underbank

- Structural repairs to external elevations.
- Repoint external elevations where necessary.
- Remove existing paint from the front elevation.
- Remove existing windows and replace with 2 over 2 timber sliding sash windows.
- Improve lighting to the steps area.
- Decorate all new external woodwork and brickwork where required.

Aunt Sally's Steps adjacent to 13 Little Underbank▶

- Repair existing stone steps to top flight by removing existing stone slips and replacing with new stone slips to match originals and install a new stone veneer across the full width of the bottom flight of steps and make good.



Before



After



Before



After

◀32 Bridge Street Brow

- Remove existing box and external roller shutter.
- Remove inappropriate signage.
- Repair existing pilasters and fascia.
- Install internal security grille and laminated glass to shopfront and security panel to door.
- Redecoration of the shopfront and traditional signwriting to fascia board.

34-36 Bridge Street Brow▶

- Remove inappropriate modern shopfronts and external shutters.
- Reinststate traditional shopfronts.
- Install internal shutters and laminated glass to shopfronts.
- Install gates to recessed door areas.



Before



After



Before



After

◀6 Little Underbank

- Roof repairs
- Reinstall historic windows.
- Reinstall shop front.

2 Little Underbank▶

- Restoration of historic shopfront to match those on Nos. 4 & 6.
- Re-slating of roof & repairs to lead gutters.
- Reinstalling cast iron rainwater goods.
- Repairs to windows & reinstalling traditional sashes where missing.



Before



After