



<b>Reference Number</b>	Bulletin 2020-02
<b>Affected Product</b>	24M Motor Graders (B9K, B93)
<b>Risks Identified</b>	Potential for fuel hose leakage causing a fire hazard
<b>Release Date</b>	December 10, 2020

## Inspection and Replacement of 460-7645 Fuel Hoses

### Issue Description

Certain 24M Motor Graders equipped with the 460-7645 Hose AS-Fuel, have the potential of the hose being installed with the filter return fitting at an incorrect orientation, which may lead to a fitting failure due to fatigue. A failure of the hose fitting will cause a fuel leak which may result in a fire hazard.

### Issue Management Actions

Hastings Deering is providing a hose replacement service to ensure all affected product has this update completed as soon as possible. A number of machines have had this fuel hose replaced.

If you operate this product, we encourage you to check all machines to identify if this hose is installed. Please contact your Mining Support Representative to discuss this issue and to schedule the replacement of any affected fuel hoses that remain in-service at the earliest convenience.

*This bulletin is to inform you of the recommendations of the supplier in respect of issues dealt with in the bulletin and should not be used as specific advice in respect of any particular events. Advice from a qualified repairer should be sought in respect of any particular events and Hastings Deering (Australia) Limited accepts no responsibility for any loss or damage occasioned by a party using this general bulletin.*