



Best Practices Covid-19 & Jobsites



What is Covid-19?

Covid-19 is a disease caused by a new coronavirus and can lead to severe respiratory illness or pneumonia and can be fatal for people, especially for those with underlying health conditions.

How is it spread?



By droplets caused by coughing or sneezing




Close personal contact




Touching an object or surface with the virus on it, then touching your face

What are the symptoms?

Symptoms can include:



Fever



Cough




Shortness of breath

Symptoms may appear 2-14 days after exposure. Symptoms are varied. If you are experiencing symptoms, call ahead to your health care provider before seeking medical care.

How to prevent spreading the virus



Wash hands often with soap for 20 secs & disinfect surfaces & tools often



Avoid contact with sick people, practice 1.5m physical distancing



Stay home when sick



Cover your mouth with a tissue or sleeve when coughing or sneezing





Don't touch your face; use disposable wipes for sweat



Wear a mask or personal protective equipment (PPE)


Best Practices Covid-19 & Jobsites



Designated Assigned Work Areas

Establish work areas to limit all close interaction between crew members.

1. Assign designated work areas for each trade member, to allow movement within those areas while maintaining at least 1.5m of separation.
2. Designate locations to place cut material within reach of each installer's designated work zone.
 - If other trades are working too close to one staging area, the cutman can place material at the other location.





Staging Materials for the Day at the Cut Station

Carry all materials to and from the cut station individually.

Take turns picking up and dropping off material maintaining a 1.5m distance between trade.

Do not attempt to carry more than is manageable.



Setup / Breakdown Assignments

Limit who loads / unloads tools and equipment into and out of the vehicle.

To ensure crew members maintain 1.5m separation:

1. Designate one crew member to enter the van/trailer area to unload & load all tools out of and into the vehicle.
2. Use the same approach for unloading and loading ladders, walkboards and pump jack scaffolding.
3. Each crew member can then move their tools from the drop-off zone to their designated work area.
 - At the end of the day, crew members can return their tools and equipment to drop-off zones one at a time, for one person to load into the vehicle.
 - Extra crew member can clean the jobsite or prep for the next day, while tools and equipment are being loaded.
 - Ensure all tools are disinfected before and after using.

- Trade A
- Trade B
- ◆ Cut Person
- ▲ Designated crew member to enter van
- Designated Work Zone
- Location to Stage Cut Materials

Limit any external visitors or third parties (e.g. building inspections) to be by exception and at a time when no one else is on site apart from the builder and/or site supervisor.