

Fuse table

PORLA 400

Maximum loading of automatic of circuit breakers

Driver: LCA 45W 500-1400MA O4A C PRE	C10	C13	C16	C20		B10	B13	B16	B20
Number of drivers	21	30	36	46		13	18	22	28

* Input voltage 230V, Time measured at 50% Ipeak

PORLA 600

Maximum loading of automatic of circuit breakers

Driver: LCA 60W 900-1750MA O4A C PRE	C10	C13	C16	C20		B10	B13	B16	B20
Number of drivers	16	21	26	35		10	13	16	21

* Input voltage 230V, Time measured at 50% Ipeak