



# ENGINEERING BULLETIN

*Subject:* Instinct Propane Venturi Update Parts Kits

*Date:* 4/27/2021

Triangle Tube has received complaints of harmonic noise on a small number of propane installations of the Instinct. Although these complaints are rare, we have researched and developed a solution to this issue. A new repair kit is available that consists of a new propane venturi, control board, and display board. All three items must be replaced at the same time.

## Venturi Update Kit Part Numbers

Model	Kit
Instinct 110	INSRKIT124
Instinct 155 Solo & Combi	INSRKIT125
Instinct 199 Solo & Combi	INSRKIT126

Existing propane installations that do not exhibit any harmonic noises do NOT need to install this kit. Natural gas installations do NOT need to install this kit. All current production units are equipped with these parts as standard items.

Please contact technical support at [techsupport@triangletube.com](mailto:techsupport@triangletube.com) or (856) 228-8881 x575 with any questions.