



Pre-delivery Inspection Checklist

22 Apr 2019 / 3B7KF23642M238968 / Jaunter X5

Complete

Score	112 / 117 (95.73%)	Flagged items	5	Actions	3
Site conducted		Sydney			
Car Make/Model		Jaunter X5			
Vehicle Identification Number		3B7KF23642M238968			
Dealer		Shining Motors, Inc.			
Location		722 Charles St., Detroit, MI 48226			
Inspected by		Charista Perez			
Conducted on		22 Apr 2019 11:44 PST			

Flagged items & Actions

5 flagged, 3 actions

Flagged items

5 flagged, 3 actions

Pre-delivery Inspection Checklist / Wheels & Tires

Spare tire

Fail

To do | Assignee: Shine Colcol | Priority: High | Due: 23 Apr 2019 09:00 PST | Created by: SafetyCulture Staff

Locate spare tire

The spare tire wasn't in the rear compartment when I checked.

Pre-delivery Inspection Checklist / Engine Compartment

Radiator & cap

Fail



Photo 14

To do | Assignee: Shine Colcol | Priority: High | Due: 23 Apr 2019 03:00 PST | Created by: SafetyCulture Staff

Replace radiator cap

The cap was loosely attached to the radiator, as if the cap was only sitting on top of the radiator but not really closed. It could cause signs of overheating during the road test.

Pre-delivery Inspection Checklist / Engine Compartment

Engine oil level

Fail



Photo 15

To do | Assignee: Shine Colcol | Priority: High | Due: 23 Apr 2019 06:00 PST | Created by: SafetyCulture Staff

Refill engine oil

The engine oil level was below acceptable levels, so it must be refilled before the road test.

Pre-delivery Inspection Checklist / Road Test

Evidence of overheating

Fail

Due to loose radiator cap up for replacement

Pre-delivery Inspection Checklist / Convenience

Service book & history

Fail

Should be updated before given to the customer

Other actions

0 actions

Pre-delivery Inspection Checklist

5 flagged, 3 actions, 112 / 117
(95.73%)

Take photos of the vehicle from all sides



Photo 1



Photo 2



Photo 3

Body Exterior

5 / 5 (100%)

Glass

Pass

Door locks/operation

Pass

Fully operational



Photo 4

Fuel filler cover/petrol cap

Pass

General bodywork condition

Pass



Photo 5

Corrosion

Pass



Photo 6

Wheels & Tires

1 flagged, 1 action, 4 / 5 (80%)

Front right tire

Pass

Front left tire

Pass

Rear left tire

Pass

Looks good



Photo 7

Rear right tire	Pass
Spare tire	Fail
To do Assignee: Shine Colcol Priority: High Due: 23 Apr 2019 09:00 PST Created by: SafetyCulture Staff	
Locate spare tire The spare tire wasn't in the rear compartment when I checked.	
Interior & Luggage Compartment	4 / 4 (100%)
Seat mechanism Works okay  Photo 8	Pass
Seat belts	Pass
Internal mirrors	Pass
Boot/tailgate lock	Pass
Electrical Controls	15 / 15 (100%)
Ignition lock/starting system	Pass
Battery charging system  Photo 9	Pass
Headlights  Photo 10	Pass
Side lights/running lights	Pass
Rear lights & number plate illumination	Pass
Brake lights	Pass

Indicator & hazard lights	Pass
Reverse & fog lights	Pass
Auxiliary lights	Pass
Panel lights/dashboard illumination	Pass
 Photo 11	
Switches & controls	Pass
Instrument/controls function	Pass
Horn	Pass
 Photo 12	
Windows & sunroof operation	Pass
Wipers & jet washers	Pass
 Photo 13	
Brakes	9 / 9 (100%)
Master cylinder security	Pass
Fluid leaks	Pass
Servo/power system	Pass
Flexible hoses	Pass
Pipes/unions & connections	Pass
Properly routed	
Discs & pads	Pass
Hand brake operation/adjustments	Pass

Hand brake linkage	Pass
Pedal/linkage	Pass
Engine Compartment	2 flagged, 2 actions, 18 / 20 (90%)
Coolant level	Pass
Coolant leaks	Pass
Antifreeze	Pass
Radiator & cap	Fail



Photo 14

To do | Assignee: Shine Colcol | Priority: High | Due: 23 Apr 2019 03:00 PST | Created by: SafetyCulture Staff

Replace radiator cap

The cap was loosely attached to the radiator, as if the cap was only sitting on top of the radiator but not really closed. It could cause signs of overheating during the road test.

Hoses & pipes	Pass
Drive belts	Pass
Water pump	Pass
Power steering fluid leve	Pass
Clutch fluid level	Pass
Brake fluid level	Pass
Engine oil level	Fail



Photo 15

To do | Assignee: Shine Colcol | Priority: High | Due: 23 Apr 2019 06:00 PST | Created by: SafetyCulture Staff

Refill engine oil

The engine oil level was below acceptable levels, so it must be refilled before the road test.

External engine leaks	Pass
Engine mounts	Pass
Turbo/supercharger	Pass
Fuel pump & pipes	Pass
 Photo 16	
Accelerator linkage	Pass
Cold starting	Pass
Fast idle when engine cold	Pass
Noise level when engine cold	Pass
Excess fumes/smoke	Pass
Clutch & Transmission	12 / 12 (100%)
Fluid/oil leaks	Pass
Cables/adjustment	Pass
Hydraulic system	Pass
Linkages (check for signs of wear)	Pass
Casings	Pass
Mountings	Pass
Drive shaft assemblies	Pass
Universal & sliding joints	Pass
Clutch backlash	Pass
Rubber gaiters	Pass
Propshaft(s)	Pass
Bearings & supports	Pass

Exhaust System		8 / 8 (100%)
Inlet manifold		Pass
Outlet manifold		Pass
Pipes		Pass
 		
Photo 17 Photo 18		
Silencer(s)		Pass
Heat shields & mountings		Pass
Joints & couplings		Pass
Catalytic converter		Pass
Overall system condition		Pass
Fuel System		5 / 5 (100%)
Fuel tank		Pass
Fuel tank fixings		Pass
Fuel lines		Pass
Breather pipes		Pass
Evidence of leaks		Pass
Suspension, Underframe & Steering		16 / 16 (100%)
Engine underside leaks		Pass
Steering joints & ball joints		Pass
Steering rack		Pass
Chassis members		Pass
Power steering		Pass
Wheels, hubs & bearings		Pass

Springs & suspension unit	Pass
Pipes & hoses	Pass
Dampers & bushes	Pass
Gaiters	Pass
Sub frames & mountings	Pass
Suspension arms, mountings & fixings	Pass
Tie bars & anti-roll bars	Pass
Anti roll-bar	Pass
Evidence of floor/chassis corrosion	Pass
Bumper stops & gaiters	Pass
Road Test	1 flagged, 14 / 15 (93.33%)
Engine - performance	Pass
Engine - noise	Pass
Engine - excessive fumes or smoke	Pass
Evidence of overheating	Fail
Due to loose radiator cap up for replacement	
Gearbox operation & noise level	Pass
Final drive operation & noise level	Pass
Clutch operation	Pass
Cooling fan operation	Pass
Instruments & controls functioning	Pass
General steering & handling	Pass
Footbrake operation	Pass
Hand brake operation	Pass

Suspension noise	Pass
Road holding stability	Pass
Warning lights	Pass
Convenience	1 flagged, 2 / 3 (66.67%)
Owners manual	Pass
Service book & history	Fail
Should be updated before given to the customer	
Keys & remote controls	Pass
Completion	

Additional Observations

Overall, the vehicle is in good working condition. Must replace the radiator cap and perform another road test before handing it over to the customer.

Name & Signature of Vehicle Inspector



Charista Perez
22 Apr 2019 12:50 PST

Media summary



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11




Photo 12



Photo 13



Photo 14



Photo 15



Photo 16



Photo 17



Photo 18