



Driver Vehicle Inspection Report (DVIR) Form

8 Mar 2024 / Alice Johnson

Complete

Score	0 / 0 (0%)	Flagged items	1	Actions	2
Company Name	RJH Logistics				
Conducted on	8 Mar 2024 09:00 PST				
Prepared by	Alice Johnson				
Location	Los Angeles, CA, USA (34.0549076, -118.242643)				
Vehicle Information					
ID	V12345				
Make	Freightliner				
Model	Cascadia				
Year	2022				
License Plate	XYZ 123				
Driver Information					
Name	Jill Wreight				
ID	D56789				

Flagged items & Actions

1 flagged, 2 actions

Flagged items

1 flagged, 1 action

Report / Post-Trip Inspection

Brake fluid level

At Risk



Photo 1

To do | Assignee: SafetyCulture Staff | Priority: Low | Due: 4 Mar 2024 19:30 PST | Created by: SafetyCulture Staff

Minor leak detected in brake lines. For repair.

Other actions

1 action

Report

Defects and Issues (if any)

Minor leak detected in brake lines during post-trip. Action created and to be taken: Marked for repair.

To do | Assignee: SafetyCulture Staff | Priority: Low | Due: 4 Mar 2024 18:00 PST | Created by: SafetyCulture Staff

Endorse repair work to crew.

Report		1 flagged, 2 actions
Pre-Trip Inspection		
Time of Pre-Trip Inspection		8 Mar 2024 09:00 PST
Brake fluid level		Safe
Brake pedal resistance		Safe
Brake lines and hoses		Safe
Headlights (high and low beam)		Safe
Brake lights		Safe
Turn signals		Safe
Tread depth		Safe
Tire pressure		Safe
Spare tire condition		Not Applicable
No spare tire available.		
Steering wheel play		Safe
Power steering fluid level		Safe
Tie rods and drag link		Safe
Shocks and struts		Safe
Leaf springs		Safe
Bushings and mounts		Safe
Windshield wipers		Safe
Horn		Safe
Mirrors		Safe
Post-Trip Inspection		1 flagged, 1 action
Time of Post-Trip Inspection		8 Mar 2024 17:30 PST

Brake fluid level

At Risk



Photo 1

To do | Assignee: SafetyCulture Staff | Priority: Low | Due: 4 Mar 2024 19:30 PST | Created by: SafetyCulture Staff

Minor leak detected in brake lines. For repair.

Brake pedal resistance

Safe

Brake lines and hoses

Safe

Headlights (high and low beam)

Safe

Brake lights

Safe

Turn signals

Safe

Tread depth

Safe

Tire pressure

Safe

Spare tire condition

Not Applicable

No spare tire available.

Steering wheel play

Safe

Power steering fluid level

Safe

Tie rods and drag link

Safe

Shocks and struts

Safe

Leaf springs

Safe

Bushings and mounts

Safe

Windshield wipers

Safe

Horn

Safe

Mirrors

Safe

Defects and Issues (if any)

Minor leak detected in brake lines during post-trip. Action created and to be taken: Marked for repair.

To do | Assignee: SafetyCulture Staff | Priority: Low | Due: 4 Mar 2024 18:00 PST | Created by: SafetyCulture Staff

Endorse repair work to crew.

Completion

Comments or Additional Notes

- During the pre-trip inspection, a minor leak was detected in the brake lines, and it has been marked for immediate repair.
- The spare tire is not present, which is noted as "Not Applicable" in both the pre-trip and post-trip inspections.
- All lights, including headlights, brake lights, and turn signals, are functioning properly.
- Tread depth and tire pressure are within acceptable ranges.
- No abnormalities were observed in the steering components, including steering wheel play, power steering fluid level, tie rods, and drag link.
- Shocks, struts, leaf springs, bushings, and mounts are all in good condition.
- Windshield wipers are operational, and the horn is functioning as expected.
- Mirrors show no signs of damage or misalignment.

Driver's Signature



Jill Wright
8 Mar 2024 20:28 PST

Mechanic's Signature (if applicable)



Isaac Kepler
8 Mar 2024 20:29 PST

Media summary



Photo 1